GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/EH/2018/SZ/ 1303

Dated: 05.06.18

FIRE SAFETY CERTIFICATE

Certified that the M/s Decode Social Dinning (a unit of Bigshark Hospitality Pvt. Ltd.), J 2/1, BK Dutta Market, Rajouri Garden, New Delhi-110027 comprised of basement, ground floor plus three upper floors but the restaurant is running at Ground floor plus two upper floors owned/occupied by M/s Decode Social Dinning (a unit of Bigshark Hospitality Pvt. Ltd.). The building was inspected by the officers concerned of this department on 26.04.2018 in the presence of Sh. Mahabir Singh (Operation Manager) & Sh. Nikhil Ajmani (Partner) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground floor plus two upper floors) is fit for occupancy class Group D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on oS. o6. 18 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. The Deputy Health Officer, West Zone (SDMC), Public Health Department, Vishal Enclave, New Delhi.

2. The Director, M/s Decode Social Dinning (a unit of Bigshark Hospitality Pvt. Ltd.), J 2/1, BK Dutta Market, Rajouri Garden, New Delhi-110027.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered

evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement shall be used as per the building bye laws.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this

Certificate, six months prior to its expiry.

INSTECTION REPORT 1. Name & address of the building: M/s Decode Social Dinning (a unit of Bigshark Hospitality Pvt. Ltd.), J 2/1, BK Dutta Market, Rajouri Garden, New Delhi-110027 Type of Occupancy : Group D (Assembly Building) Type of Case New 4. Details of Previous NOC N/A 5. Fire Safety directives letter No: N/A 6. Date of inspection 26.04.2018 7. Name of Inspecting Officers D.O. M.K. Chattopadhyay & A.D.O. Sandeep Duggal : 8. Name and designation of officers From the building side Sh. Mahabir Singh (Operation Manager) & Sh. Nikhil Ajmani (Partner) 9. Year of Construction 2018 10. Applicant's letter No. : Nil dated 20.02.2018 S. Minimum Standards on fire prevention and fire **NBC** Provided at Remarks No. safety U/R 33 MR/NMR Requirement site 1. Access to building Road width 09 mtrs Provided MR 4.5 mtrs Directly accessible MR Gate width from road N/A N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Provided 02 no.'s MR Basements N/A N/A N/A b. Width of staircases 150 & 114 cms Provided MR Upper Floor N/A N/A N/A Basements c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to One N/A N/A terrace N/A Opening in N/A Width of Corridor hall 200 & 100 cms Door Size Provided MR Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A **Smoke Management System** 4. N/A N/A N/A Basements Required Provided MR Upper floors 5. Fire Extinguishers 09 No.'s Provided MR Total numbers ABC/CO₂ Provided MR Types IS marking ISI marked MR ISI marked First-Aid Hose Reels 6. Total numbers on ground floor One Provided MR Provided MR 30 mtrs Length of hose reel hose Provided MR 5 mm Nozzle diameter

	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
of of the	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System	710.85 Y	ndisotamic self	
	Basement	N/A	N/A	DT/A
fragin	Basement Ground Floor	N/A N/A	N/A N/A	N/A N/A
CENSULTS.	 Sprinkler above false ceiling 		N/A N/A	
11.	Internal Hydrants	N/A	N/A	N/A
	Armost installment of the Salah is	ni kao nollawang m	iff ito threbuse? seed	
	Size of riser/down-comer	100 mm	Provided	MR
	 Number of hydrants 	01 No.	Provided	MR
	Hose Box	01 No.	Provided	MR
12.	Yard Hydrants		1811	
1	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	Bud te to designate	12.307.1.30	Att of the second
	Ground Level		7305 20 HE AD 18 AN	
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head			
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	> Head of the pump	40 mtrs	Provided	MR
	> Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	The state of the s	site i		
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inletAccess to tank	Required	Provided	MR
	Overhead Tank capacity	N/A	N/A	N/A
	Overhead Talik Capacity	20000 ltrs	Provided	MR
15. A	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch Line Gi	Required	Provided	MR
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
			MASS SOURS ST.	testă a
18.	Refuge Area.		a sed encolorum base	
	> Total Area	N/A	N/A	N/A
	> Location			

19.	Fire Control Room	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note:- As per letter submitted by the Director (placed at C-26) restaurant is running at ground floor plus two upper floors and third floor is been used for personal use. Basement has been shut from outside by putting a wall and it is not been used in any manner whatsoever. The height of the building from ground floor to second floor is 09 meters.

Signature of Inspecting Officer Name: - M.K. Chattopadhyay Designation: - Divisional Officer Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy. C.F.O.(South Zone)

Go for M. Kell 155.

1442/160/55

6-T. letter 10' put up for Sign pleaser

CFO (South)

miscell Wells