

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F6/DFS/MS/2018/WZ/1258

Dated: 28/5/2018

FIRE SAFETY CERTIFICATE

Certified that **Caravan Cosmetics, 0-9, Sector-5, DSIDC Bawana, Delhi-110039** located on Ground & first floor of a premise comprised of **Basement + Ground + One upper floor** owned/occupied by **Caravan Cosmetics** was granted NOC by this department vide letter no. **F6/DFS/MS/2014/WZ/1346 Dated 28/10/2014** for ground & first floor only. The premise was re-inspected by the officers concerned of this department on **08/05/2018** in the presence of **Mr. Ravi Chopra** of the factory and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. Hence the Fire Safety Certificate for ground & first floor only is renewed and premises is fit for **Class Industrial Building (G-2) Class** with effect from 28/5/2018 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. The basement shall be used strictly as per the provision of building bye laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 28/5/18 at New Delhi by


(Atul Garg)

Chief Fire Officer

Ph: 011-23414250

Copy to:

1. M/s Caravan Cosmetics, 0-9, Sector-5, DSIDC Bawana, Delhi-110039
2. The Assistant Drugs Controller & Licensing Authority, Govt of National Capital Territory of Delhi, F-17, Karkardooma, New Delhi-110032

N/b

INSPECTION REPORT

**(B + G + One upper Floors)
Basement used for storage only.
Ground and first for cosmetic.**

1. Name & address of the building : M/s Caravan Cosmetics, 0-9, Sector-5, DSIDC Bawana,
Delhi-110039
1. Type of Occupancy : Industrial G-2
2. Type of Case : Renewal
3. Details of previous NOC : No F6/DFS/MS/2014/WZ/1346 Dated – 28/10/2014
4. Fire Safety directives letter No : NBC
5. Date of inspection : 08 / 05 / 2018
6. Name of the Inspecting Officers : ADO (RN & BW)
7. Name and designation of officers
from the building side : Mr. Ravi Chopra
9. Year of Construction : 2011
10. Applicant's letter No. : Nil Dated 08/03/2018

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	6 m	6 m	M/R
	• Gate width	Directly Accessible	Directly Accessible	M/R
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	02	M/R
	• Basements	02	02	M/R
	b. Width of staircases			
	• Upper Floors	1.25 mtr	2 X 1.25 mtr	M/R
	• Basements	1.25 mtr	2 X 1.25 mtr	M/R
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	2 X 1 mtr	Provided	M/R
	h. Door Size	100 cm	110 cm	M/R

↓

3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 a/c per hour	N/A	N/A
		12 a/c per hour	N/A	N/A
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	07	07	M/R
			ABC	M/R
		ISI marked	Provided	M/R
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	Required	Provided	M/R
		30 m	Provided	M/R
		5 mm	Provided	M/R
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> • Basement • Upper Floor • Sprinkler above false ceiling 	Required	Provided	M/R
		Required	Provided	M/R
		N/A	N/A	N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
12	Yard Hydrants.			
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	N/A	N/A	N/A
		N/A	N/A	N/A

178

13	Pumping Arrangements.			
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		900 LPM	Provided	M/R
		40 m	Provided	M/R
		N/A	N/A	N/A
		Required	Provided	M/R
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		10,000 Ltr	Provided	M/R
15	Exit Signage.	Required	Provided	M/R
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A

4

N/S

19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2014/WZ/1346 Dated – 28/10/2014 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Handwritten signature

Signature of the Inspecting Officer

Name: Rajesh Kumar

Designation: Asstt. Divisional Officer

14/CFs/WZ
 CFO West
 18/5/12
 FIPD

As approved, f.t. letter is put up for your signature pl.

CFs/WZ
Handwritten signature

1/11/23/15