## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2018/ 12 6 0

Dated :- 30/5/1-8---

## FIRE SAFETY CERTIFICATE

Certified that the M/S Desi Vibes Restaurant (A Unit of Goyal Kitchen & Grill Pvt. Ltd.) located at N-95 and half portion of N-49, 2<sup>nd</sup> floor, Munshilal Building, N-Block, Connaught Place New Delhi comprises of Ground + Mezzanine + 03 upper floor, Restaurant is running at 2<sup>nd</sup> floor only owned /occupied by M/S Desi Vibes Restaurant (A Unit of Goyal Kitchen & Grill Pvt. Ltd.) has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 15-05-2018 in the presence of Mr. A.K. Goyal (Manager) and that the building / premises, is fit for occupancy class Assembly Building Group-D of Sub-Division D-5, Restaurant is running at 2<sup>nd</sup> floor only with effect from for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...... at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Officer

0/4

Copy to:-

1. The Medical Officer of Health, NDMC, Palika Kendre, New Delhi.

2. The Manager,

M/S Deshi Vibes Restaurant (A Unit of Goyal Kitchen Y Grill Pvt. Ltd.), N-95 and half portion of N-49, 2<sup>nd</sup> floor, Munsilal Building, N-Block, Connaught Place New Delhi

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPE	CTION	REPORT
TITOIL	CITOIA	KEFUKI

1. Name & address of the building M/S Deshi Vibes Restaurant (A Unit of Goyal

Kitchen Y Grill Pvt. Ltd.), at N-95 and half portion of N-49, 2<sup>nd</sup> floor, Munsilal

Building, N-Block, Connaught Place

New Delhi.

2. Type of occupancy:-Assembly Building Group-D

Gr. + Mezzanine + 03 Upper floors, Restaurant is running at 2<sup>nd</sup> floor only

3. Type of case:-

4. Details of previous FSC:-

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

New Case

N/A N/A

15/05/18

Sh. Manoj Kumar Sharma (ADO/CC)

Sh. A.K. Goyal (Manager)

Old Heritage

Nil dated 24/04/2018

S.No.	Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	e Remarks MR/NMI
1.	Access to Building	gements		
	1) Road width	Required	06 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	NI/A	
2.	Number, Width Type & Al	rrangement of	Frite	N/A
	A. Number of staircases	gement of	LAILS	
	1. Upper floors	01	02	) A (D)
	2. Basements	N/A	N/A	MR
	B. Width of staircase		IVA	N/A
	1. Upper floors	0.80 & 1.25 mtr.	1.25 mtr. & 1.0 mtr.	MR
_	2. Basements	N/A	N/A	N/A
	C. Protection of exits			IVA
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	01
	E. Width of corridor	N/A	N/A	N/A
	F. Door size/exit	2 mtr.	02 mtr.	MR
	Compartmentation			IVIIC
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
-	3) Fire rating of shaft door	N/A	N/A	N/A
4	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System			11//1
_	1) Basements	30 ACPH	N/A	N/A
2	2) Upper floors	12 a/c per hour	-	MR

5.	Fire Extinguishers	*		
	1) Total numbers	10 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			2
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection & A			
3	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	14/11	1011	
10.	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	14/11	11/12	
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			- an
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump		5	
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	-	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	a) Discharge of build			MR
		40 mtr.	40 mtr.	IVIK
	b) Head of pump		40 mtr. Provided	MR
	<ul><li>b) Head of pump</li><li>c) Power supply</li></ul>	Required	Provided	
14.	<ul><li>b) Head of pump</li><li>c) Power supply</li><li>d) Auto starting of pump</li></ul>	Required Required		MR
14.	<ul><li>b) Head of pump</li><li>c) Power supply</li><li>d) Auto starting of pump</li><li>Captive Water Storage for F</li></ul>	Required Required Tire Fighting	Provided Provided	MR MR
14.	<ul><li>b) Head of pump</li><li>c) Power supply</li><li>d) Auto starting of pump</li></ul>	Required Required	Provided	MR

	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	10000 ltr.	10000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys Risk, if any:	tem for Prote	ction of special	NA

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/2016/2333 dated 28/09/2016

have been rectified.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 / is recommended please.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

beingt's the total area of the restaurant thoro many occupant load is calculated of
ef the exits meet the criteria of meens of

escape