GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/EH/2018/NDZ/ 1288

Dated: 04/06/18

FIRE SAFETY CERTIFICATE

Certified that the **The Yellow Chilli Restaurant** running at G-11, ground floor level of a building comprised basement, ground plus three upper floors at plot no. 11, District Centre, Laxmi Nagar, Delhi-92, owned/occupied by M/s A unit of Royal Hospitality was granted FSC vide letter no- **F6/DFS/MS/EH/2015/NDZ/943 Dated 08/06/15**. The Restaurant was re-inspected by the officer concerned of this department on 21/05/18 in the presence of **Mr. K.N.Umesh (General Manager)** and found that the Restaurant building have deemed complied with the fire prevention and fire safety requirements in accordance rule 35 of the Delhi Fire Service Rule 2010 and found that the G-11 building is fit for occupancy Class D "Assembly Building" (Restaurant) with effect from £4/.66..... for a period of **three** years, subject to conditions printed overleaf.

Issued on at New Delhi by

(Vipin Kental)
Chief Fire Officer

To,

M/s A unit of Royal Hospitality, G-11, Ground Floor, Plot No. 11, V3S Mall, District Centre, Laxmi Nagar, Delhi-92.

Copy to:-

The Dy. Health Officer, EDMC, Health Department, Shahdara (South) Zone, Karkardooma, Shahdara, Delhi. CONDITIONS:

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building

: The Yellow Chilli at G-11, GF, Plot no.10 District Centre,

Laxmi Nagar, Delhi.

2. Building is comprised of

: Basement, Ground Plus Three upper floors

3. Type of Occupancy

: Assembly

4. Type of Case

: Renewal

5. Details of Previous NOC

: F6/DFS/MS/EH/2015/NDZ/943 Dated 08/06/15

6. Fire Safety direction letter No

: Nil

7. Date of Inspection

: 21/05/18

8. Name of the Inspecting Officers: : R.K.Yadav (ADO)

9. Name of the designation of Officer

from the building side

: Mr. K.N.Umesh (General Manager)

10. Year of Construction

: 2006

11. Ap	oplicant's letter No : Nil dated	08/05/18					
S.No	Minimum Standards on fire safety	NBC	Provided at Site	Remarks			
	requirements	Requirement	19	MR/NMR			
1	Access to building						
	Road width	12 m	36 m & 13.8 m	MR			
	Gate width	4.5 m	06 m	MR			
	Width of internal road	06 m	06 m	MR			
2	Number, Width, Type and Arrangement of Exits.						
	a. Number of Staircases						
	Upper Floor	N.A.	N.A.	N.A.			
	Basement	N.A.	N.A.	N.A.			
	B. Width of Staircases						
	Upper Floor	N.A.	N.A.	N.A.			
	Basement	N.A.	N.A.	N.A.			
9	c. Protection of exits		1 22 -				
	Fire check door	Required	Provided	MR			
	Pressurization	Required	Provided	MR			
	e. No. of continuous staircases to terrace	1no.	1 no.	MR			
	g. Width of Corridor	N.A.	N.A.	N.A.			
	h. Door Size	2 m	2 m & 1 m	MR			
3	Compartmentation.						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Provided	MR			
	Fire rating of shaft door	Required	Provided	MR			
	Water curtain	N.A.	N.A.	N.A.			
	Fire Dampers	N.A.	N.A.	N.A.			
4	Smoke Management System.						
	Basement	Required	Provided	MR			
	Upper floor	Required	Provided	MR			

	Fire Extinguisher	04 no.		06 no.	MR			
	Total numbers	ABC 8		ABC & CO ₂	MR			
	types	ISI ma		ISI marked	MR			
	ISI marking							
	First-aid-Hose Reels. 02 no.			02 no.	MR			
	Total numbers of each floor	30 m		30 m	MR			
	Length of hose reel hose	2750 200		5 mm	MR			
	Nozzle diameter	5 mn	1	311111				
7	Automatic fire detection and alarming	system.	n also	Provided	MR			
	Type of detectors	Heat & Si		Basement	MR			
	Location of main paner				MR			
	Location of repeater panel Security			Provided				
	Alternate source of power Batt		k DG Set	Provided	MR			
	Hooters			Provided	MR			
0	MOEFA	Required	d	Provided	MR			
8 9	Public address System.	Required	d	Provided	MR			
	Automatic Sprinkler System.							
10	basement	Req	uired	Provided	MR			
	upper floor	Req	uired	Provided	MR			
	sprinkler above false ceiling	Req	uired	Provided	MR			
11	Internal Hydrants		mm	150 mm	MR			
	size of riser/down-comer	2 n	o.	2 no.	MR			
	Number of hydrants each floor	2 n	0.	2 no.	MR			
	Hose box each floor							
12	Yard Hydrants.		0.	5 no.	MR			
	Total number of hydrants	5 n		5 no.	MR			
	Hose Box	311	· · · · · · · · · · · · · · · · · · ·					
13		Po	quired	Provided	MR			
	Ground Level		50 LPM	2850 LPM	MR			
	Discharge of main Pump		M	70 M	MR			
	> Head of Main Pump		lo.	1No.	MR			
	Number of main pumps		O LPM	180 LPM	MR			
	> Jockey pump out put) M	70 M	MR			
	> Jockey pump head		350 LPM	2850 LPM	MR			
	> Standby pump out put			70 M	MR			
	> Standby pump Head) M	Auto	MR			
	> Auto Starting /Manual stop		equired	Provided	MR			
	> Pump House Access	R	equired	Flovided	,,,,,,			
	Terrace Level	3.00		NI A	N.A.			
	Discharge of pump		I.A.	N.A.	N.A.			
	➤ Head of the Pump	_	I.A.	N.A.	N.A.			
	> Power supply		I.A.	N.A.	N.A.			
	Auto Starting of pump	1	I.A.	N.A.	IV.A.			

14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	1,00,000 ltrs	1,20,000 ltrs	MR			
	Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
	Overhead Tank capacity	20,000 Liters	40,000 Liters	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required	Provided	MR			
	Communication in lift car	Required	Provided	ed MR			
	Firemen's grounding switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	Total area	N.A.	N.A.	N.A.			
	Location	N.A.	N.A.	N.A.			
19	Fire Control Room						
	Detector system panel	Required	Provided	MR			
	Flow switch panel	Required	Provided	MR			
	PA system panel	Required	Provided	MR			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
20	Special Fire Protection systems for	Required	Provided in a	II MR			
	protection of special Risks, if any:		LT & HT Panels				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/EH/2015/NDZ/943 Dated 08/06/15, it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name

R.K.Yadav

Designation

ADO (LN)

DO (EAST)

562/cfe/ND3

19/5/11/8

miscell