

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/Hospital/2018/WZ /1280

Dated: 31/05/2018

FIRE SAFETY CERTIFICATE

Certified that the Bhagwati Hospital located at CS/OCF-6, Sec-13, Rohini, Delhi-110085 comprised of Basement + Ground + Three Upper Floors only owned / occupied by (A Unit of Sarvodaya Health Foundation, Delhi) has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/Hospital/2015/1704 dated 17/09/2015. The premises was re-inspected by the officers concerned of Fire Service on 25.04.2018 in the presence of Dr. Naresh Pamnani and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for occupancy Class Institutional (Hospital) with effect from 31/05/2018 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on 31/05/18 at New Delhi by.

(ATUL GARG)
CHIEF FIRE OFFICER.

Copy to :-

1. Dr. Naresh Pamnani (Medical Superintendent), Bhagwati Hospital, CS/OCF-6, Sec-13, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. The Basement shall be used strictly as per the provision of building bye laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

INSPECTION REPORT

Hospital Block - Basement + Ground + Three upper floors

1. Name & address of the building: Bhagwati Hospital CS/OCF-6, Sec-13, Rohini, Delhi-110085.
2. Type of Occupancy : Institutional (Hospital)
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/Hospital/2015/1704 dated 17/09/2015
5. Fire Safety directives Letter No. : F6/DFS/MS/BP/Hospital/99/1377 dated 25/10/99
6. Date of inspection : 25/04/2018
7. Name of the Inspecting Officer : Dy. CFO (WZ), A.D.O.(JWP)
8. Name and designation of Officer
from the building side : Dr. Naresh Pamnani
9. Year of Construction : 2003
10. Applicant's letter No. : Nil Dated 07/03/18

S No	Minimum standards on fire prevention and fire safety U/R 33	F6/DFS/MS/BP/Hospital/99/1377 dated 25/10/99	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 mtr	18 mtr	MR
	• Gate width	5 mtr	5 mtr	MR
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	02	02	MR
	• Basements	1, 1 (ramp)	1, 1 (ramp)	MR
	b. Width of staircases			
	• Upper floors	2.00 mtr	2.00 mtr & 1.10 mtr	MR (Old Case)
	• Basements	2.00 mtr	1.80 mtr & ramp 2.60 mtr	MR (Old Case)
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	2	2	MR
	e. Width Of Corridor	2.00 mtr	1.90 mtr to 2 mtr	MR (Old Case)
	f. Door Size	1.00 mtr	1.00 mtr	MR
3.	Compartmentation			
	• Fire check door	Required	Provided in basement	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	• Basements	Required	Exhaust fan provided	MR
	• Upper floors	NA	NA	NA
5.	Fire Extinguishers			
	• Total numbers	20	52	MR
	• Types	ISI marked ABC/CO ₂	Provided	MR
	• IS marking	Required	Provided	MR

(Signature)


	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30Mtr.	30Mtr.	MR
	• Nozzle diameter	5mm.	5mm.	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Smoke	Provided	MR
	• Location of Main Panel	GF	GF	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basements	Required	Provided	MR
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	• Size of riser/down-comer	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
	• Hose Box	NA	NA	NA
12.	Yard Hydrants			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	NA	NA	NA
	➤ Head of main pump	NA	NA	NA
	➤ Number of main pumps	NA	NA	NA
	➤ Jockey pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	NA	NA	NA
	➤ Auto Starting/Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	• Terrace level			
	➤ Discharge of pump	450 LPM & 180 LPM	450 LPM & 180 LPM	MR
	➤ Head of the pump	40MH	40 MH	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	25,000 ltr	25,000 ltr	MR
	➤ Draw of connection	NA	NA	NA
	➤ Fire service inlet	NA	NA	NA
	➤ Access to tank	NA	NA	NA
	• Overhead Tank capacity	12,500 lts.	12,500 lts	MR


21/25

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	NA	NA	NA
	➤ Pressurization of lift lobby	NA	NA	NA
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	2 x 750 KVA	MR
18.	Refuge Area			
	➤ Total area	NR	NR	NR
	➤ Location	NR	NR	NR
19.	Fire control room			
	➤ Detector system panel	Required	Provided	MR
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	Required	Provided	MR
	➤ Battery backup	Required	Provided	MR
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring has also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/Hospital/2015/1704 dated 17/09/2015 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.



 Signature of the Inspecting Officer
 Name : A.K. Jaiswal
 Designation : A.D.O. (JWP)


 Signature of the Inspecting Officer
 Name : D.P. Bhardwaj
 Designation : Dy.C.F.O. (West)

~~CFO West~~
~~30/5/18~~

F.T.P.

~~ADDP~~ F.T. is put up for signature pl.
~~CFO (West)~~
~~31/05/18~~


31/5/18