GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ /1220

Dated: 24/5/18

FIRE SAFETY CERTIFICATE

Certified that the **Vagishwari World School**, A-100-101, Nanehy Park, Matiyala Bindapur Road, Uttam Nagar, New Delhi-110059 is running at ground floor plus one upper floor of a building comprised of ground plus three upper floors, having total 07 rooms on ground floor and 07 rooms on First floor (Including Class rooms, Offices, Store & Staff room etc.), owned/occupied by Vagishwari World School. The school building was inspected by the officer concerned of this department on 24.04.2018 in the presence of Sh. Sumit Gupta (Manager) and found that Vagishwari World School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**ground floor plus one upper floor only**) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

 The Chairman, Vagishwari World School, A-100-101, Nanehy Park, Matiyala Bindapur Road, Uttam Nagar, New Delhi-110059

 Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

School is running at ground floor plus one upper floor in a four storied building. INSPECTION REPORT Vagishwari World School, A-100-101, Nanehy Park, Matiyala Bindapur 1. Name & address of the building: Road, Uttam Nagar, New Delhi-110059. 2. Type of Occupancy Educational New Type of Case 3. 4. Details of Previous NOC N/A 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 24.04.2018 A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers From the building side Sh. Sumit Gupta (Manager) 9. Year of Construction Before 2018 Form "I" dated 06.03.2018 10. Applicant's letter No. Dir. Of Edu. Provided at site Remarks Minimum Standards on fire prevention and S. No. Circular dt. MR/NMR fire safety U/R 33 01.03.2011 1. Access to building Accessible (06 mtrs) M/R 09 mtrs Road width 4.5 mtrs Directly accessible M/R Gate width N/A from road N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases M/R Upper Floors 02 no.'s Provided Basements N/A N/A N/A b. Width of staircases 150 cms/additional 100 & 100 cms M/R Upper Floor staircase of 75 cms (02 mtrs staircase **Basements** if less than 150 cms split into two) N/A N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A N/A Width of Corridor N/A N/A N/A M/R (Students are 120 cms 100 cms Door Size less than 40 in each classroom) 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural ventilation M/R Required Upper floors provided 5. Fire Extinguishers Provided M/R 05 no's Total numbers ABC type Provided M/R Types IS marking ISI marked M/R ISI marked **First-Aid Hose Reels** 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
8.	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
	,		1 1/1 1	1771
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants		9	1
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants		п	
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level		*	1
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out putJockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	, a	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting		9	
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A N/A
15.	Overhead Tank capacity	200 2000		
	Evit Signage	N/A N/A	N/A N/A	N/A
13.	Exit Signage.	IN/A	IN/A	N/A
16.	Provision of Lifts.		1	(No Lift)
		~		(TIO LIII)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	 Fireman's Grounding Switch 	N/A	N/A	N/A
	Lift Signage			
	, , , ,	N/A	N/A	N/A
4.5		N/A	N/A	N/A
17.	Standby power supply			
10	D. C A			
18.	Refuge Area. > Total Area	NT/A	NT/A	NT/A
	> Location	N/A	N/A	N/A
100	Location	NI/A	NI/A	NI/A

2/3

19.	Fire Control Room				
00 100 100	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel PA System Panel Pattern has large.	N/A	N/A	N/A	
		N/A	N/A	N/A	
	Battery backupBuilding Floor Plans	N/A	N/A	N/A	
		N/A	N/A	N/A	
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per undertaking given by the Chairman (placed at C-2), school is running at ground floor plus one upper floor only. Second & third floor have sealed at staircase and will not be used without permission. Students strength will be less than forty and fire safety certificate is required for ground floor and first floor only.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

308/DOCED) dt. 27/04/18

Divisional Officer (South West)

27/4/18

8-5-18

Land 1/5

con (32) pl peak ve

DCF052