

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ/ 1170

Dated: 22/5/18

FIRE SAFETY CERTIFICATE

Certified that the **Nigam Pratibha Vidyalaya**, New J.J. Hastal No.-2, Shiv Vihar, Uttam Nagar, New Delhi-110059 comprised of ground plus one upper floor, having total 44 rooms (22 rooms at ground floor & 22 rooms on first floor including Class Rooms, Office & Store etc.) owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2014/SZ/1589 dated 15.12.2014. The school building was re- inspected by the officer concerned of this department on 23.04.2018 in the presence of Sh. Satya Narain (Principal) and found that the Nigam Pratibha Vidyalaya have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on.....22/5/18..... at New Delhi.

W
T/S
(VIPIN KENTAL)
CHIEF FIRE OFFICER

CSAO
18/5/18

Copy to:-

1. The Principal,
Nigam Pratibha Vidyalaya, New J.J. Hastal No.-2,
Shiv Vihar, Uttam Nagar, New Delhi-110059
2. Director of Education,
S.D.M.C, Civic Centre,
Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT

1. Name & address of the building : Nigam Pratibha Vidyalaya, New J.J. Hastal No.-2, Shiv Vihar, Uttam Nagar, New Delhi-110059
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/School/2014/SZ/1589 dated 15.12.2014
5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011
6. Date of inspection : 23.04.2018
7. Name of Inspecting Officer : A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Satya Narain (Principal)
9. Year of Construction : 2007
10. Applicant's letter No. : Nil dated 15.03.2018

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Requirement as per FSC dt. 15.12.2014 | Provided at site | Remarks MR/NMR |
|--------|--|---|--|--------------------|
| 1. | Access to building | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | 06 mtrs 4.5 mtrs N/A | Provided Directly accessible from road N/A | MR MR N/A |
| 2. | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | | | |
| | • Upper Floors | Two | Provided | MR |
| | • Basements | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | • Upper Floor | 150 cms/additional staircase of 75 cms if less than 150 cms | 150 & 130 cms | MR, being old case |
| | • Basements | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircases to terrace | N/A | N/A | N/A |
| | e. Width of Corridor | 150 cms | 230 cms | MR |
| | f. Door Size | 100 cms | 110 cms (double door) few with single door | MR, being old case |
| 3. | Compartmentation | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Sealing of electrical shafts | N/A | N/A | N/A |
| | • Fire Rating of shaft door | N/A | N/A | N/A |
| | • Water Curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |
| 4. | Smoke Management System | | | |
| | • Basements | N/A | N/A | N/A |
| | • Upper floors | Required | Natural Ventilation provided | MR |
| 5. | Fire Extinguishers | | | |
| | • Total numbers | 06 No's | Provided | MR |
| | • Types | ABC/CO ₂ type | Provided | MR |
| | • IS marking | ISI marked | ISI marked | MR |
| 6. | First-Aid Hose Reels | | | |
| | • Total numbers on each floor | N/A | N/A | N/A |
| | • Length of hose reel hose | N/A | N/A | N/A |
| | • Nozzle diameter | N/A | N/A | N/A |

N/12

| | | | | |
|-----|--|-----|-----|-----|
| 19. | Fire Control Room | | | |
| | • Detector System Panel | N/A | N/A | N/A |
| | • Flow Switch Panel | N/A | N/A | N/A |
| | • PA System Panel | N/A | N/A | N/A |
| | • Battery backup | N/A | N/A | N/A |
| | • Building Floor Plans | N/A | N/A | N/A |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2014/SZ/1589 dated 15.12.2014 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.



Sandeep
07/5/18

Signature of Inspecting Officer
Name:- Sandeep Duggal
Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

[Signature]
815/18

DCFO (S2)

[Signature]
9/5

FTM.
CFO for m.scell [Signature]
11/5

F.T. letter is put up for signature please.

CFO (S2) m.scell [Signature]

Sandeep
16/5/18

391/DO(SW)
07/05/18

1382/CFSL
11/5