GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/School/2018/NDZ/

Dated: 22/5/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Nehru Adarsh Sr. Sec. School, East Old Seelampur, Delhi-31, comprised of ground plus one upper floor only owned / occupied by Nehru Adarsh Sr. Sec. School was issued FSC vide letter No. F.6/DFS/MS/School/2013/NDZ/907 Dated 12/09/13. The school building was re-inspected by the officer concerned of this department on 23/04/18 in presence of Smt. Pratibha Nagar, Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. 262-362 dated 17/01/2005 issued by Director of Education and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from for a period three year, subject to conditions printed overleaf.

Issued on.....at New Delhi by

(Vipin Kental)
Chief Fire Officer

To.

The Principal,
M/s Nehru Adarsh Sr. Sec. School,
East Old Seelampur,
Delhi- 31.

Copy to:-

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi- 110053.

- Conditions -

- 1 All the means of escape shall be kept free of all type of obstruction all the time.
- 2 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

N/16

1. Name & address of the building: Nehru Adarsh Sr. Sec. School,

East Old Seelampur, Delhi-31. : Ground plus one upper floor only

2. Building is comprised of 3. Type of Occupancy

Educational

4. Type of Case

: Renewal

5. Details of Previous FSC letter

: F.6/DFS/MS/School/2013/NDZ/907 Dated 12/09/13

6. Fire Safety circular No

(Circular No. 262-362 dated17/01/05)

7. Date of Inspection

: 23/04/18

8. Name of the Inspecting officers : ADO Omprakesh

9. Name and designation of Officer

from the building side

: Smt. Pratibha Nagar (Principal)

10. Year of Construction

: 1980

11. Applicant's letter No

: Nil Dated – 17/03/2018

NO.	Minimum Standards on fire		Provided at Site	Remark			
	prevention and fire safety U/R33	as per D.O.E Cirucular Dt 17.01.05		MR/NMR			
1	Access to building		• .				
4	 Road width 	06 Mtrs	03 Mtrs	MR/old			
	7,		(A)	accepted			
	 Gate width 	N/A	N/A	N/A			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
_	a. Number of Staircases	5					
	Upper Floor	01 no.	02 no.	MR			
	Basement	N/A	N/A	N/A			
	b. Width of Staircases			¥			
	Upper Floor	1.50 mtr	1.50 m & 0.90 m	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases	N/A	N/A	N/A			
	to terrace	1.5 m	2.20 m	MR			
	e. Width of Corridor	1.0 m	1.15 m	MR			
0	1. Door Size			1011			
3	Compartmentation.	N/A	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	• File Dailipers						
4	Smoke Management System.	N/A	N/A	N/A			
_	Basement	N/A N/A	N/A	N/A			
	Upper floor Fig. 5. tip swip here	₩1V//\	14//\	14//-1			
5.	Fire Extinguishers	04 nos.	07 nos.	MR			
	Total numbers	ABC & Co2	ABC & Co2	MR			
	• types	091 92002-0 9000 000000 1-000 00002-000.					
	 ISI marking 	ISI marked	ISI marked	MR			

H/17

6	First-aid-Hose Reels.						
	Total numbers of each floor	01 no.	01 no.	MR			
		30 m	30 m	MR			
	 Length of hose reel hose 	5 mm	5 mm	MR			
	Nozzle diameter	5					
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	Provided	MR			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual	N/A	N/A	N/A			
	stopping	NI/A	N/A	N/A			
	> Pump House Access	N/A	IN/A	IN/A			
	Terrace Level	2201 DM	220LPM	MR			
	> Discharge of pump	220LPM 40 mtr	40 mtr	MR			
7	> Head of the Pump	Required	Provided	MR			
	> Power supply	N/A	N/A	N/A			
14	Auto Starting of pumpCaptive Water Storage for Fire Fighting		11//7	14//1			
14	Underground tank capacity	N/A	N/A	N/A			
	 Onderground tank capacity Draw-off connection 	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
		2500 Ltrs	2500 Ltrs	MR			
	 Overhead Tank capacity 	ZOUUTIIS	2000 LUS	IVIII			

16	Provision of Lifts.					
	 Pressurization of Lift Shaft 	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	Communication in lift car	N/A	N/A	N/A		
	Firemen's grounding switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	 Detector system panel 	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A		

The Fire protection systems provided in the building were Tested / Checked and found functional, at the time of inspection.

Keeping in view, of the deemed compliance, of the minimum standards on Fire prevention and Fire safety measures as required under the rules.

The Fire safety Certificate issued vide letter no. F.6/DFS/MS/School/2013/NDZ/907 Dated 120/09/13 has grant under circular No. 262-362 dated 17/01/2005 is recommended to renewal under rule 37 of the Delhi Fire Service Rule 2010.

Ombale an 25/4/18

Signature of the Inspecting Officer

: - Om Prakash

Designation: - ADO (Shahdara)

Fit. lelle is propos and put up for sounds for