

FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/EH/WZ/2018/ 1124

Dated: 17/5/2018

FIRE SAFETY CERTIFICATE

Certified that the **Haldiram Products Private Limited located at** Ground Floor(Shop No. 6 ,7 & 8) and First Floor (Shop No-106), Mall The ARSS Felix, Plot No. 40, Block-A, Community Centre, Paschim Vihar, New Delhi – 63 owned / occupied by Haldiram Products Private Limited has already been issued Fire Safety Certificate vide letter No. F6/DFS/MS/EH/2014/WZ/1465 dated 26/11/14. The premises / Building was re-inspected by the officers concerned of Fire Service on 02.05.2018 in the presence of Mr. Udit Awasthi (G.M.) and found that building / premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class **Assembly (Group-D)** with effect from 17/5/2018 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 17/5/18 **at New Delhi by.**

(ATUL GARG)

CHIEF FIRE OFFICER.

Copy to :-

1. Authorized Signatory, Haldiram Products Private Limited, 19-A, Shivaji Marg, Najafgarh Road, New Delhi-110015.
2. Dy. Health Officer (NDMC), Public Health Department, Rohini Zone, Sec.-5, Rohini, Delhi-85.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. The basement shall be used strictly as per the provision of building bye laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: **Haldiram's Products Private Limited**,
Ground Floor(Shop No. 6,7 & 8) and First Floor (Shop No-106), Mall The ARSS
Felix, Plot No. 40, Block-A, Community Centre, Paschim Vihar, New Delhi – 63.
2. Type of Occupancy : **Assembly** Area of the Shop:- 150m²
3. Type of Case : **Renewal**
4. Details of previous NOC : **F6/DFS/MS/EH/2014/WZ/1465 dated 26/11/14**
(FSC also issued to the Mall vide letter
No.F6/DFS/MS/2018/WZ/847 dated 25/04/2018)
5. Fire Safety directives Letter No. : **NBC (Part-IV)**
6. Date of inspection : **02/05/2018**
7. Name of the Inspecting Officer : **A.D.O. (Jwp) & D.O. (West)**
8. Name and designation of Officer
from the building side : **Sh. Udit Awasthi (G.M.)**
9. Year of Construction : **2013**
10. Applicant's letter No. : **Nil Dated 27/03/2018**

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 mtr	6 mtr	MR
	• Gate width	4.5 mtr	4.5 mtr	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	2	1 (Internal) 2 (Mall)	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	1.50 Mtr. & 1.00 Mtr.	1.50 Mtr.x2 (Mall) & 1.20 Mtr (Internal Stair)	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size (on ground & 1 st floor)	2Mtr. x1, 1Mtr. x1 (Emergency Door)	2.00Mtr. x1, 1.70Mtr. x1	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	4	6	M/R
	• Types	ISI marked ABC/CO ₂	Provided	M/R
	• IS marking	Required	Provided	M/R

6.	First - Aid Hose Reels			
	• Total numbers on each floor	1	Provided by the Mall	MR
	• Length of hose reel hose	30 Mtr.	Provided by the Mall	MR
	• Nozzle diameter	5 mm	Provided by the Mall	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Required	Provided	MR
	• Location of Main Panel	Required	Provided by the Mall	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	• Size of riser/down-comer	Required	Provided by the Mall	MR
	• Number of hydrants per floor	Required	Provided by the Mall	MR
	• Hose Box	Required	Provided by the Mall	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements Provided In the Mall			
	• Ground Level			
	➤ Discharge of main pump	N/A	Provided by the mall	N/R
	➤ Head of main pump	N/A	Provided by the mall	N/R
	➤ Number of main pumps	N/A	Provided by the mall	N/R
	➤ Jockey pump out put	N/A	Provided by the mall	N/R
	➤ Jockey pump head	N/A	Provided by the mall	N/R
	➤ Standby Pump out put	N/A	Provided by the mall	N/R
	➤ Standby Pump Head	N/A	Provided by the mall	N/R
	➤ Auto Staring/Manual stopping	N/A	Provided by the mall	N/R
	➤ Pump House Access	N/A	Provided by the mall	N/R
	• Terrace level			
	➤ Discharge of pump	900 LPM	Provided by the mall	N/R
	➤ Head of the pump	40 MTR	Provided by the mall	N/R
	➤ Power supply	Required	Provided by the mall	N/R
	➤ Auto starting of pump	Required	Provided by the mall	N/R
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw of connection	N/A	N/A	N/A

N/13

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Batter backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. **F6/DFS/MS/EH/2014/WZ/1465 dated 26/11/14** renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer
 Name : Ashok Kumar Jaiswal
 Designation : A.D.O. (Jwala Puri)

Signature of the Inspecting Officer
 Name : Mukesh Verma
 Designation : D.O. (West)

(Handwritten signatures and notes)

7/5/18

14/5/18

19/08/18

FT DG

F.T. is put up for sign. pl.

ADJ/JD

ADJ