GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/School/2018/NDZ/ 1586

Dated 26/5/18

FIRE SAFETY CERTIFICATE

Issued on.....at New Delhi by

(Vipin Kental) Chief Fire Officer

al a

Copy to:-

- The Principal, M/s Vishwa Bharti School, Gali No.-16, Brahmpuri, Delhi -110053.
- The Dy. Director of Education B-Block, Yamuna Vihar, Delhi

- Conditions -

- 1 All the means of escape shall be kept free of all type of obstruction all the time.
- 2 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"



1. Name & address of the building: Vishwa Bharti School, Gali No.-16, Brahmpuri, Delhi -110053.

2. Building is comprised of : G+1

3. Type of Occupancy : Educational

4. Type of Case : New
5. Details of Previous FSC letter : Nil.

6. Fire Safety direction letter No 7. Date of Inspection : 13/04/2018 : 13/04/2018

7. Date of Inspection : 13/04/20188. Name of the Inspecting officers : ADO Om Prakash

9. Name and designation of Officer

from the building side : Sh. Sunil Sharma (Principal)

10. Year of Construction : 1980

11. Applicant's letter No : VBS/24/2018/1681 Dated – 16/03/2018

	- 10 10 10 10 10 10 10 10 10 10 10 10 10						
NO.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remark			
1	Access to building	as per DO E	8	MR/NMF			
The second of th							
	Gate width	06 Mtrs	06 Mtrs	MR			
		N/A	N/A	N/A			
2	Width of internal road	N/A	N/A	N/A			
	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	02 no.	02 no.	MR			
	Basement	N/A	N/A	N/A			
	b. Width of Staircases			1 1// 1			
	Upper Floor	1.5 mtr	1.10 & 0.85 mtr	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of exits			14// (
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases to terrace	01 no.	01 no.	MR			
	e. Width of Corridor	1.5 m	2.0 m	MR			
	f. Door Size	1.0 m	1.0 m	MR			
3	Compartmentation.		, , , , , , , , , , , , , , , , , , ,				
	 Fire check door 	N/A	N/A	N/A			
•	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	 Water curtain 	N/A	N/A	N/A			
	 Fire Dampers 	N/A	N/A	N/A			
	Smoke Management System.						
	 Basement 	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A				
	Fire Extinguishers N/A N/A N/A						
	 Total numbers 	04 nos.	08 nos.	MID			
	types	ABC & Co2	ABC & Co2	MR MR			
	 ISI marking 	ISI marked	ISI marked	MR			
				IVII			

MIT

6	First-aid-Hose Reels.					
	Total numbers of each floor	N/A	N/A	NI/A		
	 Length of hose reel hose 			N/A		
	Nozzle diameter	N/A	N/A	N/A		
7	, , , , , , , , , , , , , , , , , , , ,	N/A	N/A	, N/A		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	 Location of main panel 	N/A	N/A	N/A		
	 Location of repeater panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	 Basement 	N/A	N/A	N/A		
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants	No				
	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.					
12	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	IN/A	IN/A	IN/A		
10	Ground Level	N/A	N/A	N/A		
	 Discharge of main Pump 	N/A	N/A	N/A		
	Head of Main Pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	N/A	N/A	N/A		
	Standby pump Head	N/A	N/A	N/A		
	Auto Starting /Manual	N/A	N/A	N/A		
	stopping					
	Pump House Access	N/A	N/A	N/A		
	Terrace Level					
	Discharge of pump	N/A	N/A	N/A		
	Head of the Pump	N/A	N/A	N/A		
	Power supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
14	Captive Water Storage for Fire Fighting					
1.	 Underground tank capacity 	N/A	N/A	N/A		
10	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
15	Exit Signage.	N/A	N/A	N/A		

		1012				
16	Provision of Lifts.	0	v			
1	 Pressurization of Lift Shaft 	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	 Location 	N/A	N/A	N/A		
19	Fire Control Room					
	 Detector system panel 	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
4	 PA system panel 	N/A	N/A	N/A		
	 Battery backup 	N/A	N/A	N/A		
	 Building Floor Plans 	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A		

The Fire protection systems provided in the building were Tested / Checked and found functional, at the time of inspection.

Keeping in view of the compliance of the minimum standards on Fire prevention and Fire safety measures as required under the F16/Estate/CC/Fire Safety/2011/3298 to 3398 issued by Director of Education, It is recommended to issue Fire Safety Certificate.

Ombales 1814/18

Signature of the Inspecting Officer

Name

:- Om Prakash

Designation :- ADO (Shahdara)

DO (East)

submitted for approved plus

m ee 1714118

(F). Why not requirement in inspection report as DOE CIL BT 1.3.11 ments once instead of

regurement only. 2. F7 D.

DUFONDZ

OFA (HAM

Sir f.T. Letter is put of for your bind Signature Please.