

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2018/SZ/ 1041

Dated: 14/5/18

FIRE SAFETY CERTIFICATE

Certified that the M/s **Mistral Restaurant** (Unit of Lettuce Entertainment You Limited) now changed the name of restaurant as M/s **Home** (Unit of PVR Limited) located at 3rd floor, Ambience Mall, Vasant Kunj, New Delhi was issued FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1303 dated 11/12/2013. The said premise was re-inspected by the officer concerned of this department on 26-04-2018 in the presence of Mr. Tyagi (Liaison Manager) and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class **Assembly** (Restaurant) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14/5/18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The DHO, S.D.M.C, Public Health Deptt., South Zone, Green Park, New Delhi-110016
2. Auth. Signatory, M/s Home (Unit of PVR Limited), 3rd floor, Ambience Mall, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept unlocked & free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

| INSPECTION REPORT | | | | |
|-------------------|---|--|--|-------------------------------|
| 1 | Name & Address of the Building | M/s Home (Unit of PVR Ltd) Formerly Mistral Restt, 3 rd floor, Amb. Mall, Vasant Kunj, New Delhi-70 | | |
| 2 | Type of Occupancy | Assembly 'Group-D' (Restaurant) | | |
| 3 | Building Comprised of | Three Tier basement, Ground + 03 upper floors | | |
| 4 | Type of Case | Renewal | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/EH/2013/SZ/1303 Dated 11/12/2013 | | |
| 6 | Fire Safety Directives Letter No | Nil | | |
| 7 | Date of Inspection | 26-04-2018 | | |
| 8 | Name of the Inspecting Officers | R.N. Singh, ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Mr. Amit Tyagi (Liaison Manager) | | |
| 10 | Year of construction | 2008 Restt running at 3 rd floor of the mall building | | |
| 11 | Applicant letter No. | DHO/SZ/2018/D/49 dated 11-04-2018 | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC requirements | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | F.6/DFS/MS/Mall/SZ/2017/33 Dated 09/01/2017 | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Restt within Amb. Mall | As above As above As above | MR N/A N/A |
| 2 | Number, width, type & arrangement of exits | Provided & Maintained by Ambience Mall | | |
| | a. Number of Staircase | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 02 (for Restt.) N/A | Provided near Restt. N/A | MR N/A |
| | b. Width of Staircase | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Upper floors • Basement floor | 1.5 mtr each N/A | Provided by Mall As above | MR N/A |
| | c. Protection of exits | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Fire check door • Pressurization | Required Required | As above As above | MR MR |
| | d. No. of continuous staircase to terrace | Required | As above | MR |
| | e. Width of corridor | N/A | N/A | N/A |
| | f. Door size | 1.5m (2 exits) | 2m & 1.05m | MR |
| 3 | Compartmentation. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. | Required Required N/A N/A N/A | As above As above As above As above As above | MR MR N/A N/A N/A |
| 4. | Smoke Management system. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Basement • Upper floors | 30 ACPH 12 ACPH | N/A Exhaust fans provided | N/A MR |
| 5. | Fire Extinguishers. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Total numbers • Types • ISI Marking | | 12 No's ABC & CO2 Provided | MR MR MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by Ambience Mall | | |
| | <ul style="list-style-type: none"> • Total numbers on each floor. • Length of hose-reel hose. • Nozzle Diameter | | As above As above As above | MR MR MR |

M/s Home Restt (formerly Mistral Restt.), 3rd floor, Ambience Mall, Vasant Kunj, New Delhi

| | | | | |
|-----|---|--|-------------------|-----|
| 7 | Automatic fire detection & alarming system | Provided & Maintained by Ambience Mall | | |
| | • Type of detectors | Required | As above | MR |
| | • Location of Main Panel | Required | As above | MR |
| | • Location of Repeater Panel | Required | As above | MR |
| | • Alternate source of power | Required | As above | MR |
| | • Hooter's location | Required | As above | MR |
| 8. | MOEFA | N/A | As above | MR |
| 9. | Public Address System | N/A | As above | MR |
| 10. | Automatic Sprinkler System | Provided & Maintained by Ambience Mall | | |
| | • Basement | N/A | As above | N/A |
| | • Upper floors | Required | As above | MR |
| | • Sprinkler above false ceiling | N/A | As above | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by Ambience Mall | | |
| | • Size of Riser/Down-comer | N/A | As above | MR |
| | • Number of Hydrant per floor | N/A | As above | MR |
| | • Hose box. | N/A | As above | MR |
| 12. | Yard Hydrants. | Provided & Maintained by Ambience Mall | | |
| | • Total number of hydrants. | N/A | N/A | N/A |
| | • Hose box. | N/A | N/A | N/A |
| 13. | Pumping arrangements. | Provided & Maintained by Ambience Mall | | |
| | • Ground Level | Provided & Maintained by Ambience Mall | | |
| | ➤ Discharge of main pump. | N/A | 2280 LPM | N/A |
| | ➤ Head of main pump. | N/A | 70m | N/A |
| | ➤ Number of main pumps. | N/A | 2 Nos | N/A |
| | ➤ Jockey Pump output. | N/A | 180 LPM | N/A |
| | ➤ Jockey Pump head. | N/A | 70m | N/A |
| | ➤ Standby Pump output. | N/A | 2280 LPM | N/A |
| | ➤ Standby Pump head. | N/A | 70m | N/A |
| | ➤ Auto Starting/Manual Stopping. | N/A | Provided | N/A |
| | ➤ Access to pump house | N/A | Provided | N/A |
| | • Terrace Level | Provided & Maintained by Ambience Mall | | |
| | ➤ Discharge of pump. | 900 LPM | As above | N/A |
| | ➤ Head of pump. | 40 mtr | As above | N/A |
| | ➤ Power supply. | Required | As above | N/A |
| | ➤ Auto starting of pump. | Required | As above | N/A |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by Ambience Mall | | |
| | • Underground tank capacity. | N/A | 5,00,000 Ltr | MR |
| | ➤ Draw-off connection. | N/A | As above | MR |
| | ➤ Fire Service Inlet. | N/A | As above | MR |
| | ➤ Access to tank. | N/A | As above | MR |
| | • Overhead tank capacity. | 10,000 Ltr | 30,000 Ltr | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by Ambience Mall | | |
| | • Pressurization of lift shaft. | Required | As above | MR |
| | • Pressurization of lift lobby. | Required | As above | MR |
| | • Communication in lift car. | Required | As above | MR |
| | • Fireman's switch. | Required | As above | MR |
| | • Lift signage. | Required | As above | MR |
| 17 | Standby Power Supply | Required | Provided (DG Set) | MR |
| 18. | Refuge Area | Provided & Maintained by Ambience Mall | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |

M/s Home Restt (formerly Mistral Restt.), 3rd floor, Ambience Mall, Vasant Kunj, New Delhi

| | | | | | |
|-----|--|--|----------|----------|----|
| 19. | Fire Control Room. | Provided & Maintained by Ambience Mall | | | |
| | | • Detector System Panel. | N/A | As above | MR |
| | | • Flow Switch Panel. | N/A | As above | MR |
| | | • PA system Panel. | N/A | As above | MR |
| | | • Battery backup | N/A | As above | MR |
| | • Building floor plan | N/A | As above | MR | |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | N/A | As above | N/A | |

The Fire protection systems provided in the premises/building was test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/SZ/1303 Dated 11/12/2013, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

R.N. Singh
26/11/18

Signature of the Inspecting Officer
Name : R.N. Singh
Designation: ADO (BCP)

M/s Home Restt (formerly Mistral Restt.), 3rd floor, Ambience Mall, Vasant Kunj, New Delhi

DO (SD)

Prakash
12/5/18

Dy. C.B. (SP)

Leaf
4/5



CFD 371

Ambience mall valid FSC copy to be breed
on file

4/5

DCFD 32

[Signature]
4/5

1354/CF 32
27/5/18/11/5
14/5



DO (SD)

Fire required document is placed at