

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 10 47

Dated: -19-13-

FIRE SAFETY CERTIFICATE

Certified that the Nine Street Guest House located at 9390, Multani Dhanda, Pahar Ganj, New Delhi comprised of Basement + Ground + 04 Upper floors, Basement (storage), Ground floor (Reception + 01 guest rooms), 1st floor (03 guest rooms), 2nd (03 guest rooms), 3rd floor (use for owner residence) and 4th floor (closed), total 07 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/EH/2015/NDZ/713 dated 11/05/15. The premises was re-inspected by the officer concerned of this department on 01/05/18 in the presence of Sh. K.K Singh (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 07 guest rooms only with effect from ----- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued --- 4 15 18 --- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

- of me 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ref. letter no. 1634/Addl. C.P/Lic. (H) dated 03/04/2018.
- 2. The Manager, Nine Street Guest House at 9390, Multani Dhanda, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1.	Name & address of the building Nine Street Guest House at 9390, Multani				
2.	Type of occupancy:-	Dhanda, Pahar Ganj, New Delhi Residential, Sub Division-A-1 B+Gr. + 04 Upper floors (total 07 Guest rooms) Basement (storage), Ground floor (Reception + 01			
	guest rooms), 1 st floor (03 guest rooms), 2 nd (03 rooms), 3 rd floor (use for owner residence) and 4 th floor (closed)				
3.	Type of case:-	Renewal			
	Details of previous FSC:- No. F6/DFS/MS/EH/2015/NDZ/713 date 11/05/15.				
5.	Fire safety directives No	N/A			
	6. Date of inspection:- 01/05/18				
7.	Name of the inspecting officer				
8.	Name & designation of officer				
	the building side:-		ingh (Manager)		
9.	Year of construction:-	2008			
10.	Applicant's letter No:-	1634/Addl. (C.P/Lic. (H) dated	03/04/2018. Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	03 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr			1 1 7 7	
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	01 Nos.	01 Nos.	MR	
	B. Width of staircase	0.1.1.05.	011105.	11111	
	1. Upper floors	0.80 mtr.	1.0 mtr.	MR	
	2. Basements	0.80 mtr.	1.0 mtr.	MR	
	C. Protection of exits	0.00 mm.	1.0 mt.	TVIC	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	01	01	MR	
	staircase to terrace		O I	IVIIX	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation	or mit.	or mu.	IVIIX	
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A N/A	N/A N/A	N/A N/A	
	3) Fire rating of shaft door	N/A N/A	N/A N/A		
	4) Water curtain	N/A		N/A	
	5) Fire Dampers	N/A N/A	N/A N/A	N/A	
4.	Smoke Management System	1N/A	IN/A	N/A	
→.	1) Basements	30 ACDII	NI/A	NI/A	
	2) Upper floors	30 ACPH	N/A	N/A	
	2) Opper noors	12 ACPH	Natural	MR	

5.	Fire Extinguishers			
3.	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided Provided	MR
(First-Aid Hose Reel	Required	Flovided	IVIK
6.	1) Total number of eachfloor	01	01	MR
		30 mtr.		MR
	2) Length of hose reel hose 3) Nozzle diameter	05 mm	30 mtr.	
7		And the control of th	05 mm	MR
7.	Automatic Fire Detection & A	N// A		
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	1		
	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	-		
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
10.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump	1471	11/11	1.071
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	h) Auto starting/Manual	IN/A	IN/A	IN/A
	stopping			
	2) Terrace level	225 I DN (225 I DM	MD
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	18 mtr.	18 mtr.	MR
	O HOMEON CHIMPIN	Required	Provided	MR
	c) Power supply			2.00
	d) Auto starting of pump	Required	Provided	MR

m

14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR	
15.	Exit Signage.	Required	Provided	·MR	
16.	Provision of Lifts.		_		
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection Syste Risk, if any:	N/A			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2015/NDZ/713 dated 11/05/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Dy. CFO(NDZ)