GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/School/2018/SZ/ / O 5 3

Dated: 1.4/.5/18

FIRE SAFETY CERTIFICATE

Certified that the **Sukhodaya Model School** located at L–101, Old Rangpuri Road, Mahipalpur Extn, New Delhi-110037, comprised of Ground + One upper floor was issued FSC by this department vide letter No. F6/MS/DFS/School/2014/SZ/1547 dated 11/12/2014. The school premises was re-inspected by officer concern of this department on 23/04/2018 in the presence of Mr. Subhash Chander (Manager) and observed that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. 262–362 dated 17/01/2005 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class '**Educational**' Group–B, (School) as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of the conditions mentioned below.

Issued on 1915 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

5

- 1. Manager, Sukhodaya Model School, L–101, Old Rangpuri Road, Mahipalpur Extn, New Delhi-110037
- 2. Directorate of Education, South MCD, Civic Centre, Minto Road, New Delhi-110002

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept unlocked and free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECTIO	N REPORT	toppi gguool I 10	1 014		
1 1	Name & Address of the Building	SUKHODAYA	MODEL SCHOOL, L-10	I, Olu		
		Rangpuri Road, Mahipalpur Extn, New Delhi–37				
	Type of Occupancy	Educational "Group-B" (School)				
3	Building Comprised of	Ground + 01 upper floor				
4	Type of Case	Renewal 1/2014/07/1547 Dt 11 12 2014				
	Details of Previous NOC	F.6/MS/DFS/School/2014/SZ/1547 Dt. 11-12-2014				
6	Fire Safety Directives Letter No	Circular No. 262-362 dated 17-01-2005				
7	Date of Inspection	23-04-2018				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of	Mr. Subhash Chander (Manager)				
	Officers from the building side					
10	Year of construction	1998 + 2005				
11	Applicant letter No.	SMS/31358/FHQ-1 dated 02-04-2018				
No.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks MR/NMI		
	and Fire Safety U/R 33	requirement		IVIR/IVII		
1	Access to Building.		()	MR		
	Road width	Required	6 mtr	N/A		
	 Gate width 	N/A	N/A			
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of ex	cits				
	a) Number of Staircase		§	1 (D)		
	Upper floors	02 Nos	03 Nos	MR		
	Basement floor	N/A	N/A	N/A		
-						
-		1.5m / 0.75m	1.16m, 1.13m & 0.90m	MR		
	* *	N/A	N/A	N/A		
	Basement floor	14/71				
	c) Protection of exits	NI/A	N/A	N/A		
	 Fire check door 	N/A		N/A		
	 Pressurization 	N/A	N/A			
al de la companya de	d) No. of continuous staircase to terrace	One	Provided	MR		
	e) Width of corridor	N/A	1.5 mtr	MR		
	f) Door size	1.0m	Provided	MR		
3	Compartmentation.					
	Fire check door.	N/A	N/A	N/A		
	 Sealing of electrical shafts. 	N/A	N/A	N/A		
	• Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	NA	NA	NA		
4.	Smoke Management system.			,		
-10	Basement	30 ACPH	N/A	N/A		
		12 ACPH	N/A	N/A		
5.	Fire Extinguishers.	Required	14 Nos	MR		
	Total numbers	ABC / CO2	CO2 & ABC type	MR		
	Types					
	ISI Marking	Required	Provided	MR		
6.	First Aid Hose Reels.					
0.	Total numbers on each floor.	One	Provided	MR		
	 Length of hose-reel hose. 	30m	Provided	MR		
		5mm	Provided	MR		
	Nozzle Diameter	Rangpuri Road, Mahipalpur Extn, New Delhi				

Sukhodaya Model School, L-101, Old Rangpuri Road, Mahipalpur Extn, New Delhi

7 Automatic fire detection & alarming s	ystem		
Type of detectors	N/A	N/A	N/A
 Location of Main Panel 	N/A	N/A	N/A
 Location of Repeater Panel 	N/A	N/A	N/A
Alternate source of power	N/A	N/A	N/A
Hooter's location	N/A	N/A	N/A
8. MOEFA	N/A	N/A	N/A
9. Public Address System	N/A	N/A	N/A
10. Automatic Sprinkler System			
Basement	N/A	N/A	N/A
 Upper floors 	N/A	N/A	N/A
 Sprinkler above false ceiling 	N/A	N/A	N/A
11. Internal Hydrants.	WAS TO LOOK		
Size of Riser/Down-comer	N/A	N/A	N/A
Number of Hydrant per floor	N/A	N/A	N/A
Hose box.	N/A	N/A	N/A
12. Yard Hydrants.			
Total number of hydrants.	N/A	N/A	N/A
Hose box.	N/A	N/A	N/A
13. Pumping arrangements.			
Ground Level			
 Discharge of main pump. 	N/A	N/A	N/A
➤ Head of main pump.	N/A	N/A	N/A
Number of main pumps.	N/A	N/A	N/A
Jockey Pump output.	N/A	N/A	N/A
Jockey Pump head.	N/A	N/A	N/A
Standby Pump output.	N/A	N/A	N/A
Standby pump head.	N/A	N/A	N/A
Auto Starting/Manual Stoppi	ing. N/A	N/A	N/A
Terrace Level			
Discharge of pump.	Required	450 LPM	MR
Head of pump.	Required	40m	MR
Power supply.	Required	N/A	MR
Auto starting of pump.	Required	N/A	MR
14. Captive water storage for Fire Fig			
 Underground tank capacity. 	N/A	N/A	N/A
Draw-off connection.	N/A	N/A	N/A
Fire Service Inlet.	N/A	N/A	N/A
Access to tank.	N/A	N/A	N/A
Overhead tank capacity.	2,500 Ltr	5,000 ltrs	MR
15. Exit Signage.	Required	Provided	MRA
16. Provisions of Lifts.	21/4	NI/A	N/A
 Pressurization of lift shaft. 	N/A	N/A	
 Pressurization of lift lobby. 	N/A	N/A	N/A
 Communication in lift car. 	N/A	N/A	N/A
• Fireman's switch.	N/A	N/A	N/A
 Lift signage. 	N/A	· N/A	N/A
17 Standby Power Supply	N/A	N/A	N/A
18. Refuge Area	14/73	7 7 1 X X	14/11
> Total area	N/A	N/A	N/A
The second secon	N/A	N/A	N/A
> Location	Old Rangpuri Road, Mahi		

Sukhodaya Model School, L-101, Old Rangpuri Road, Mahipalpur Extn, New Delhi

19.	Fire Control Room.			
2/0	Detector System Panel.	N/A	N/A	N/A
	 Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any.			1.6

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under Director of Education circular, the FSC issued vide letter No. F.6/MS/DFS/School/2014/SZ/1547 dated 11/12/2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

Sukhodaya Model School, L-101, Old Rangpuri Road, Mahipalpur Extn, New Delhi

DO (SD)

Milan

NISTIS

OVERSESSE)

1353 July 715 July 215 July 21

Cloyd

n·scell

FT 100.

4/5

A G. M. lelier is prormo of

Signation Wha

0300 (22) 1/2 NA

CPO(12)/

miscell

Weys.