GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated: 16/05/2012

No. F6/DFS/MS/EH/SZ/2018/ 1069

FIRE SAFETY CERTIFICATE

Certified that the M/s. PIKKLE Restaurant (A unit of Shine More Hospitality) running at First Floor of a building comprised of basement, stilt, ground plus three upper floors at Property No. 25/B, Pusa Road, New Delhi owned/occupied by M/s Shine More Hospitality was inspected by the officer concerned of this department on 13/04/2018 in presence of Sh. Devenderjit Singh Sahni (Partner) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (restaurant) with effect from 160512018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 16/05/18 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. Sh. Devenderjit Singh Sahni (Partner), M/s. PIKKLE Restaurant (A unit of Shine More Hospitality), First Floor, 25/B, Pusa Road, New Delhi.

2. The Deputy Health Officer, North Delhi Municipal Corporation, Karol Bagh Zone, New Delhi- 110005.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.

3. The trained firefighting staffs should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning

5. The basement shall be used as per the provisions of BBL.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : M/s. Pikkle Restaurant (a unit of Shine More Hospitality), FF, 25/B, Pusa Road, New Delhi.

: Assembly (Restaurant)

3. Type of Case : New Case4. Details of previous NOC : N/A

5. Fire Safety directives letter No : N/A.

6. Date of inspection : 13.04.2018

7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West)

8. Name and designation of officers

2. Type of Occupancy

from the building side : Sh. Devenderjit Singh Skie, owner

9. Year of Construction : 2017-18

10. Applicant's letter No. : Nil dated 22.03.2018

The said restaurant is running on First Floor of a building comprised of basement, stilt, ground and three upper floors.

S. No.		inimum Standards on fire ention and fire safety U/R 33	Requirement a BBL-83 / NBC-		Remarks MR/NMR			
1	Acces	eess to building						
	•	Road width	06 mts	Provided	MR			
	•	Gate width	4.5 mts	Provided	MR			
	•	Width of internal road	N/A	N/A	N/A			
Number, Width, Type & Arrangement of Exits								
	a. Number of staircases		-	-	_			
	•	Upper Floors	02	Provided	MR			
	•	Basements	N/A	N/A	N/A			
	b. Wic	th of staircases	-	-	· -			
	•	Upper Floors	2.0 mts.	2.0, 1.85 mts	MR			
	•	Basements	N/A	N/A	N/A			
	c. Prot	ection of exits	-	-	_			
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization	N/A	N/A	N/A			
	2	. of continuous staircases to race						
	g. Wid	th of Corridor	2.0 mts	No corridor	N/A			
	h. Doo	r Size	2.0 mts.	Provided	MR			
	Comp	artmentation.	**	-				
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
	Smoke Management System.							
	•	Basements	30 a/c per hou	r Exhaust fan provided	MR			

	• Upper floors	12 a/c per hour		MR			
5	Fire Extinguishers						
	Total numbers	12	Provided	MR			
	• Types	CO ₂ , ABC type	Provided	MR			
	IS marking	ISI marked	Provided	MR			
6	First-Aid Hose Reels.						
	 Total numbers on each floor 	01	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarmin						
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	• Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	Entire Restaurant	N/A	Provided				
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A			
	r unp House Access	N/A	N/A	N/A			

			N/3				
1		race level					
112	>	Discharge of pump	450 lpm	Provided	MR		
	~	Head of the pump	30 mts	Provided	MR		
	>	Power Supply	Required	Provided	MR		
	>	Auto Starting of pump	Required	Provided	MR		
14	Captive W	ater Storage for fire fightin					
	Und	erground tank capacity	N/A	N/A	N/A		
	> Drav	w-off connection	N/A	N/A	N/A		
	> Fire	service inlet	N/A	N/A	N/A		
		Access to tank	N/A	N/A	N/A		
	Over	head Tank capacity	20,000	Provided	MR		
15	Exit Signag	e.	Required	Provided	MR		
16	Provision of	f Lifts.					
	• Press	surization of Lift Shaft	N/A	N/A	N/A		
	• Press	surization of Lift lobby	N/A	N/A	N/A		
	• Com	munication In lift Car	N/A	N/A	N/A		
	• Firen	nan's Grounding Switch	N/A	N/A	N/A		
	• Lift S	Signage	N/A	N/A	N/A		
17	Standby pov	ndby power supply		Provided	MR		
18	Refuge Area.						
	> Total	Area	N/A	N/A	N/A		
	Locat	ion	N/A	N/A	N/A		
19	Fire Control	6					
	• Dete	ector System Panel	N/A	N/A	N/A		
RESE,	• Flow	v Switch Panel	N/A	N/A	N/A		
	PAS	System Panel	N/A	N/A	N/A		
8 4 1	• Batte	er backup	N/A	N/A	N/A		
Fire 9	• Buil	ding Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:		Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules-2010.

DFA is put up for approval & signature please

73/20/8W