## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2018/SZ/ 698

Dated: ..20/.7.//8

## **FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the name & style of M/s Carbon (A Unit of Delhi Lounge & Bar Pvt. Ltd) at Shop No-R3, lower ground floor, World Mark-I, Aerocity, New Delhi, comprised of Three tiers basement, ground, mezzanine + 06 upper floors. The restaurant running at lower ground floor of the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 12/07/2018 in the presence of Mr. Sanjay Pandey (Manager) and that the premises is fit for occupancy class 'Assembly' Group–D (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on \_\_\_\_\_\_ at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

## Copy to: -

- 1. DHO (NGZ), South MCD, Public Health Deptt., Dhansa Stand, Najafgarh, New Delhi-43
- 2. Director, M/s Carbon (Unit of Delhi Lounge & Bar Pvt. Ltd) at Shop No-R3, LGF, World Mark-I, Aerocity, IGI Airport, New Delhi-110037

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

		ON REPORT			
1	Name & Address of the Building	M/s CARBON at Shop No. R3, Lower ground floor, World Mark-I, Aerocity, IGI Airport, New Delhi-37 (A Unit of Delhi Lounge & Bar Pvt. Ltd)			
2	Type of Occupancy	Assembly 'Group-D' (Restaurant)			
3	Building comprised of	03 Basements, Ground, Mezzanine + 06 upper floors.			
4	Type of Case	New	Stourie, Wiezzainne + 00 up	per moors.	
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	12-07-2018			
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)			
9	Name & Designation of Officers from the building side	Mr. Sanjay Pandey (Manager)			
10	Year of construction	2014 Restt located LG Floor of the building			
11	Applicant letter No.		No. 9338 dated 28-06-2018	ung	
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC / BBL requirements	Provided at Site	Remarks MR/NMF	
1	Access to Building.		ixed/SZ/2018/338 Dated 28		
	Road width	Restt located	As above	MR	
	Gate width	in Asset-11,	As above	N/A	
	Width of internal road	Aerocity	As above	N/A	
2	Number, width, type & arrangement of		As above	IN/A	
	a. Number of Staircase	Provided & Maintained by Bldg Mgmt.			
	Upper floors	N/A	As above	N/A	
	Basement floor	N/A	to seem to prove the at 1997		
			As above	N/A	
	b. Width of Staircase	Provided & Maintained by Bldg Mgmt.			
	<ul> <li>Upper floors</li> </ul>	N/A	As above	N/A	
	<ul> <li>Basement floor</li> </ul>	N/A	As above	N/A	
	c. Protection of exits	Provided & Maintained by Bldg Mgmt.			
	Fire check door	N/A	As above	N/A	
	<ul> <li>Pressurization</li> </ul>	N/A	As above	N/A	
	d. No. of continuous staircase to terrace	Required			
	e. Width of corridor	N/A	As above N/A	MR	
	f. Door size	2 exits	2m & 1.5m	N/A MR	
3	Compartmentation.		ed & Maintained by Bldg M		
	• Fire check door.	N/A	As above	N/A	
	<ul> <li>Sealing of electrical shafts.</li> </ul>	N/A	As above As above	N/A	
	• Fire rating of shaft door.	N/A	As above	N/A	
	Water curtain	N/A	As above As above	N/A	
	Fire dampers.	N/A	As above	N/A	
4.	Smoke Management system.		A CONTRACTOR OF THE PARTY OF TH		
	Basement	Provided & Maintained by Bldg Mgmt.  30 ACPH N/A N/A			
	Upper floors	12 ACPH	N/A	N/A	
5.	Fire Extinguishers.	12 ACPH	Exhaust fans Provided	MR	
3.	Total numbers	06 N ==	D '1-1	3.45	
		06 Nos ABC / CO2	Provided	MR	
	Types ISI Marking		ABC & Co2	MR	
6.	ISI Marking     First Aid Hose Reels.	ISI marked	Provided	MR	
0.		Provided & Maintained by Bldg Mgmt.			
	Total numbers on each floor.	One	Provided near Restt.	MR	
	<ul> <li>Length of hose-reel hose.</li> </ul>	30m	As above	MR	
	Nozzle Diameter	5mm	As above	MR	

M/s Carbon at Shop No-R3, LGF, Cart No-01, World Mark-I, NH-8, West Wing, New Delhi

7	Automatic fire detection & alarming system.	Provided	l & Maintained by Bldg M	gmt.	
,	Type of detectors	N/A	Smoke & Heat	N/A	
la T	<ul> <li>Location of Main Panel</li> </ul>	N/A	Mezzanine floor	N/A	
	Location of Repeater Panel	N/A	FCR at GF	N/A	
	Alternate source of power	N/A	Provided	N/A	
	Hooter's location	N/A	All area	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System	Provided & Maintained by Bldg Mgmt.			
	Basement	N/A	As above	N/A	
	Upper floors	N/A	As above	N/A	
	Sprinkler above false ceiling	N/A	As above	N/A	
11.	Internal Hydrants.	Provided	d & Maintained by Bldg M	Igmt.	
	Size of Riser/Down-comer	N/A	As above	N/A	
	Number of Hydrant per floor	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
12.	Yard Hydrants.	Provided & Maintained by Bldg Mgmt.			
	Total number of hydrants.	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
13.	Pumping arrangements.			•	
	Ground Level	Provided & Maintained by Bldg Mgmt.			
	Discharge of main pump.	N/A	2280 LPM	N/A	
	➤ Head of main pump.	N/A	105m	N/A	
	Number of main pumps.	N/A	Two	N/A	
	> Jockey Pump output.	N/A	2 x 180 LPM	N/A	
	Jockey Pump head.	N/A	105m	N/A	
	Standby Pump output.	N/A	2280 LPM	N/A	
	Standby Pump head.	N/A	105m	N/A	
	Auto Starting / Manual Stopping.	N/A	Provided	N/A	
	Pump House Access	N/A	Provided	N/A	
	Terrace Level		d & Maintained by Bldg N	<del></del>	
	Discharge of pump.	450 LPM	As above	MR	
	Head of pump.	40 mtr	As above	MR	
	Power supply.	Required	As above	MR	
	> Auto starting of pump.	Required	As above	MR	
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Bldg Mgmt.			
	• Underground tank capacity.	N/A	1,50,000 Ltr	N/A	
	> Draw-off connection.	N/A	Provided	N/A	
	Fire Service Inlet.	N/A	Provided	N/A N/A	
	Access to tank.	N/A 5 000 L tr	Provided	MR	
15	Overhead tank capacity.  Frit Signage	5,000 Ltr Required	20,000 Ltr Provided	MR	
15. 16.	Exit Signage. Provision of Lifts.		ed & Maintained by Bldg N		
10.	Pressurization of lift shaft.	N/A	As above	N/A	
	D	N/A	As above As above	N/A	
	<ul><li>Pressurization of lift lobby.</li><li>Communication in lift car.</li></ul>	N/A	As above	N/A	
	<ul><li>Fireman's switch.</li></ul>	N/A	As above	N/A	
		N/A	As above	N/A	
17	• Lift signage.	Required	Provided	MR	
1/		DOCUMENT.	Flovided	IVII	
10	Standby Power Supply		ed & Maintained by Bldg M	Mamt	
18.	Refuge Area	Provide	ed & Maintained by Bldg N	<del></del>	
18.			ed & Maintained by Bldg N/A N/A	Mgmt.  N/A  N/A	

M/s Carbon at Shop No-R3, LGF, Cart No-01, World Mark-I, NH-8, West Wing, New Delhi

		Provided & Maintained by Bldg Mgmt.		
19.	Fire Control Room.	N/A	As above	N/A
	Detector System Panel.	N/A	As above	N/A
	Flow Switch Panel.	N/A	As above	N/A
	PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	N/A	As above	N/A
		N/A	As above	N/A
20		N/A	As above	N/A
20.	. a ! I Diala if ony	· /1:1di	no were test checked a	t random and

The Fire protection systems provided in the premises/building were test checked at random and found functional at the time of inspection. Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Carbon at Shop No-R3, LGF, Cart No-01, World Mark-I, NH-8, West Wing, New Delhi

Fen FSC of main premise is al-C/6.

As approved FT i putup for 1 can perus.

Seponstine Process.

M-SCEU Me 2017,