## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2018 / CNG / 1734

Dated 25/07/18

## FIRE SAFETY CERTIFICATE

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on 25/57/18 at New Delhi by

Chief Fire Officer Ph:-011-23414250

din

Copy to:-

1. Chief General Manager (Project), Indraprastha Gas Limited, IGL Bhawan, Plot no-4, Community Centre, R.K. Puram, Sec-09, New Delhi-110022.

**INSPECTION REPORT** 

1. Name & address of the building :CNG Filling Station (IGL) DSIDC, Sector-04, Rohini, Delhi-39.

2. Type of Occupancy : CNG Filling station **Group 'J'** 

3. Type of Case :Renewal

4. Details of previous NOC :F6/DFS/MS/2015/CNG/WZ/1105 Dated:26.06.2015

5. Fire Safety directives letter No :--

6. Date of inspection :25/06/20187. Name of the Inspecting Officers :ADO (RN)

8. Name and designation of officers

from the building side

: Mr. Sanjay, Manager

9. Year of Construction : 2010

10. Applicant's letter No.

: IGL/F&S/2018/15/37 dated 09.04.2018

	um Standards on fire prevention and fire safety U/R 33	NBC Provided at site Requirement		Remarks MR/NMR	
- Access t	Access to building				
•	Road width	08m	30m	MR	
•	Gate width	NA	NA	NA	
•	Width of internal road	NA NA		NA NA	
Number, Width, Type & Arrangement of Exits					
a. Numb	er of staircases				
•	<ul><li>Upper Floors</li><li>Basements</li></ul>	Required	Provided	MR	
		NA	NA	NA	
b. Width	of staircases				
•	ерре: 1 10013	1.25 mtr.	1.25m	MR	
o Duatas	Basements	NA	NA	NA	
	tion of exits				
	<ul><li>Fire check door</li><li>Pressurization</li></ul>	NA	NA	NA	
		NA	NA	NA	
	f continuous staircases to terrace	NA	NA	NA	
f. Door S	of Corridor ize	NA	NA	NA	
		1.0m	1.0m	MR	

3	Compartmentation.						
	Piccolar I	·	1				
	• Fire check door	NA	NA		NA		
	Sealing of electrical shafts	NA	NA		NA		
	Fire Rating of shaft door	NA	NA		NA		
	<ul><li>Water Curtain</li><li>Fire Dampers</li></ul>	NA	NA		NA		
	The Dampers	NA	NA		NA		
1	Smoke Management System.						
	Basements	30 a/c per hour	NA		NA		
	• Upper floors	12 a/c per hour	NA		NA		
5	Fire Extinguishers						
	Total numbers	19nos	22nos		MR		
	• Types	ABC & Co2	06 trolley- 75 kg. 13- DCP, CO2-03	1	MR		
	ISI marking	Yes	Yes		MR		
	First-Aid Hose Reels.	1					
	Total numbers on each floor	NA	NA		NA		
	Length of hose reel hose	NA	NA		NA		
	Nozzle diameter	NA	NA		NA		
	Automatic fire detection and alarming system.						
	Type of detectors	NA	NA		NA		
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA		NA		
	Location of Repeater Panel	NA	NA		NA		
	<ul><li>Alternate source of power</li><li>Hooters' Location</li></ul>	NA	NA		NA		
		NA	NA		NA		
	MOEFA	Required	Provided		MR		
	Public Address System.	NA	NA		NA		
	Automatic Sprinkler System.						
	Basement	NA	NA		NA		
	Upper Floor	NA	NA		NA		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	NA	NA		NA		
	Internal Hydrants	-			11/1		

1		NA	NA	NA		
	Size of riser/down-comer	NA NA	NA	NA		
	Number of hydrants per floor		NA	NA		
	Hose Box	NA	1,42			
Yar	d Hydrants.		NIA	NA		
	Total number of hydrants	NA	NA			
	Total number of flydrams     Hose Box	NA	NA	NA		
Pur	Pumping Arrangements.					
	Ground Level		*	- 7/ A		
	Dumn	N/A	N/A	N/A		
	<ul><li>Discharge of main Fump</li><li>Head of Main pump</li></ul>	N/A	N/A	N/A		
	Number of main pumps		N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A		N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A			
	Auto Starting/ Manual stopping	S N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level			1		
	Discharge of pump	NA	NA	NA		
	> Head of the pump	NA NA	NA	NA		
	> Power Supply		NA	NA NA		
	Auto Starting of pump	NA		NA		
		NA	NA	1112		
14	4 Captive Water Storage for fire fighting.			2		
14		NA	NA	NA		
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	. NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity		NA	NA		
15	Exit Signage.	NA	1474			
16	Provision of Lifts.	-		NTIA		
10		N/A	N/A	N/A		
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A		



					9	
	Communication In lift Car	NA	NA		NA	
	Fireman's Grounding Switch	NA	NA		NA	
	Lift Signage	NA	NA		NA	
17	Standby power supply	NA	NA		NA	
18	Refuge Area.					
	> Total Area	N/A	N/A		N/A	
	Location	N/A	N/A		N/A	
19	Fire Control Room					
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> </ul>	N/A		N/A	N/A	
		N/A		N/A	N/A	
		N/A		N/A	N/A	
	Batter backup	N/A		N/A	N/A	
	Building Floor Plans	N/A		N/A		
20	Special Fire Protection Systems for		Fire buckets filled with sand, No		N/A MR	
	Protection of special Risks, if any:	smoking boards were found displayed in Hindi & English. No lose electric wiring were seen in		Provided	·	
		premises & Co2 flood found provide	ing system	*		
21	DCP spray System for cascade	Provided		8 5	MR	
				4, 7		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 1105 dated 26.06.2015 under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation:- ADO/RN

49

Y V )

. .

tette is fa

1 ~.

(Ay

Mouth

and the same