GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 1772

Dated: 31/7/12

FIRE SAFETY CERTIFICATE

Issued on ... 1.1.7.1.1.8......... at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

2. The Manager,

Amba Dx. Guest House at 3437, Dariba Pan, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

1	.Name & address of the buildin	SPECTION REP					
1.	.ivaine & address of the building		Guest House at	3437, Dariba			
2	Type of occupancy	Pan, Paha	r Ganj, New Delhi	i			
۷,	Type of occupancy:-	Residentia	l, Sub Division-A	- 1			
	Grand Grand Grand (12 + 7 total 19 Guest rooms)						
	Ground floor (03 guest rooms + reception), I'st floor to 4th floor (04 guest rooms at each						
3.	Type of case:-	Renewal	Addetien of soom	ms at each floor			
	Details of previous FSC:-	F6/DFS/M	S/GH/2015/NDZ/	1022			
		09/10/201		1822 dated			
5.	Fire safety directives No N/A Date of inspection:- 05/06/18						
6.							
8.	Name of the inspecting officer:- Sh. Manoj Kumar Sharma (ADO/CC) Name & designation of officer						
	From the building side:-		ndon (M				
9.	The contract (Manager)						
	0 4 1:						
No.	Minimum Standards on fire	Nil dated 03/04 Requirement/					
	Prevention and fire safety U/R	Existing fire	Provided at site	Remarks			
	33	safety		MR/NMR			
		arrangements					
	Access to Building						
	1) Road width	N/A	N/A	N/A			
	2) Gate width	N/A	N/A	N/A			
	3) Width of internal road	N/A	N/A	N/A			
	Number, Width Type & Ar		vite	IN/A			
	A. Number of staircases	generat of E.	ATTS				
	1. Upper floors	01 No.	01 No.	MD			
	2. Basements	N/A	N/A	MR			
	B. Width of staircase	11/71	IN/A	N/A			
	1. Upper floors	0.80 mtr.	1.5	1.65			
	Opper moors	Existing old case	1.5 mtr.	MR			
	2. Basements	N/A	NI/A	21/1			
	C. Protection of exits	IN/ A	N/A	N/A			
	1. Fire check door	N/A	N/A				
	2. Pressurization	The state of the s	N/A	1 17 7 8			
	D. No. of continuous	N/A	N/A	N/A			
		01	01	MR			
-	staircase to terrace			T.			
+	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	1 mtr.	1 mtr.	MR			
	Compartmentation						
-	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System		4	1			
	1) Basements	NA	N/A	N/A			
	2) Upper floors						
	2) Opper Hoors	12 a/c per	Natural Ventilation	MR			

5.	Fire Extinguishers	λ				
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel	reception	Trovided	IVIK		
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System		. 1/ / 1	IN//A		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling		13//1	IN/ PA		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor			14/74		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump		71	13/71		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual stopping	N/A	N/A	N/A		
	2) Terrace level	3				
	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
4.	Captive Water Storage for Fi	re Fighting	TTOVICCO	IVIIX		

	capacity			
	a) Draw-off connection	N/A	N/A	
	b) Fire service inlet	N/A	N/A N/A	N/A
_	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5000 ltr.	5000 ltr.	N/A MR
15.	Exit Signage.	D 1		
16.	Provision of Lifts.	Required	Provided	MR
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
18.	Stand by Power Supply	Required	Provided	MR
10.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	27/4	
	a) Detector system	70.5	N/A	N/A
	panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	·N/A
0.		N/A	N/A	N/A
J	Special Fire Protection System for Protection of special Risk, if any:			

Earlier owner was informed vide this department letter no. F6/DFS/MS/GH/2009/1395 dated 19.05.2009 point no. 6 which clearly states addition of room will be considered after getting the clarification Delhi Police Lic. Now Delhi Police recommended 7 guest rooms vide this latter no. 2889-97/Addl. C.P/Lic.(H) dated 04.10.2017.

The guest house building have added 07 (seven) more rooms. Now the floor wise occupancy at Ground floor (03 guest rooms + reception), 1st floor to 4th floor (04 guest rooms at each floor), total 19 guest rooms.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide F6/DFS/MS/GH/2015/NDZ/1822 dated 09/10/2015 renewal under rule 35 of the Delhi Fire Service

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Defo(MDZ) A.

Prisa case of addition Talteration of accordingly.