## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS /GH/ 2018 / 1756

Dated: 27/7 /2018

## FIRE SAFETY CERTIFICATE

Certified that the Hotel Seven Seas located at A-2 & 3, Sarai Pipal Thala Extn. Adarsh Nagar, Delhi comprised of Basement+ Ground + two upper floors (Ground floor Reception+ Two Room, First floor 15 Rooms, Second floor 14 Rooms) owned/occupied by Hotel Seven Seas (Puran Chand) has already been issue fire safety certificate vide letter no. F6/DFS/MS/2015/GH/WZ/945 dated 08.06.2015 The premises was re-inspected by the officer concerned of Fire Service on 05.07.2018 in the presence of Sh. Ramesh (Manager) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition.. The premises have therefore deemed complied with the fire prevention and fire safety accordance with rule 33 of the Delhi Fire Service rule 2010, and the building/ premises is fit for occupancy Class Residential (Guest House) for total 31 Guest Rooms Only with effect from 7 /7 /2018 for a period, of three years in accordance with rules 36 unless renewed under rule. 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in">www.dfs.Delhigovt.nic.in</a>
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on ... 2.7.17.1.8... at New Delhi by

Chief Fire Officer Ph:-Q11-23414250

Copy to: -

1. The Additional Commissioner of Police (Lic), 1st floor, Police Station, Defence Colony, New Delhi.

2. The Manager, Hotel Seven Seas A-2 & 3, Sarai Pipal Thala Extn. Adarsh Nagar, Delhi.

**INSPECTION REPORT** 

1. Name & address of the building

: Hotel Seven Seas A-2,3 Sarai Pipal Thala Extn. Adarsh Nagar, Delhi.

2. Type of Occupancy

:Guest House(B+G+02 upper floors)

3. Type of Case

:Renewal

4. Details of previous NOC

:F6/DFS/MS/2015/GH/WZ/945 dated 08/06/2015

5. Fire Safety directives letter No

:Nil

6. Date of inspection

:05.07.2018

7. Name of the Inspecting Officers

:ADO (RN)

8. Name and designation of officers

from the building side

: Sh. Ramesh (Manager)

9. Year of Construction

. ....

10. Applicant's letter No.

: Nil dated 03.06.2018

Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR			
Access to building						
Road width	06m	9m	MR			
Gate width	Directly	Directly Accessible	MR			
Width of internal road	Accessible NA	NA NA	NA			
Number, Width, Type & Arrangement of Exits						
a. Number of staircases		e de la companya de				
Upper Floors	02	02	MR			
Basements	01	01				
b. Width of staircases	01	01 01 MR(old case)				
Upper Floors	1m	1.26m & 1.00m	N/D/-11			
Basements	1 m	1.26m & 1.00m	MR(old case)			
c. Protection of exits	1111	1.02111	MR(old case)			
Fire check door	27.4	214				
Pressurization	NA	NA	NA			
d. No. of continuous staircases to terrace	01	01	MR			
e. Width of Corridor	NA	NA	NA			
f. Door Size	NA	NA	NA			
	NA	NA	NA			

3	Compartmentation.					
	Fire check door	NA	NA		NA	
	Sealing of electrical shafts	NA	NA		NA	
	Fire Rating of shaft door	NA	NA	-	NA	
	Water Curtain	NA	NA		NA	
	• Fire Dampers				1	
	·	NA	NA		NA	
	Smoke Management System.					
	Basements	30 a/c per hour	NA		NA	
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	NA		MR	
	Fire Extinguishers					
	Total numbers	13 nos	15	T	MR	
	Types	ABC & Co2	W. Co2 - (9ltr Cap)	-	MR	
	ISI marking	7120 & 002	ABC type – one at each floor		IVIX	
		Yes	Yes		MR	
	First-Aid Hose Reels.					
	Total numbers on each floor	01	01		MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30m	30m		MR	
	Nozzle diameter	5mm	5mm		MR	
	Automatic fire detection and alarming system.					
	Type of detectors	NA	NA		NA	
	Location of Main Panel	NA	NA		NA	
	Location of Repeater Panel	NA	. NA	1.50	NA	
	Alternate source of power	NA	NA		NA	
	Hooters' Location	NA	NA		NA	
	MOEFA	Required	Provided		MR	
	Public Address System.	NA	NA		NA	
)	Automatic Sprinkler System.					
	Basement	Required	Provided		MR	
	Upper Floor	NA	NA		NA	
	Sprinkler above false ceiling	NA	NA		NA	
	Internal Hydrants					

	Size of riser/down-comer	NA	NA	NA			
•	Number of hydrants per floor	NA	NA	NA			
•	Hose Box	NA	NA	NA			
Yard	Yard Hydrants.						
•	Total number of hydrants	NA	NA	NA			
•	Hose Box	NA	NA	NA			
Pump	Pumping Arrangements.						
•	Ground Level		Total Control of the				
	Discharge of main Pump	N/A	N/A	N/A			
-	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	➤ Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
•	<ul><li>Standby Pump Head</li><li>Auto Starting/ Manual stopping</li></ul>	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
•	Terrace level						
	Discharge of pump	450lpm	450lpm	MR			
	> Head of the pump	40m	40m	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
Capt	Captive Water Storage for fire fighting.						
	Underground tank capacity	NA	NA	NA			
7	Draw-off connection	NA	NA	NA			
3	Fire service inlet	NA	NA	NA			
7	Access to tank	NA	NA	NA			
	Overhead Tank capacity	10,000ltr	10,000 ltr.	MR			
Exit	Signage.	Required	Provided	MR			
1	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
5 Prov		N/A N/A	N/A N/A	N/A N/A			

	Fireman's Grounding Switch	NA	NA	NA	
	• Lift Signage	NA	NA	NA	
7	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	* N/A	
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
C	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 945 dated 08.06.2015 under rule 35 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation: - ADO/RN

As approved, f.t. tettre is puty