

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F.6/DFS/MS/2018/NDZ/ 54/1778

Dated: 01/08/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Barbeque Nation Restaurant at G-2 & G-3 Ginger Hotel, Plot No.- C, DDA Community Centre, Vivek Vihar, Delhi, comprised of ground floor only owned / occupied by M/s A unit of Barbeque Nation Hospitality Ltd., was granted FSC vide letter no. F6/DFS/MS/EH/2015/NDZ/1274 dated 16/07/15. The restaurant was inspected by the officer concerned of this department on 25.07.18 in presence of (Manager) and found that the restaurant have deemed complied with the Fire prevention and Fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010. with effect from ...01/08/18 for a period of three years in accordance with Rule 36 unless renewed under rule 37, or sooner cancelled under Rule 40, and subject to compliance of the conditions under Rule 38, of the Delhi Fire Service Rule 2010, subject to conditions printed overleaf.

Issued on 01/08/18 at New Delhi by

178
(Vipin Kertal)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. Barbeque Nation Restaurant
M/s A unit of Barbeque Nation Hospitality Ltd.
G-2 & G-3 Ginger Hotel, Plot No- C,
DDA Community Centre, Vivek Vihar, Delhi.
2. The Dy. Health Officer,
East Delhi Municipal Corporation, Health Department,
Shahdara (South) Zone, Karkardooma,
Shahdara, Delhi.

01/1

CONDITIONS

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. All comments/ directions of the Licensing Department shall always be permitted and followed.
7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : M/s Barbeque Nation at G-2 & G-3 Ginger Hotel,
Plot No.- C, DDA Community Centre, Vivek Vihar, Delhi.
2. Building is comprised of : Ground floor only.
3. Type of Occupancy : Assembly, (Restaurant)
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/2015/NDZ/1274 dated 16/07/15.
6. Fire Safety direction letter No : NBC Part-IV,
7. Date of Inspection : 25.07.2018
8. Name of the Inspecting officers : F. Brown (DO East)& Om Prakash (ADO Shahdara)
9. Name and designation of officer
from the building side : (Manager)
10. Year of construction : 2009
- 11 Applicant's letter No : NIL dated 02/07/18.

S.No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	NBC Part-IV Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	12 m	30 m	MR
	• Gate width	4.5 m	06 m	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits.			
	a. Number of Staircases			
	• Upper floor	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	B. Width of Staircases	N/A	N/A	N/A
	• Upper floor	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	c. Protection of Exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	02 m	03 nos. 2.0 m each	MR
3	Compartmentation.	Required	Provided for entire building	
	• Fire check door	N/A	Provided	MR
	• Sealing of electrical shafts	N/A	sealed	MR
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basement	N/A	N/A	N/A
	• Upper floor	N/A	N/A	N/A
5.	Fire Extinguishers.			
	• Total numbers	04 nos.	06 Nos.	MR
	• Types	ABC /CO ₂	ABC /CO ₂	MR
	• IS marking	ISI marked	ISI marked	MR

2/10

06	First-Aid-Hose Reels.			
	• Total numbers on each floor	01 no.	01 no.	MR
	• Length of hose reel hose	30 m	30 m	MR
	• Nozzle diameter	5 mm	5 mm	MR
07	Automatic Fire Detection and Alarming System.			
	• Type of detectors	Heat/smoke	Provided	MR
	• Location of main panel	N/A	At ground floor	MR
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	Battery & DG Set	Provided	MR
	• Hooter's location	Different Location	Different Location	MR
08	MOEFA	Required	Provided	MR
09	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	150mm	150mm	MR
	• Number of hydrants per floor	02 nos	02 nos	MR
	• Hose box	02 nos	02 nos	MR
12	Yard Hydrants.			
	• Total number of hydrants	NA	Provided	MR
	• Hose box	NA	Provided	MR
13	Pumping Arrangements. Provided for entire mall building			
	• Ground Level	NA	Provided	MR
	• Discharge of main pump	N/A	2280 LPM	MR
	• Head of main pump	N/A	88 mtrs	MR
	• Number of main pumps	N/A	2 nos.	MR
	• Jockey pump out put	N/A	450 LPM	MR
	• Jockey pump head	N/A	88 mtrs	MR
	• Standby pump out put	N/A	2280 LPM	MR
	• Standby pump head	N/A	88 mtrs	MR
	• Auto starting /manual stopping	N/A	Provided	MR
	• Pump house access	N/A	Provided	MR
	➤ Terrace Level			
	• Discharge of pump	450 lpm	Provided	MR
	• Head of the pump	88 mtrs	Provided	MR
	• Power supply	Required	Provided	MR
	• Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	N/A	2,00,000 Ltrs.	MR
	• Draw-off connection	N/A	Provided	MR
	• Fire service inlet	N/A	Provided	MR
	• Access to tank	N/A	Provided	MR
	• Overhead Tank capacity	20000 Ltrs.	20000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room For main building			
	• Detector system panel	Required	Provided	MR
	• Flow switch panel	N/A	Provided	MR
	• PA system panel	N/A	Provided	MR
	• Battery backup	N/A	Provided	MR
	• Building Floor Plans	N/A	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

Keeping in view the non compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to issue the shortcomings as stated above at Sl. No. 5, 6.

Om Prakash
28/12/18

Signature of the Inspecting Officer
Name: Om Prakash
Designation: ADO (Shahdara)

Francis Brown

Signature of the Inspecting Officer
Name: Francis Brown
Designation: DO (East)

DCFO (NDZ) *[Signature]*

C.F.D. m.scell FT/107.
31/7

F.T. letter is put up for signature please.

C.F.D.

[Signature]