GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2018/NDZ/ 1809

Dated: 3/8/18

FIRE SAFETY CERTIFICATE

Certified that the Sneh International School, Junior, Jagriti Enclave, Vikas Marg, Extn., Delhi-92, owned/occupied by Sneh International School, Comprised of ground plus two upper floors was granted FSC vide letter no. F6/DFS/MS/School/2013/NDZ/834 dt-03/09/13 (for B,G+1). The school building was inspected by the officer concerned of this department on 12/07/18 in the presence of Ms. Seema Joshi (Cordinator) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the BBL & NBC and found that the building is fit for occupancy class B "Educational Building" with effect from 3/8/18 for a period of three years, subject to conditions printed overleaf.

Issued on 3/8/18 at New Delhi by

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

To,

The Principal, Sneh International School, Junior, Jagriti Enclave, Vikas Marg, Extn. Delhi-92.

Copy to:-

The Deputy Director of Education, D-Block, Anand Vihar, Delhi.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. "The owner /occupier shall apply for renewal of this Fire Safety certificate to the Director inform'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

Name & address of the building

: Sneh International School, Junior, Jagriti Enclave, Vikas Marg

Extn., Delhi-92.

2. Building is comprised of

: B+G+2 upper floors.

3. Type of Occupancy

: Educational

4. Type of Case

: Additional/Alteration

5. Details of Previous FSC letter

: F6/DFS/MS/School/2013/NDZ/834 dt-03/09/13 (for B,G+1)

6. Fire Safety direction letter No

: NBC

7. Date of Inspection

: 12/07/18

8. Name of the Inspecting officers

: ADO R.K. Yadav

9. Name and designation of Officer:

From the building side

: Ms. Seema Joshi (Cordinator)

10. Year of Construction

: 2011

11. Applicant's letter No

: Nil Dated- 21/06/18

S. N	Minimum Standards on fire prevention and fire safety U/R33	BBL & NBC Part-IV Requirement	Provided at Site	Remarks MR/NMR			
1	Access to building						
	Road width	06 m.	06 m.	MR			
	 Gate width 	4.5 m.	4.5 m.	MR			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases	,					
	Upper Floor	01Nos.	02 Nos.	MR			
	Basement	01Nos.	02 Nos	MR			
	B. Width of Staircases	e e a		2			
	Upper Floor	1.50 m. & less	1.60 & 1.20m	MR			
		1.50 m.	1 no of	MR			
	Basement		staircase 1.30	old			
			m & 2 exits	acceptable			
	c. Protection of exits			The first is			
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases	01 No.	01 No.	MR			
	to terrace	1.50m.	1.50m.	MR			
	e. Width of Corridor		01 m.	MR			
	f. Door Size	01 m.	UTIII.	IVIIX			
3	Compartmentation.	NI/A	NI/A	N/A			
	Fire check door	N/A	N/A N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	IN/A	IN/A			
4	Smoke Management System.						
	 Basement 	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
5.	Fire Extinguishers						
	 Total numbers 	08 nos.	08 nos.	MR			
	types	ABC /CO ₂	ABC /CO ₂	MR			
	IS marking	ISI marked	ISI marked	MR			

3	First-aid-Hose Reels.	1 Nos.	Provided	MR				
	Total numbers of each floor	30mtr.	Provided	MR				
	Length of hose reel hose	05mm	Provided	MR				
	Nozzle diameter O5mm Provided							
		N/A	N/A	N/A				
	Type of detectors	N/A	N/A	N/A				
	Location of main panel		N/A	N/A				
	Location of repeater	N/A	IN/A	14// 3				
	panel Alternate source of	N/A	N/A	N/A				
		IN/A	1477					
	powerHooter's location	N/A	N/A	N/A				
	S COURS AND S COUR	N/A	N/A	N/A				
3	MOEFA Public address System.	Required	Provided	MR				
)	Automatic Sprinkler System.	required						
10		Required	Provided	MR				
	Basement	Nequired	11001404					
	upper floor	N/A	N/A	N/A				
	sprinkler above false	N/A	N/A	N/A				
	ceiling	e ga Tolka	9 5 6	E .				
11	Internal Hydrants	20 LBH 90 95 52 9						
	size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per	N/A	N/A	N/A				
	floor							
	Hose Box	N/A	N/A	N/A				
12	Yard Hydrants.	29	9					
3 6000	Total number of hydrants	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
13	Pumping Arrangements.							
10	Ground Level							
	Discharge of main	N/A	N/A	N/A				
	Pump	44		10.7				
	Head of Main Pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A	N/A				
	Standby pump Head	N/A	N/A	N/A				
	Auto Starting /Manual	N/A	N/A	N/A				
	stopping	NI/A	NI/A	N/A				
	Pump House Access	N/A	N/A	IN/A				
	Terrace Level	450 1 511	Descrided	MR				
	Discharge of pump	450 LPM	Provided Provided	MR				
	Head of the Pump	40 M	Provided	MR				
	> Power supply	Required	Provided	MR				
	Auto Starting of pump	Required	Flovided	IVII				
14	Captive Water Storage for Fire Fighting.							
	Underground tank capacity	N/A	N/A	N/A				
	> Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	· N/A	N/A	N/A				
	> Access to tank	N/A	N/A	N/A				
-	Overhead Tank capacity	15,000 Ltr	. 15,000Ltr.	MR				
	5 Exit Signage.	Required		MR				

6	Provision of Lifts.	N/A	N/A	
	Pressurization of Lift Shaft		N/A	NII
	Pressurization of Lift lobby	N/A	N/A	N/A
-	Communication in lift car	N/A	N/A	N/A
	Firemen's grounding	N/A		
	switch	NI/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	1071	
18	Refuge Area.	N/A	N/A	N/A
10	Total area	N/A	N/A	N/A
- 1-	• Location	IN/A	*	
19	Fire Control Room	N/A	N/A	N/A
13	Detector system panel	N/A	N/A	N/A
	 Flow switch panel 	N/A	N/A	N/A
	 PA system panel 		N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Drotoction systems	N/A		1.50

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

In view of deemed compliance of the minimum standards of fire prevention and fire Safety measured as required under the rules. The fire safety certificate issued vide letter no. F6/DFS/MS/School/2013/NDZ/834 dt-03/09/13 (for B,G+1) renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name

R.K. Yadav

Designation ADO (LN)

6,56/C/0 MM

Dy cropupy.

CFO- mscell 2017. En, FT Letter a pur up for signahuept RKet