GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/School/2018/SZ/ 1823

Dated: 6.1.8.1.1.8

FIRE SAFETY CERTIFICATE

Certified that **The Siddhartha Public School** located at 586–D/7, Buddha Vihar, Govindpuri, New Delhi-110019, comprised of ground plus two upper floors was issued FSC by this department vide letter No.F.6/DFS/MS/School/2014/SZ/601 dated 13-05-2014. The premises was re-inspection by officer concerned by this department on 12.07.2018 in the presence of Sh. Ram Singh (Secretary) of the school and found that school building is now comprised of ground plus three upper floors (School management has submitted an undertaking that third floor is not used for school purpose). The school building upto 2nd floor have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the premises is fit for occupancy class **"Education, Group–B"** (School) as above with effect from the date of issue of this certificate for period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued 6/8/18 at New Delhi by

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to: -

- 1. Secretary, The Siddhartha Public School at 586-D/7, Buddha Vihar, Govindpuri, N. Delhi-19
- 2. Directorate of Education, South MCD, Civic Centre, Minto Road, New Delhi-110002

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 7. Third floor of the building shall not be used for school purpose.

	INSPECT	ION REPORT				
1	Name & Address of the Building					
		Vihar, Govind Puri, New Delhi-110019				
2	Type of Occupancy	Educational, Group—B (School)				
3	Building Comprised of	Ground + 03 upper floors but school management h				
		submitted an undertaking not to use 3rd floor for				
4	Type of Case	Renewal (upto 2 nd	floor only)			
5	Details of Previous NOC	F.6/MS/DFS/2014	/SZ/601 dated 13-05-20	14 for G+02		
6	Fire Safety Directives Letter No		Safety/2011/3298 to 3398 date	d 01.03.2011		
7	Date of Inspection	12-07-2018				
9	Name of the Inspecting Officers	Mehmood, ADO (SJ)				
9	Name & Designation of Officers	Sh. Ram Singh (Secretary)				
10	from the building side Year of construction					
11			6, 2 nd Floor-2014 & 3 rd 1	Floor-2017-1		
S. No.	Applicant letter No.		9184 dated 26-06-2018			
S. 140.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
1	and Fire Safety U/R 33 Access to Building.	requirements		MR/NMF		
	Road width	6 mtr	D '1 1	1.00		
	Gate width	-NA-	Provided	MR		
	Width of internal road	-NA-	-NA-	-NA-		
2			-NA-	-NA-		
	Number, width, type & arrangement of each Number of Staircase	XIUS.				
	> Upper floors.	02 Nos	Provided	MD		
	Basement floor.	-NA-		MR		
	b) Width of Staircase	-INA-	-NA-	-NA-		
	> Upper floors	1.5 mtr	1.67m & 1.85m	MR		
	Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits	1171	-14/4-	-IN/A-		
	Fire check door	-NA-	-NA-	-NA-		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	One	Provided	MR		
	e) Width of corridor	-NA-	-NA-	-NA-		
	f) Door size	1m	Provided	MR		
3	Compartmentation.			1111		
	Fire check door.	-NA-	-NA-	-NA-		
	• Sealing of electrical shafts.	-NA-	-NA-	-NA-		
14	• Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
	 Fire dampers. 	-NA-	-NA-	-NA-		
4.	Smoke Management system.					
	Basement	30 ACPH	-NA-	-NA-		
	 Upper floors 	12 ACPH	-NA-	-NA-		
5.	Fire Extinguishers.					
	Total numbers	Required	10 Nos	MR		
	• Types	ABC / CO2	ABC & CO2	MR		
	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.	151 marked	TTOVICE	IVIK		
U.	Total numbers on each floor.	One	Provided	MD		
47			THE POST OF THE PO	MR		
	• Length of hose-reel hose.	30m	Provided	MR		
	 Nozzle Diameter 	5mm	Provided	MR		

The Siddhartha Public School at 586-D/7, Buddha Vihar, Govindpuri, New Delhi-110019

	the first detection 0 alarming avertant	•		
7 A	automatic fire detection & alarming system.	-NA-	-NA-	-NA-
	Type of detectors Leasting of Main Panel	-NA-	-NA-	-NA-
	Location of Main Panel Location of Panester Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
0 7	Hooter's location	-NA-	-NA-	-NA-
	MOEFA	-NA-	-NA-	-NA-
	Public Address System	-INA-	-IVA-	-14/1-
10. A	Automatic Sprinkler System	-NA-	-NA-	-NA-
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
44 7	Sprinkler above false ceiling	-INA-	-INA-	-11//
11. I	nternal Hydrants.	-NA-	-NA-	-NA-
	Size of Riser/Down-comer		-NA-	-NA-
	Number of Hydrant per floor	-NA-		
	Hose box.	-NA-	-NA-	-NA-
12. Y	Yard Hydrants.	D.T.A.	NIA	N.T.A.
	• Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13. P	oumping arrangements.			
	Ground Level			7.7.4
	Discharge of main pump.	-NA-	-NA-	-NA-
	> Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Auto starting/manual stopping.Pump house access.	-NA-	-NA-	-NA-
	1	-NA-	-NA-	-NA-
	Terrace Level	150 Y 77 Y		1 10
	Discharge of pump.	450 LPM	Provided	MR
	Head of pump.	40 mtr	Provided	MR
	Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.	274	NIA.	NIA
	• Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	
15	Overhead tank capacity. This is a second of the capacity	10,000 Ltr	Provided Provided	MR MR
	Exit Signage.	Required	Provided	IVIN
16. I	Provision of Lifts.	-NA-	-NA-	-NA-
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	• Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.			
	Lift signage.	-NA-	-NA-	-NA-
	Standby Power Supply	-NA-	-NA-	-NA-
18. I	Refuge Area	371	N/A	
	• Total area	-NA-	-NA-	-NA-
	 Location 	-NA-	-NA-	-NA-

The Siddhartha Public School at 586-D/7, Buddha Vihar, Govindpuri, New Delhi-110019

19.	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the	-NA-	-NA-	-NA-
	Protection of special Risk, if any.	7		

The shortcoming communicated by this department vide letter dated 28/05/2018 (at C-18) deemed complied as school management has submitted an undertaking that 3rd floor is not used for school purpose.

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/601 dated 13/05/2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

The Siddhartha Public School at 586-D/7, Buddha Vihar, Govindpuri, New Delhi-110019

DO (SB)

DO

1699 (FOCS2) 6/8/18 41.1. Letter loss vg 7.

1820 Miscell Wags