

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/Hospital/2018/WZ/ 1866

DATED: 8/8/18

FIRE SAFETY CERTIFICATE

Certified that the **Shree Aggarsain International Hospital (Shree Aggarsain North-Ex-welfare Society)**, PSP, Sector-22, Rohini, Delhi-110085 comprised of three tire basement, Ground plus nine upper floors owned/occupied by **Shree Aggarsain North-Ex-welfare Society** have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 01.08.2018 in the presence of Sh. Surender Gupta (Chairman), Sh. Devender Singh (Fire Manager) of the hospital and that the building is fit for occupancy class- Institutional“(Hospital building)” with effect from..8/8/18..... for a period of **three years**, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010.subject to condition as mentioned below.

Issued on .....8/8/18..... at New Delhi by

  
Atul Garg  
Chief Fire Officer

**Copy to,**

1. The Authorized Signatory, Shree Aggarsain International Hospital (Shree Aggarsain North-Ex-welfare Society) , PSP, Sector-22, Rohini, Delhi-110085

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The basement shall be used strictly as per the provisions of Building Bye laws.
- e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
- f. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
- g. This fire safety certificate is issued for two basements & ground plus two upper floors subject to condition that 3<sup>rd</sup> floor to 5<sup>th</sup> floors which are laying vacant shall be made operational after taking clearance from Delhi Fire Service.

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI – 110001**

No. F 6 / DFS / MS/Hospital/2018/ 3492

Dated 10/8/18

**CORRIGENDUM**

In partial modification to the official letter issued by this vide department letter no. F.6/ DFS/ MS/Hospital/2018/WZ/1866 dated 08.08.2018, the para contents mentioned/listed in Conditions G of the fire safety certificate i.e. "This fire safety certificate is issued for two basements & ground plus two upper floors subject to condition that 3<sup>rd</sup> to 5<sup>th</sup> floors which are laying vacant shall be made operational after taking clearance from Delhi Fire Service" may be treated as **cancelled**.

Other contents of letter shall remain unchanged.

Yours faithfully

  
(Atul Garg)

Chief Fire Officer  
Ph.-011-23414250

Copy to,

1. The Authorized Signatory, Shree Aggarsain International Hospital, Shree Aggarsain North-Ex-Welfare Society), PSP, Sector-22, Rohini, Delhi.



1	Name & address of the building	Shree Aggarsain International Hospital (Shree Aggarsain North-Ex-welfare Society (Hospital)) , PSP, Sector-22, Rohini, Delhi-110085		
2	Building Comprised of	(3B+G+9 Upper floors )		
3	Type of Occupancy	Institutional (Hospital)		
4	Type of case	New		
5	Details of previous NOC	No		
6	Fire safety directives letter No	F6/MS/DFS/BP/2010/2586 dated 06.09.2010		
7	Date of inspection	01.08.2018		
8	Name of the inspecting Officers	DCFO Dharampal Bhardwaj & ADO Rajesh Kumar		
9	Name and designation of officers from the building side	Sh. Surieder Gupta (Chairman), Sh. Devender Singh (Fire Manager)		
10	Year of construction	2018		
11	Applicant's letter No.	Nil DATED 23.07.2018		
<b>S. NO.</b>	<b>Minimum Standards on fire prevention and fire safety U/R 33</b>	<b>Directives issued No. 2586 dated 06.09.2010/ NBC Requirement</b>	<b>Provided at site</b>	<b>Remarks MR / NMR</b>
<b>1</b>	<b>Access to building</b>			
	1) Road width	9 Mtr	Provided	MR
	2) Gate width	6 Mtr	Provided	MR
	3) Width of internal road	6 Mtr	Provided	MR
<b>2</b>	<b>Number, width Type &amp; arrangement of exits</b>			
	<b>a. Number of staircases</b>			
	1. Upper floors	6 Nos.+ 1 Ramp	Provided	MR
	2. basements	6 Nos.+ 2 Ramps	Provided	MR
	<b>b. Width of staircase</b>			
	1. Upper floors	2 Mtr	Provided	MR
	2. basements	2 Mtr	Provided	MR
	<b>c. Protection of exits</b>			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	Required	Provided	MR
	<b>d. No. of continuous staircase to terrace</b>	6 Nos.	Provided	MR
	<b>e. Width of corridor</b>	2.4	Provided	MR
	<b>f. Door size</b>	2, 1.35 & 1.20 Mtrs	Provided	MR
<b>3</b>	<b>Compartmentation.</b>			
	1. Fire check door	Required	Provided	MR
	2. Sealing of electrical shafts	Required	Provided	MR
	3. Fire Rating of shaft door	Required	Provided	MR
	4. water curtain	Required	Provided	MR
	5. Fire dampers	Required	Provided	MR
<b>4</b>	<b>Smoke Management system.</b>			
	basement	30 a/c per hour	Provided	MR
	upper floors	12 a/c per hour	Provided	MR
<b>5</b>	<b>Fire Extinguishers</b>			
	total numbers		473 Nos. Provided	MR
	Types	ISI	ABC, CO2 , Water Co2	MR



6	<b>First-Aid Hose Reels.</b>			
	total numbers on each floor	6 Nos	Provided	MR
	Length of Hose reel hose	30 Mtr	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7	<b>Automatic fire detection and alarming system</b>			
	Type of detectors	Required	<b>Provided</b>	<b>MR</b>
	location of Main Panel	Ground floor	Provided	MR
	location of Repeater panel	Required	Provided	MR
	Alternate source of power	Required	Battery Backup Provided	MR
	hooter's location	Required	Staircase Provided	MR
8	<b>MOEFA</b>	Required	Provided	MR
9	<b>Public Address System.</b>	Required	Provided	MR
10	<b>Automatic Sprinkler System.</b>			
	basement	Required	<b>Provided</b>	<b>MR</b>
	upper floors	Required	Provided	MR
	sprinkler above false ceiling	Required	Provided	MR
11	<b>Internal Hydrants</b>			
	Size of riser/down-corner	150 MM	Provided	MR
	Number of Hydrants per floor	6 Nos.	Provided	MR
	hose Box	6 Nos	Provided	MR
12	<b>Yard Hydrants.</b>			
	total number of hydrants	16 Nos	Provided	MR
	house box	16 Nos.	Provided	MR
13	<b>Pumping arrangements</b>			
	<b>1. Ground level</b>			
	a. Discharge of main Pump	2850 LPM	2850 LPM Provided	MR
	b.Head of main pump	105 Mtr	Provided	MR
	c.Number of main pumps	Two	Two Nos. Provided	MR
	d.jockey pump out put	180 LPM (2 Nos.)	180 LPM 2 Nos. Provided	MR
	e.jockey pump head	105 Mtr	Provided	MR
	f. Standby Pump output	2850 LPM	2850 LPM Provided	MR
	g.Stanby Pump head	105 Mtr	Provided	MR
	h.Auto Starting/Manual stopping	Required	Provided	MR
	pump house access	Provided	Provided	MR
	<b>Water Curtain Pump</b>	<b>N/A</b>	<b>1620 LPM Provided</b>	<b>MR</b>
	<b>2.Terrace level</b>			
	a. Discharge of pump	N/A	900 LPM Provided	MR
	b. head of the pump	N/A	40 Provided	MR
	c. Power supply	N/A	Provided	MR
	d. Auto starting of pump	N/A	Provided	MR
14	<b>Captive water storage for fire fighting</b>			
	1. Underground tank capacity	2.00,000 Ltr	2.00,000 Ltr Provided	MR
	a. Draw-off connection	Required	Provided	MR
				MR



N/A

INSPECTION REPORTS

15	<b>Exit Signage.</b>	Required	Provided	MR
16	<b>Provision of lifts.</b>			
	a. Pressurization of lift shaft	Required	Provided	MR
	b. pressurization of lift lobby	Required	Provided	MR
	c. communication in lift car	Required	Provided	MR
	d. Fireman's grounding switch	Required	Provided	MR
	e. Lift signage	Required	Provided	MR
17	<b>Standby power supply</b>	Required	Provided	MR
18	<b>Refuge Area.</b>			
	total area	180 Sq Mtr	Provided	MR
	location	7th floor	Provided	MR
19	<b>Fire control room</b>			
	a. Detector system Panel	Required	Provided	MR
	b. Flow switch Panel	Required	Provided	MR
	c. PA system Panel	Required	Provided	MR
	d. Batter backup	Required	Provided	MR
	e. Building floor plans	Required	Provided	MR
20	<b>Special Fire Protection systems for protection of special risks, if any:</b>	Required	CO2 Automatic suppression system Provided	MR


This department issued shortcoming vide letter no. F6/DFS/MS/HOSPITAL/2018/WZ/3139 dated 24.07.2018 have been compailed. The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule it is recommended to grant of Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/.


Accordingly DFA is put up for your approval and signature please.



Signature of the inspecting officer  
 Name Dharampal Bhardwaj  
 Designation : DCFO (WZ)



Signature of the inspecting Officer  
 Name Rajesh Kumar  
 Designation ADO (RN)

CFO. WZ /   
 6/8/18

1- FTPLS  
 2- file number shud be done.

As approved, f.t. letter is put up for your signature @ 10/11