GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2018/ | 923

Dated: 21/8/18

FIRE SAFETY CERTIFICATE

Certified that the M/s. Pawandeep Hotels & Infrastructure Pvt. Ltd. located at B-20, Bada Bazar Road, Old Rajinder Nagar, New Delhi- 110060, is running on the ground floor of a building comprised of ground plus two upper floors owned/occupied by M/s. Pawandeep Hotels & Infrastructure Pvt. Ltd. The premises was inspected by the officer concerned of this department on 16.08.2018 in presence of Sh. Pawan Kumar Aggarwal, owner of the restaurant and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (restaurant) with effect from 2118 Jts. for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 21/8 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

 The Manager, M/s. Pawandeep Hotels & Infrastructure Pvt. Ltd., B-20, Bada Bazar Road, Ground Floor, Old Rajinder Nagar, New Delhi- 110060.

2. The Deputy Health Officer, North Delhi Municipal Corporation, Public Health Department, Anand Parbat, Karol Bagh Zone, New Delhi- 110005.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s. Pawandeep Hotels & Infrastructure Pvt. Ltd., B-20, Bada Bazar Road, Ground Floor, Old Rajinder Nagar, New Delhi- 110060

2. Type of Occupancy

: Assembly (Restaurant)

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : N/A.

6. Date of inspection

: 16.08.2018

7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West)

8. Name and designation of officers

from the building side

: Sh. Pawan Kumar Aggarwal

9. Year of Construction

: 1962

10. Applicant's letter No.

: nil dated nil

The said restaurant is running at Ground Ele

S. No.	said restaurant is running at Ground F Minimum Standards on fire prevention and fire safety U/R 33	Requiremen	tas	Domonika				
1	Access to building							
	• Road width	06 mts	Provided	MR				
	• Gate width	4.5 mts	Provided	MR				
	• Width of internal road	N/A	N/A	N/A				
?	Number, Width, Type & Arrange	ment of Exits						
	a. Number of staircases	-	_ ^					
	Upper Floors	N/A	Restaurant at G	F N/A				
	Basements	N/A	N/A	N/A				
	b. Width of staircases	_	-	- 1VA				
	• Upper Floors	N/A	Restaurant at G	F N/A				
	Basements	N/A	N/A	N/A				
	c. Protection of exits	_	-	-				
	Fire check doorPressurization	N/A	N/A	N/A				
	e. No. of continuous staircases to terrace	N/A	N/A	N/A				
- 1	g. Width of Corridor	N/A	N/A	N/A				
	h. Door Size	N/A	N/A	N/A				
-		2.0 mts	Provided	MR				
-	Compartmentation.							
	• Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	• Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				
	• Fire Dampers	N/A	N/A	N/A				
	Smoke Management System.	11/11						
	• Basements	30 a/c per ho	ır N/A	N/A				
	• Upper floors	12 a/c per hor		ion MR				
I	Fire Extinguishers			1411				

		08	Provided	MR
	Total numbers	CO ₂ , ABC type	Provided	MR
	• Types	ISI marked	Provided	MR
	IS marking The Add Hara Books	<u></u>		
6	First-Aid Hose Reels.	01	Provided	MR
	Total numbers on each floor	30 m	Provided	MR
-	• Length of hose reel hose	5 mm	Provided	MR
	Nozzle diameter	4072		
7	Automatic fire detection and alarming	N/A	N/A	N/A
	Type of detectors		NI/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	IVA
	Alternate source of power	N/A	N/A	N/A
		N/A	N/A	N/A
	Hooters' Location		Provided	MR
8	MOEFA	Required	N/A	N/A
9	Public Address System.	N/A	14/11	
10	Automatic Sprinkler System.	N/A	N/A	N/A
	Basement			N/A
	• Entire Restaurant	N/A	Provided	N/A
	Sprinkler above false ceiling	N/A	N/A	1472
11	Internal Hydrants			NAD
	Size of riser/down-comer	Required	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	MR
		01		
12		27/4	N/A	N/A
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	IN/A	
13				
	Ground Level	N/A	N/A	N/A
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump		N/A	N/A
	Number of main pumps	N/A N/A	N/A	N/A
	Jockey Pump out put	N/A N/A	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	# P II 1	N/A	N/A	N/A
		77/4	N/A	N/A
= 0	> Auto Starting/ Manual stopping > Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPN	M Provided	MR

0	
2	8 0
1,	14
	\ }

		nly				
	> Power Supply	Required	Provided	MR		
7	Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting	ıg.				
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
200 A	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	20,000 lts	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
41	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules- 2010.

DFA is put up for approval & signature please

8/18

DCFO (SZ)

M.K. CHATTOPADHYAY Divisional Officer (South West)