GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2018/SZ/ 2060

Dated: 1.9.1.9./18

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Shervani Fort View located at 11, Sunder Nagar, New Delhi, comprised of Ground + 2 upper floors (Ground floor- reception + 05 guest rooms + dinning & drawing room, 1st Floor- 07 guest rooms, 2nd Floor- 07 guest rooms), total 19 guest rooms was issued FSC by this department vide letter No. F6/DFS/MS/GH/2015/NDZ/1082 dated 26/06/2015. The premises was re-inspected by officer concerned of this department on 24/08/2018 in the presence of Mr. Harish Sharma (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Residential, Group-A for 19 guest rooms at ground to 2nd floor", as above with effect from the date of issue of this certificate for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued 15 918 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph: 011-23412225

Copy to: -

- 1. The Addl. Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi-110049
- 2. Proprietor, M/s Hotel Shervani Fort View located at 11, Sunder Nagar, New Delhi-110003

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

| | INSPECT | TION REPORT | | | |
|-------|---|---|-------------------------|--------------|--|
| 1 | Name & Address of the Building | M/s Hotel Sherv | ani Fort View. | | |
| | | 11, Sunder Nagar, New Delhi-110003 | | | |
| 2 | Type of Occupancy | Residential, "Group—A" (Guest House) | | | |
| 3 | Building Comprised of | Ground + 2 upper | | | |
| 4 | Type of Case | Renewal | 110013. | | |
| 5 | Details of Previous NOC | | 2015/NDZ/1082 dated 2 | 6-06-2015 | |
| 6 | Fire Safety Directives Letter No | Nil | 2013/11BE/11002 dated 2 | .0-00-2013 | |
| 7 | Date of Inspection | 24-08-2018 | | | |
| 8 | Name of the Inspecting Officers | Mehmood, ADO (SJ) | | | |
| 9 | Name & Designation of Officers | Mr. Harish Sharma (Manager) | | | |
| | from the building side | ivii. Harisii Silariila (ivialiagei) | | | |
| 10 | Year of construction | Gd. Floor (Reception + 05 guest rooms), 1 st floor | | | |
| | | (07 guest rooms) and 2 nd floor (07 guest rooms), | | | |
| | | Total- 19 Guest Rooms | | | |
| 11 | Applicant letter No. | Outdoor Diary No. 8532 dated 08.06.2018 | | | |
| S. No | Minimum standards on Fire Prevention | Old NOC | Provided at Site | Remarks | |
| | and Fire Safety U/R 33 | requirements | | MR/NMI | |
| 1 | Access to Building. | | | | |
| | Road width | Required | 15 mtr | MR | |
| | Gate width | -NA- | -NA- | -NA- | |
| | Width of internal road | -NA- | -NA- | -NA- | |
| 2 | Number, width, type & arrangement of exits. | | | 1112 | |
| | a) Number of Staircase | | 2 | | |
| | Upper floors. | One | Provided | MR | |
| | Basement floor. | -NA- | -NA- | | |
| | b) Width of Staircase | -INA- | -NA- | -NA- | |
| | > Upper floors | 0.90 | 1 17 4- 1 25 | MD | |
| | Basement floor | 0.80 mtr | 1.17m to 1.25m | MR (old case | |
| | c) Protection of exits | -NA- | -NA- | -NA- | |
| | Fire check door | NIA |) T A | 27.4 | |
| | > Pressurization | -NA- | -NA- | -NA- | |
| | d) No. of continuous staircase to terrace | -NA- | -NA- | -NA- | |
| | e) Width of corridor | One | Provided | MR | |
| | f) Door size | -NA- | 1.05m | MR | |
| 3 | Compartmentation. | 1m | 1m (final exit) | MR (old case | |
| 3 | | 27.4 | | | |
| | • Fire check door. | -NA- | -NA- | -NA- | |
| | • Sealing of electrical shafts. | -NA- | -NA- | -NA- | |
| | • Fire rating of shaft door. | -NA- | -NA- | -NA- | |
| | Water curtain | -NA- | -NA- | : -NA- | |
| | • Fire dampers. | -NA- | -NA- | -NA- | |
| 4. | Smoke Management system. | | | s | |
| | • Basement | 30 ACPH | -NA- | -NA- | |
| | Upper floors | 12 ACPH | Natural ventilation | MR | |
| 5. | Fire Extinguishers. | | | | |
| | Total numbers | Required | 09 Nos | MR | |
| | • Types | ABC / CO2 | ABC & CO2 | MR | |
| | ISI Marking | ISI marked | Provided | MR | |
| 6. | First Aid Hose Reels. | 151 marked | 11011000 | IVIK | |
| | Total numbers on each floor. | One | Provided | MD | |
| | | | | MR | |
| | Zengui of nose reel nose. | 30m | Provided | MR | |
| | Nozzle Diameter | 5mm | Provided | MR | |

M/s Hotel Shervani Fort View at 11, Sunder Nagar, New Delhi

| 7 | Automatic fire detection & alarming system. | | | |
|------|---|-------------------|-----------------|---------|
| | Type of detectors | -NA- | Smoke type | -NA- |
| | Location of Main Panel | -NA- | Ground floor | -NA- |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| | Alternate source of power | -NA- | Provided | -NA- |
| | Hooter's location | -NA- | Each floor | -NA- |
| 8. | MOEFA | -NA- | -NA- | -NA- |
| 9. | Public Address System | -NA- | -NA- | -NA- |
| 10. | Automatic Sprinkler System | 1111 | 7.77 | |
| 10. | Basement | -NA- | -NA- | -NA- |
| | Upper floors | -NA- | Provided | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 11. | Internal Hydrants. | -11//- | -1471- | -1471 |
| 11. | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | Number of Hydrant per floor | | | |
| - 10 | Hose box. | -NA- | -NA- | -NA- |
| 12. | Yard Hydrants. | D.T.A. | D:1-10131 | NT A |
| | • Total number of hydrants. | -NA- | Provided 01 No | -NA- |
| | Hose box. | -NA- | Provided 01 No | -NA- |
| 13. | Pumping arrangements. | | | |
| | Ground Level | X | | |
| | Discharge of main pump. | -NA- | -NA- | -NA- |
| | Head of main pump. | -NA- | -NA- | -NA- |
| | Number of main pumps. | -NA- | -NA- | -NA- |
| | Jockey Pump output. | -NA- | -NA- | -NA- |
| | Jockey Pump head. | -NA- | -NA- | -NA- |
| | Standby Pump output. | -NA- | -NA- | -NA- |
| | Standby Pump head. | -NA- | -NA- | -NA- |
| | Auto Starting / Manual Stopping. | -NA- | -NA- | -NA- |
| | Pump house access. | -NA- | -NA- | -NA- |
| | Terrace Level | | 9 | |
| | Discharge of pump. | Boosting pump | 450 LPM | MR |
| | Head of pump. | Required | 35 mtr | MR |
| | Power supply. | Required | Provided | MR |
| | Auto starting of pump. | Required | Provided | MR |
| 14. | Captive water storage for fire fighting. | | | |
| | Underground tank capacity. | -NA- | -NA- | -NA- |
| | Draw-off connection. | -NA- | -NA- | -NA- |
| | Fire Service Inlet. | -NA- | -NA- | -NA- |
| | Access to tank. | -NA- | -NA- | -NA- |
| | Overhead tank capacity. | 2,500 Ltr | Provided | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | | | |
| | Pressurization of lift shaft. | -NA- | -NA- | -NA- |
| | Pressurization of lift lobby. | -NA- | -NA- | -NA- |
| | Communication in lift car. | -NA- | -NA- | -NA- |
| | • Fireman's switch. | Required | Provided | MR |
| | Lift signage. | Required | Provided | MR |
| 17. | Standby Power Supply | Required | Provided DG Set | MR |
| 18. | Refuge Area | | | |
| | Total area | -NA- | -NA- | -NA- |
| | • Location | -NA- | -NA- | -NA- |
| | | at 11 Sunder Naga | | -1 ALT. |

M/s Hotel Shervani Fort View at 11, Sunder Nagar, New Delhi

| 19. | Fire Control Room. | | 1 | |
|-----|---|------|------|------|
| | Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| 20. | Special Fire Protection System for the | -NA- | -NA- | -NA- |
| | Protection of special Risk, if any. | | | 1 10 |

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2015/NDZ/1082 dated 26-06-2015, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting

Name: Mehmood Design: ADO (SJ)

M/s Hotel Shervani Fort View at 11, Sunder Nagar, New Delhi

Cho Sep miscell 17th, up for Lignorture blease hamsed from corrections

miscell Vic