GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

No.F.6/DFS/MS/School/2018/SZ/ 2/20

Dated: 1919118

FIRE SAFETY CERTIFICATE

Certified that the **Raghubir Singh Modern School**, L-2, Mohan Garden, New Delhi-110059 comprised of ground floor plus three upper floors, owned/occupied by Raghubir Singh Modern School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2015/SZ/225 dated 17.02.2015. The School building was re-inspected by the officer concerned of this department on 07.08.2018 in the presence of Sh. Rajiv Tyagi (Manager) and found that Raghubir Singh Modern School have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, Raghubir Singh Modern School, L-2, Mohan Garden, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Raghubir Singh Modern School, L-2, Mohan Garden, New Delhi-59

2. Type of Occupancy : Educational3. Type of Case : Renewal

4. Details of Previous NOC : F.6/DFS/MS/School/2015/SZ/225 dated 17.02.2015

5. Fire Safety directives letter No : N/A6. Date of inspection : 07.08.2018

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. Rajiv Tyagi (Manager)

9. Year of Construction : 1997 to 2015

10. Applicant's letter No. : RSMS/CFO/DFS/6/18/1061 dated 19.06.2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 17.02.2015	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road widthGate widthWidth of internal road	Accessible 06 mtrs 4.5 mtrs N/A	Provided 03 mtrs N/A	MR MR, being old case N/A		
2.	Number, Width, Type & Arrangement of Exit	S				
	a. Number of staircases	T		-		
	• Upper Floors	03 No's	03 No's	MR		
	Basements	N/A	N/A	N/A		
	b. Width of staircases					
	• Upper Floor	150 cms/additional staircase of 75 cms	157, 150-142 & 128-124 cms	MR, being old case		
	• Basements	if less than 150 cms N/A	N/A	N/A		
		1 1/ 71	11/71	IN/A		
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door	N/A	N/A	N/A		
	Pressurizationd. No. of continuous staircases to	IN/A	IN/A	N/A		
	terrace	Required	Two	MR		
	e. Width of Corridor	150 cms	185 cms	MR		
	f. Door Size	100 cms	100 cms	MR		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
1.	Smoke Management System					
	Basements	N/A	N/A	N/A		
	• Upper floors	Required	Natural ventilation	MR		
5.	Fire Extinguishers					
	Total numbers on each floor	04 no.'s	Provided	MR		
	Types	ABC/CO ₂ type	Provided	MR		
	IS marking	ISI marked	ISI marked	MR		
6.	First-Aid Hose Reels					
	Total numbers on each floor	02 no.'s	Provided	MR		
	Length of hose reel hose	30 mtrs	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		

7.	Automatic fire detection and alarming system			30
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants) NT/A	27/4	27/4
	Size of riser/down-comer	N/A N/A	N/A N/A	N/A
	Number of hydrants per floor Have Person			N/A
2	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants	77/4	27/4	27/4
	Total number of hydrants	N/A	N/A	N/A
2	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put			
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
	7 Auto Starting/Manual Stopping	N/A	N/A	N/A
	2 - 2	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level		7	
	Discharge of pump	450 LPM	Provided	MR
	➤ Head of the pump	30 mtrs	Provided	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
		rtoquirea	1101146	
4.	Captive Water Storage for fire fighting		•	
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/Á
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 ltrs	Provided	MR
5.	Exit Signage.	Required	Provided	MR
	Exit Signage.	Required	Flovided	IVIX
6.	Provision of Lifts.			No I :C
U.	Prevision of Lifts. Pressurization of Lift Shaft	N/A	N/A	No Lift N/A
	Pressurization of Lift Shart Pressurization of Lift lobby	200 18300 00 1000		
	Communication In lift Car	N/A N/A	N/A N/A	N/A N/A
	Fireman's Grounding Switch			
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
7.	Standby power supply	N/A	N/A	N/A
8.	Refuge Area.			
	> Total Area > Location	N/A	N/A	N/A
	B I contion		*	

		and the same of th		
19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	 PA System Panel 	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/School/2018/SZ/2549 dated 15.06.18 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F F.6/DFS/MS/School/2015/SZ/225 dated 17.02.2015 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

D.O. (South West) 805/120CSW)

DG5 (52)

Go \$7 m. scell F710.

G.T. letter in fact up for signature please.

GOCST m. scell W.