GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ/ 2/50

Dated: 1919/18

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Boys Sr. Sec. School,** Paprawat, New Delhi-110043 comprised of two blocks namely Block-A & Block-B. Each block is having ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2015/SZ/1707 dated 17.09.2015. The school building was re- inspected by the officer concerned of this department on 28.08.2018 in the presence of Sh. Bhim Singh Meena (Vice Principal) and found that the Govt. Boys Sr. Sec. School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Boys Sr. Sec. School, Paprawat, New Delhi-110043
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

one upper floor. INSPECTION REPORT 1. Name & address of the building: Govt. Boys Sr. Sec. School, Paprawat, New Delhi-110043 Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2015/SZ/1707 dated 17.09.2015 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 28.08.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Bhim Singh Meena (Vice Principal) 9. Year of Construction 2014 10. Applicant's letter No. GBSSS/Pap/2018/344 dated 09.08.2018 Minimum Standards on fire prevention and Requirement Provided at Remarks fire safety U/R 33 as per FSC dt. site MR/NMR 17.09.2015 1. Access to building Road width Accessible 06 mtrs Provided MR 4.5 mtrs Gate width Provided M/R N/A Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 03 no.'s in each Provided MR Basements block b. Width of staircases N/A N/A N/A Upper Floor Basements 140, 140 & 145 150 cms MR, being old cms in blk-A & 150 case (03no.'s) in Blk-B c. Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A N/A e. Width of Corridor 150 cms 175 cms in each MR f. Door Size block 100 cms 107 cms MR (Double door) 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System Basements N/A N/A N/A Upper floors Natural Ventilation Required MR provided 5. Fire Extinguishers Total numbers 14 No's Provided MR Types ABC/CO₂ type Provided MR IS marking ISI marked ISI marked MR 6. First-Aid Hose Reels Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A

| 7. | Automatic fire detection and alarming system | The second second | | |
|-------------------------|---|-------------------|------------|------------|
| | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| 8. | Location of Repeater Panel | N/A | | |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| | MOEFA | | N/A | N/A |
| 0. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | | | 4 |
| | • Basement | N/A | N/A | N/A |
| | Ground Floor | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants | | 11/12 | 14/11 |
| | Size of riser/down-comer | N/A | N/A | N/A |
| | Number of hydrants per floor | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 12. | Yard Hydrants | | | |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 13. | Pumping Arrangements | | | * |
| | Ground Level | | | |
| | Discharge of main Pump | N/A | N/A | N/A |
| | Head of Main pump | N/A | N/A | N/A |
| | Number of main pumps | N/A | | |
| | Jockey Pump out put | 195 032 47740, 1 | N/A | N/A |
| | Jockey pump head | N/A | N/A | N/A |
| | Standby Pump out put Standby Pump Head | N/A | N/A | N/A |
| | Standby Pump HeadAuto Starting/Manual Stopping | N/A | N/A | N/A |
| | 7 Tuto Starting Wandar Stopping | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Pump House Access | N/A | N/A | N/A |
| | Pump House AccessTerrace level | | | |
| | > Discharge of pump | N/A | N/A | NI/A |
| | Head of the pump | N/A | N/A N/A | N/A |
| | Power Supply | N/A | N/A N/A | N/A N/A |
| | Auto Starting of pump | N/A | N/A | |
| | | IN/A | N/A | N/A |
| 10. 11. 12. 13. 16. | Captive Water Storage for fire fighting | | 1 | i. |
| | Underground tank capacity | N/A | N/A | N/A |
| * | Draw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | |
| | Access to tank | | | N/A |
| | Overhead Tank capacity | N/A | N/A | N/A |
| 15 | Fyit Signage | N/A | N/A | N/A |
| 13. | Exit Signage. | N/A | N/A | N/A |
| 16. | Provision of Lifts. | | . (| (No Lift) |
| | Pressurization of Lift Shaft | N/A | N/A | N/A |
| J | Pressurization of Lift lobby | N/A | N/A | N/A |
| 10 | Communication In lift Car | N/A | N/A | N/A |
| , | Fireman's Grounding Switch | N/A | | |
| | Lift Signage | | N/A | N/A |
| 17. | Ctondby normal | N/A | N/A | N/A |
| 1/. | Standby power supply | N/A | N/A | N/A |
| 18. | Refuge Area. | | | |
| | > Total Area | N/A | N/A | N/A |
| | A Location | 11/11 | IVA | IV/F1 |

| Fire Control Room | Control Room | | | |
|--|--|--|--|--|
| Detector System Panel | N/A | N/A | N/A | |
| Flow Switch Panel PA System Panel Battery backup Building Floor Plane | N/A | N/A | N/A | |
| | N/A | N/A | N/A | |
| | N/A | N/A | N/A | |
| Dunding Floor Flans | N/A | N/A | N/A | |
| Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A | |
| | Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of | Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A | • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A N/A N/A N/A N/A | |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2015/SZ/1707 dated 17.09.2015 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

F.T. leter is put up for signature please.