GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/LPG/2018/SZ/ 2\66

Dated: 20/9/18

FIRE SAFETY CERTIFICATE

Certified that M/s **R.K.** Agencies (Storage of L.P. Gas Cylinders of Indane) located at F-10, Hauz Rani, Saket, New Delhi-110017, comprised of Single Storey (Tin Shade) building was issued FSC by this department vide letter No. F6/DFS/MS/2013/SZ/959 dated 24/09/2013. The premises was re-inspected by officer concerned of this department on 12/09/2018 in the presence of Ms. Karishma Narula (Proprietor) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Group J Hazardous Building" as above with effect from 20/01 2018 for period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued 20 10 118 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph; 011-23412225

Copy to: -

- 1. Proprietor, M/s R.K. Agencies, F-10, Hauz Rani, Saket, New Delhi-110017
- 2. Administrative Officer, South MCD, South Zone, Green Park, New Delhi-110016

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

| | INSPECTIO | N REPORT | TALLIANI DAN | T | | |
|-------|--|---|------------------------|-------------------|--|--|
| 1 | Name & Address of the Building | M/s R.K. AGENCIES, F-10, HAUZ RANI, | | | | |
| | | SAKET, NEW DELHI- 110017 | | | | |
| 2 | Type of Occupancy | Storage Building "Group-J" (LPG Storage) | | | | |
| 3 | Building Comprised of | Single Storey (Tin Shade). | | | | |
| 4 | Type of Case | Renewal F.6/DFS/MS/2013/SZ/959 dated 24-09-2013 | | | | |
| 5 | Details of Previous NOC | | 3/SZ/959 dated 24-09-2 | 013 | | |
| 6 | Fire Safety Directives Letter No | Nil | | | | |
| 7 | Date of Inspection | 12-09-2018 | | | | |
| 8 | Name of the Inspecting Officers | Mehmood, ADO (SJ) | | | | |
| 9 | Name & Designation of | Mr. Karishma Narula (Proprietor) | | | | |
| 9 | Officers from the building side | | | | | |
| 10 | Year of construction | | | | | |
| 11 | Applicant letter No. | Nil dated 07-09-2 | 2018 | D | | |
| . No | Minimum standards on Fire Prevention | Old NOC | Provided at Site | Remarks MR/NMR | | |
| . 110 | and Fire Safety U/R 33 | requirements | 12 | WIR/INIVIN | | |
| 1 | Access to Building. | | | MD | | |
| 1 | Road width | Required | 6 mtr | MR | | |
| | • Gate width | N/A | N/A | N/A | | |
| | Width of internal road | N/A | N/A | N/A | | |
| 2 | Number, width, type & arrangement of exits. | | | | | |
| 2 | a. Number of Staircase | | | 27/1 | | |
| | > Upper floors. | N/A | N/A | N/A | | |
| | Basement. | N/A | N/A | N/A | | |
| | b. Width of Staircase | | | | | |
| | > Upper floors | N/A | N/A | N/A | | |
| | Basement | N/A | N/A | N/A | | |
| | c. Protection of exits | | | | | |
| | | N/A | N/A | N/A | | |
| | Fire check doorPressurization | N/A | N/A | N/A | | |
| | d. No. of continuous staircase to terrace | N/A | N/A | N/A | | |
| | | N/A | N/A | . N/A | | |
| | e. Width of corridor | 1.0 mtr | Provided | MR | | |
| | f. Door size | 1.0 1111 | To figure | a. | | |
| 3 | Compartmentation. | N/A | N/A | N/A | | |
| | • Fire check door. | N/A | N/A | N/A | | |
| | Sealing of electrical shafts. | N/A | N/A | N/A | | |
| | • Fire rating of shaft door. | N/A | N/A | N/A | | |
| | Water curtain | N/A | N/A | N/A | | |
| | Fire dampers. | 1 1/11 | | · · | | |
| 4. | Smoke Management system. | N/A | N/A | N/A | | |
| | Basement | N/A N/A | N/A | N/A | | |
| | Upper floors | IN/A | 14/11 | | | |
| 5. | Fire Extinguishers. | D 1 | 05 No's | MR | | |
| | Total numbers | Required | | MR | | |
| | • Types | ABC / Co2 | ABC type | MR | | |
| | ISI Marking | ISI marked | Provided | IVIIX | | |
| 6. | First Aid Hose Reels. | | 37/1 | NT/A | | |
| | Total numbers on each floor. | N/A | N/A | N/A | | |
| | Length of hose-reel hose. | N/A | N/A | N/A | | |
| | Nozzle Diameter | N/A | N/A | N/A | | |

M/s R.K. Agencies at F-10, Hauz Rani, Saket, New Delhi-110017

| 7 A | automatic fire detection & alarming system. | | | |
|-------|---|-------------------------|------------|----------------|
| 7 23 | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooter's location | N/A | N/A | N/A |
| 8. N | MOEFA | N/A | N/A | N/A |
| | Public Address System | N/A | N/A | N/A |
| | Automatic Sprinkler System | 1 1/1 1 | 11/12 | 1 1/ 1 2 |
| 10. | Basement | N/A | N/A | N/A |
| | Upper floors | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. I | nternal Hydrants. | 11/11 | - 1111 | |
| 11. 1 | Size of Riser/Down-comer | N/A | N/A | N/A |
| | _ | N/A | N/A | N/A |
| | Number of Hydrant per floor Hose boy | N/A | N/A | N/A |
| 12 3 | Hose box. Yourd Hydrones. | 11/17 | 11/11 | 1 1/ 1 1 |
| 12. Y | Yard Hydrants. | N/A | N/A | N/A |
| | Total number of hydrants. Hasa boy. | N/A | N/A N/A | N/A |
| 12 T | Hose box. | IN/A | IN/A | 1 1/17 |
| | Pumping arrangements. | | | |
| • | Ground Level | NI/A | N/A | N/A |
| | Discharge of main pump. | N/A | N/A N/A | N/A |
| | Head of main pump.Number of main pumps. | N/A | N/A N/A | N/A |
| | Number of main pumps.Jockey Pump output. | N/A | N/A N/A | N/A |
| | Jockey Pump head. | N/A | | N/A N/A |
| | Standby Pump output. | N/A | N/A | |
| | Standby Pump head. | N/A | N/A | N/A |
| | Auto Starting / Manual Stopping. | N/A | N/A | N/A |
| | > Pump house access. | N/A | N/A | N/A |
| | 1 | N/A | N/A | N/A |
| • | | NT/A | N/A | NI/A |
| | Discharge of pump. | N/A | 1 1/11 | N/A |
| | Head of pump. | N/A | N/A | N/A |
| | Power supply.Auto starting of pump. | N/A | N/A | N/A |
| 1.4 | | N/A | N/A | N/A |
| 14. | Captive water storage for Fire Fighting. | NI/A | NI/A | N/A |
| | Underground tank capacity. | N/A N/A | N/A N/A | N/A N/A |
| | Draw-off connection. Fig. 6. In 1.1. The second sec | N/A N/A | N/A N/A | . N/A . N/A |
| | • Fire Service Inlet. | N/A N/A | N/A N/A | N/A N/A |
| | • Access to tank. | | N/A N/A | N/A N/A |
| 15 | Overhead tank capacity. | N/A | | |
| | Exit Signage. | N/A | N/A | N/A |
| 16. | Provision of Lifts. | 3.17.4 | 27/4 | 3.T/A |
| | Pressurization of lift shaft. | N/A | N/A | N/A |
| | Pressurization of lift lobby. | N/A | N/A | N/A |
| | Communication in lift car. | N/A | N/A | N/A |
| | • Fireman's switch. | N/A | N/A | N/A |
| | Lift signage. | N/A | N/A | N/A |
| | Standby Power Supply | N/A | N/A | N/A |
| 18. | Refuge Area | Augustinative programme | | |
| | Total area | N/A | N/A | N/A |
| | Location | N/A | N/A | N/A |

M/s R.K. Agencies at F-10, Hauz Rani, Saket, New Delhi-110017

| 19. | Fire Control Room. | | | > T / A |
|-----|--|----------|--|---------|
| | Detector system panel. | N/A | N/A | N/A |
| | • Flow switch panel. | N/A | N/A | N/A |
| | PA system panel. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Battery backup.Building floor plan. | N/A | N/A | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any. | Required | "No Smoking" sign boards in Hindi & English found displayed and Sand Buckets provided. | MR |

The Fire protection systems provided in the building / premises were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/2013/SZ/959 dated 24-09-2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s R.K. Agencies at F-10, Hauz Rani, Saket, New Delhi-110017

DO (8D)

A. B. A. Lelin Progrand

cholder
miscell 477.