## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ / 218/

Dated: 25/08/2018

## FIRE SAFETY CERTIFICATE

Certified that the **New Age Public School,** 12, Gupta Enclave, Vikas Nagar, Main Ranholla Road, New Delhi-110059, comprised of ground floor only having total 22 rooms (Including class rooms, Science Lab, Comp. Room, Office, Library, Reception, Staff Room & Activity room etc.) owned/occupied by Ahoram Tyagi Memorial Educational Society (Regd.) was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2015/SZ/1643 dated 10.09.2015 was re- inspected by the officer concerned of this department on 31.08.2018 in the presence of Sh. Gaurav Tyagi (Chairman) and found that New Age Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 25/69/2018 at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, New Age Public School, 12, Gupta Enclave, Vikas Nagar, Main Ranholla Road, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Ordana Proof Office **INSPECTION REPORT** 1. Name & address of the building: New Age Public School, 12, Gupta Enclave, Vikas Nagar, Main Ranholla Road, New Delhi-110059 Type of Occupancy Educational Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2015/SZ/1643 dated 10.09.2015 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 31.08.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Gaurav Tyagi (Chairman) 9. Year of Construction 2012-2013 10. Applicant's letter No. ATMES/9/18 dated 09.08.2018 S. No. Minimum Standards on fire prevention and Requirement Provided at site Remarks fire safety U/R 33 as per FSC dt. MR/NMR 10.09.2015 1. Access to building Accessible Road width MR, being old case 5.1 mtrs 4.5 mtrs MR, being old case Gate width 3.4 mtrs N/A N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors N/A N/A Ground floor Basements only b. Width of staircases N/A N/A N/A Upper Floor Basements N/A N/A Ground floor c. Protection of exits only Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace e. Width of Corridor N/A N/A N/A N/A N/A N/A Door Size 90 cms 100 cms M/R, being old (Few single door) case 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A N/A Basements Upper floors N/A N/A N/A 5. Fire Extinguishers 07 no's Total numbers Provided M/R ABC/CO<sub>2</sub> type Types Provided M/R IS marking ISI marked M/R ISI marked 6. First-Aid Hose Reels Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A N/A Nozzle diameter NT/A

7.	Automatic fire detection and alarming system			
9 1	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
<i>)</i> .	Tubile Address System	17/71	14/11	17/11
10.	Automatic Sprinkler System			9
	Basement	N/A	N/A	N/A
	<ul> <li>Ground Floor</li> </ul>	N/A	N/A	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
11.	Internal Hydrants		-	
	<ul> <li>Size of riser/down-comer</li> </ul>	N/A	N/A	N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			*
	Ground Level	*		
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>			
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	7 rate starting transact stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level		9 2 2	8
	> Discharge of pump	N/A	N/A	N/A
	> Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A .	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet			
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
4.7	D 11 0710			
16.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	<ul><li>Pressurization of Lift Shaft</li><li>Pressurization of Lift lobby</li></ul>			
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
	- Ditt Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	TVLX	11/11	11/11
A / 0	Samuel Ponter Supply			
18.	Refuge Area.		×	
10.				
10.	> Total Area	N/A	N/A	N/A

1/10

9.		ntrol Room	N/A	N/A	N/A
		El Carital Danal	N/A	N/A	N/A
		PA System Panel	N/A	N/A	N/A
	•	Battery backup	N/A	N/A	N/A
	•	Building Floor Plans	N/A	N/A	N/A
20.	Special	Fire Protection System for Protection of	N/A	N/A	N/A
	special	special Risks, if any:		<b>*</b>	>

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2015/SZ/1643 dated 10.09.2015 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

10/9/18

1036/20/86

DCF0 (52)

1119

11/9

'l

m-scell

4299

F. T. letter is putup for signature please

miscell

409.

DER SER

36/0P.SL