GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ/ 2 | 8 9

Dated: 26 9 118

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C Primary School,** Tilak Nagar No.-3 (Block-24), New Delhi-110018 comprised of ground plus one upper floor, having total 14 rooms (Including Class Rooms & Office etc.) owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2015/SZ/1670 dated 14.09.2015. The school building was re- inspected by the officer concerned of this department on 31.08.2018 in the presence of Smt. Asha Madaan (Principal) and found that the S.D.M.C Primary School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, S.D.M.C Primary School, Tilak Nagar No.-3 (Block-24), New Delhi-110018
- Director of Education,
 S.D.M.C, Civic Centre,
 Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

sa of Ground plus one apper moor. **INSPECTION REPORT** 1. Name & address of the building: S.D.M.C Primary School, Tilak Nagar No.-3 (Block-24), New Delhi-18 2. Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2015/SZ/1670 dated 14.09.2015 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 31.08.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Smt. Asha Madaan (Principal) 9. Year of Construction 2012 10. Applicant's letter No. Nil dated 08.08.2018 S. No. Minimum Standards on fire prevention and Requirement Provided at Remarks fire safety U/R 33 as per FSC dt. site MR/NMR 14.09.2015 1. Access to building Road width 06 mtrs Provided MR 4.5 mtrs MR, being old case Gate width 3.7 mtrs N/A N/A N/A Width of internal road 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 no. 02 no.'s MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms/additional 140 & 120 cms MR Basements staircase of 75 cms if less than 150 cms N/A N/AN/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace e. Width of Corridor N/A N/A N/A 100 cms 110 cms MR Class room Door Size (double door) 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A Basements Natural Ventilation Required Upper floors MR provided 5. Fire Extinguishers Total numbers 06 No's Provided MR ABC/CO₂ type Types Provided MR IS marking ISI marked ISI marked MR First-Aid Hose Reels 6. Total numbers on each floor N/A N/A N/A N/A Length of hose reel hose N/A N/A

	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants		>	
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	USC 1000 NS-11-01		N/A
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	11/12		
	Terrace level	3.T/A	NT/A	N/A
	Discharge of pump	N/A	N/A N/A	N/A N/A
	> Head of the pump	N/A	N/A N/A	N/A N/A
	Power SupplyAuto Starting of pump	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.	on of Lifts.		No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift Shart Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A N/A	N/A N/A	N/A
	Fireman's Grounding Switch			
	 Lift Signage 	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.	ν		
	> Total Area	N/A	N/A	N/A
	> Location			NI/A
		N/A	N/A	N/A

19. Fire Co		ontrol Room					
	•	Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
	•	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A			
20.		Fire Protection System for Protection ial Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2015/SZ/1670 dated 14.09.2015 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

MSCELL FT M.
12/2
F.T. Setter in put up for,