GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F.6/DFS/MS/School/2018/NDZ/ 2201

Dated: 28/9/13

FIRE SAFETY CERTIFICATE

Certified that the M/s Adarsh Vidya Niketan Public School, 25, Shiv Mandir Gali, Maujpur, Delhi- 110053, comprised of Ground plus one upper floor, owned / occupied by Adarsh Vidya Niketan **Public** School was issued **FSC** vide letter No. F.6/DFS/MS/School/2015/NDZ/1575 dt 01/09/15. The school building was re-inspected by the officer concerned of this department in presence of Sh. P.K. Arora, Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. 262-362 dated 17/01/2005 issued by Director of Education and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from ... 19/9/18......for a period three year, subject to conditions printed overleaf.

Issued on.....at New Delhi by

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

To,

The Manager, M/s Adarsh Vidya Niketan Public School, 25, Shiv Mandir Gali, Maujpur, Delhi- 110053.

Copy to:-

The Director of Education,
East Delhi Municipal Corporation,
419, Udyog Sadan, Patparganj Industrial Area, Delhi- 92.

- Conditions -

- 1 All the means of escape shall be kept free of all type of obstruction all the time.
- 2 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

1. Name & address of the building : Adarsh Vidya Niketan Public School,

25, Shiv Mandir Gali, Maujpur, Delhi- 110053.

2. Building is comprised of : G+1 Floor,
3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous FSC letter
 6. Fire Safety direction letter No
 F.6/DFS/MS/School/2015/NDZ/1575 dt 01/09/15
 Circular No. 262-362 dated17/01/05)

6. Fire Safety direction letter No7. Date of Inspection13/09/201813/09/2018

7. Date of Inspection : 13/09/20188. Name of the Inspecting officers : ADO Om Prakash

Name and designation of Officer

from the building side : Sh. P.K. Arora (Manager)
10. Year of Construction : 1991

10. Year of Construction : 1991 11. Applicant's letter No : NIL Dated – 28/08/2018

NO.	Minimum Standards on fire	011					
140.	prevention and fire safety U/R33	Old	Provided at Site	Remark			
1	Access to building	Requirement		MR/NMR			
. The second of building							
	Gate width	06 Mtrs	05 Mtrs	MR / Old Case			
	Width of internal road	N/A	N/A	N/A			
	· ·	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases		40 00				
	Upper Floor	01 no.	02 nos.	MR			
	 Basement 	N/A	N/A	N/A			
	b. Width of Staircases						
	 Upper Floor 	1.5 m	1.25 m & 0.95 m	MR			
	 Basement 	N/A	N/A	N/A			
	c. Protection of exits		2				
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	 d. No. of continuous staircases to terrace 	01 nos.	01 nos.	MR			
	e. Width of Corridor	1.50 m	1.50 m	MR			
	f. Door Size	1.0 m	1.0 m	MR			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
la la	 Fire rating of shaft door 	N/A	N/A	N/A			
	 Water curtain 	N/A	N/A	N/A			
	 Fire Dampers 	N/A	N/A	N/A			
4	Smoke Management System.	,					
	Basement	N/A	N/A	N/A			
	 Upper floor 	N/A	N/A	N/A			
5.	Fire Extinguishers						
	 Total numbers 	04 nos.	06 nos.	MR			
	types	ABC & Co2	ABC & Co2	MR			
	ISI marking	ISI marked	ISI marked	MR			

トノナ

6	First-aid-Hose Reels.						
	Total numbers of each floor	1 no.	1 no.	MR			
	 Length of hose reel hose 	30 m	30 m	MR			
	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.	8					
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
22	 sprinkler above false ceiling 	N/A	N/A	N/A			
11	Internal Hydrants		•				
	 size of riser/down-comer 	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
r.	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	 Auto Starting /Manual stopping 	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace Level		1 177 1	107			
	Discharge of pump	220 LPM	220 LPM	MR			
	➤ Head of the Pump	40 m	40 m	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
4	Captive Water Storage for Fire Fightin			1411			
	Underground tank capacity	N/A	N/A	N/A			
	➤ Draw-off connection	N/A	N/A	N/A			
	➢ Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	2500	2500 Liters	MR			
15	Exit Signage.	N/A	N/A	N/A			

16	Provision of Lifts.			
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
×	 Communication in lift car 	N/A	N/A	N/A
	 Firemen's grounding switch 	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	 Total area 	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A
19	Fire Control Room		p.	
	 Detector system panel 	N/A	N/A	N/A
	 Flow switch panel 	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The Fire protection systems provided in the building were Tested / Checked and found functional, at the time of inspection.

Keeping in view, of the deemed compliance, of the minimum standards on Fire prevention and Fire safety measures as required under the rules, The Fire safety Certificate issued vide letter no. F.6/DFS/MS/School/2015/NDZ/1575 dt 01/09/15 has grant under circular No. 262-362 dated 17/01/05 is recommended to renewal under rule 37 of the Delhi Fire Service Rule 2010.

Omhales 17/9/18

Signature of the Inspecting Officer

Name: Om Prakash

Designation: ADO (Shahdara)

DO (East) 10 18.

Dy. CFO/NDZ

Sir, F.T. Letter is put up for your kind Signature Rease.

Omfadeur 28/9