GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2018/NDZ/ 296

Dated: 0|)|0|18

FIRE SAFETY CERTIFICATE

Certified that M/s Gyan Modern Public School at A-411, Part-2 Main Circular Road, Sonia Vihar, Delhi-110094, comprised of ground plus one upper floor, owned/occupied by Gyan Modern Public School was inspected by the officer concerned of this department in the presence of Mr. Amit Sharma, Principal of the school and found that the school building have complied with the fire prevention and fire safety requirements in accordance with Circular Letter No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/11 issued by Director of Education and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from officer concerned of three years, subject to conditions, printed overleaf.

Issued on at New Delhi by

(Vipin Kental) Chief Fire Officer

To.

The Manager, M/s Gyan Modern Public School A-411, Part-2 Main Circular Road, Sonia Vihar, Delhi-110094,

Copy:-

The Dy. Director of Education, B-Block, Yamuna Vihar Delhi-110053 ole by

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

ADOT!

1. Name & address of the building : Gyan Modern Public School at A-411, Part-2

Main Circular Road, Sonia Vihar, Delhi-110094

2. Building is comprised of : Ground plus one upper floor

3. Type of Occupancy : Educational

4. Type of Case : New

5. Details of Previous FSC letter : Nil

6. Fire Safety directive letter No : Circular 01/03/11 issued by DoE

7. Date of Inspection : 29/08/2018/.

8. Name of the Inspecting officers : ADO Vijay Bahadur

9. Name and designation of officer

from the building side : Mr. Amit Sharma, Principal

10. Year of Construction : 2003

11. Applicant's letter No : Nil, Dated- 30/07/2018

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMR				
01	Access to Building							
	Road width	06 mtr.	06 mtr.	MR				
	 Gate width 	N/A	N/A	N/A				
	 Width of internal road 	N/A	N/A	N/A				
02	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases			7				
	 Upper floor 	01 nos	02 nos	MR				
	 Basement 	N/A	N/A	N/A				
	b. Width of Staircases							
	 Upper floor 	1.50 mtr	1.15 mtr & 0.75 mtr	MR				
	 Basement 	N/A	N/A	N/A				
	c. Protection of exits	AND THE RESIDENCE OF THE PARTY						
	Fire check door	N/A	N/A	N/A				
	 Pressurization 	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A				
	e. Width of corridor	1.50 mtr	1.82 mtr	MR				
	f. Door Size	01 mtr.	01 mtr.	MR				
03	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	Fire dampers	N/A	N/A	N/A				
04	Smoke Management System.							
PLANTA NO. IL PROPERTO NO. IL PROPERTO NO.	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A	N/A				
05.	Fire Extinguishers							
	Total numbers	04 nos.	06 nos.	MR				
	• types	ABC /CO ₂	ABC /CO ₂	MR				
	IS marking	ISI marked	ISI marked	MR				

	Total numbers on each floor	N/A	N/A	N/A		
	Length of hose reel hose	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
7	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	Location of repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
3	MOEFA	N/A	N/A	N/A		
)	Public Address System.	N/A	N/A	N/A		
)	Automatic Sprinkler System.					
The state of the s	Pagamont	N/A	N/A	N/A		
Autopolica and a second and a s	Basement upper floor	N/A	N/A	N/A		
Section of the second	upper floor sprinkler above false ceiling	N/A	N/A	N/A		
1	Internal Hydrants	14//				
	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
200	Hose box	N/A	N/A	N/A		
2	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose box	N/A	N/A	N/A		
3	Pumping Arrangements. > Ground Level					
The property of		N/A	N/A	N/A		
	Discharge of main pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
Casteron Tra	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head Standby nump out put	N/A	·N/A	N/A		
	Standby pump out putStandby pump head	N/A	N/A	N/A		
1	Auto starting /manual stopping	N/A	N/A	N/A		
	Pump house access	N/A	N/A	N/A		
	> Terrace Level					
Tario de la composición dela composición de la composición de la composición dela composición dela composición dela composición de la composición de la composición dela composición de la composición dela	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	N/A		
and the second	Power supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
4	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	N/A	N/A	N/A		
-	Draw-off connection	N/A	N/A	N/A		
Secretary of the second	Fire service inlet	N/A	N/A	N/A		
distribution of the second	Access to tank	N/A	N/A	N/A		
- Const	Overhead tank capacity	N/A	N/A	N/A		
	• Overhead tank capacity	N/A	N/A	N/A		

16	Provision of Lifts.					
7	Pressurization of lift shaft	N/A	N/A	N/A		
	 Pressurization of lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	Lift signage	N/A	N/A	N/A		
17	Standby Power Supply	N/A	N/A	N/A		
18	Refuge Area.					
3	Total area	N/A	N/A	N/A		
	 Location 	N/A	N/A	N/A		
19	Fire Control Room					
RELEVISION PRINCIPLE REPORTS	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	 PA system panel 	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by Director of Education, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

Name

:- Vijay Bahadur

Designation

:- A.D.O (TP)

CIFG Mixell FT/01. 27 letter is put up for signature plante

efo (NDZ) * Miscell