## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2018/ School 2386

Dated: 257 (6/2018

## FIRE SAFETY CERTIFICATE

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in">WWW.dfs.Delhigovt.nic.in</a>

Issued on .....25./1.8...... at New Delhi

Chief Fire Officer Ph:-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 54.
- 2. The Principal, VSPK International School, Sector-13, Rohini, Delhi-110085.

**INSPECTION REPORT** 

1. Name & address of the building : VSPK International School, Sec-13, Rohini, Delhi-110085.

2. Type of Occupancy :Educational

3. Type of Case : Renewal (B+G+03 upper floors)

4. Details of previous NOC :F6/MS/DFS/2003/1153 Dated: 27.05.2003

5. Fire Safety directives letter No : No.F.6./DFS/MS/BP/2002/717 Dated: 01/05/2002

6. Date of inspection : 11.10.20187. Name of the Inspecting Officers : ADO (RN)

8. Name and designation of officers

from the building side : Dr. Neelu Goswami , Principal

9. Year of Construction : 2002

10. Applicant's letter No. : No. nil dairy no. 10834 dated: 27.07/2018

Plot Area-7712.138 sqm

Plot Ai	rea-7712.1						
	Minim	um Standards on fire prevention and fire safety U/R 33	NBC Part 4	Provided at site	Remarks MR/NMR		
1	Access to building						
	•	Road width	06m	06m	MR		
	•	Gate width	05m	05m	MR		
	•	Width of internal road	NA	NA	NA		
	Number	, Width, Type & Arrangement of Exits	,				
	a. Numb	er of staircases					
	•	Upper Floors	02 &01 ramp	02 & 01	MR(old case)		
	•	Basements	02	ramp 03	MR(old case)		
	b. Width	<ul><li>b. Width of staircases</li><li>Upper Floors</li></ul>	0.2	03	- IVIIC(OIG Case)		
	•		1.50m each	1.5m each	MR		
	•	Basements	1.50m	1.50m x02 & 1.00m x02 iron staircase	MR(old case)		
	c. Protec	c. Protection of exits	1.00m AU2 from staticase				
	•	Fire check door	Required	Provided	MR		
	•	Pressurization	Required	Provided	MR		
	d. No. c	f continuous staircases to terrace	NA	NA	NA		
	e. Width	Width of Corridor	1.50m	1.50m	MR		
	f. Door	Size	1.0 m	1.0 m	MR		
	Compa	rtmentation.	=				
	•	Fire check door	Required	Provided	MR		
	J.,						



13	Pumpin	g Arrangements.	<del></del>				
	•	Ground Level	ound Level				
	-	Discharge of main Pump	N/A	N/A	N/A		
		<ul><li>Head of Main pump</li><li>Number of main pumps</li></ul>	N/A	N/A	N/A		
		Jockey Pump out put	N/A	N/A	N/A		
		> Jockey pump head	N/A	N/A	N/A		
		Standby Pump out put	N/A	N/A	N/A		
		Standby Pump Head	N/A	N/A	N/A		
		Auto Starting/ Manual stopping	N/A	N/A	N/A		
		Pump House Access	N/A	N/A	N/A		
	<ul><li>Terrace level</li><li>Discharge of pump</li></ul>	1620 lpm	900 lpm x2	MR			
		Head of the pump	40m	40m	MR		
		<ul><li>Power Supply</li></ul>	Required	Provided	MR		
		> Auto Starting of pump	Required	Provided	MR		
4	Captive Water Storage for fire fighting.						
	•	Underground tank capacity	NA	NA	NA		
	>	Draw-off connection	NA	NA	NA		
	>	Fire service inlet	NA	NA	NA		
	>	Access to tank	NA	NA	NA		
	•	Overhead Tank capacity	20,000 ltrs	25,000 ltrs	MR		
5	Exit Sig	nage.	Required	Provided	MR		
5	Provision of Lifts.						
	•	Pressurization of Lift Shaft	NA	NA	NA		
	•	Pressurization of Lift lobby	NA	NA	NA		
	•	Communication In lift Car	NA	NA	NA		
	•	Fireman's Grounding Switch	NA	NA	NA		
	•	Lift Signage	NA	NA	NA		
7	Standby	power supply	Required	Provided	MR		
8	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
9	Fire Control Room						
	•	Detector System Panel	NA	NA	NA		



Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Batter backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
O Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 1153 dated 27.05.2003 under DFS Rules, 2010.

> Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation: - ADO/RN

As approved F.T. Letter in failings or your signature Pl 1/1.