GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2018/NDZ/ 2342

Dated: | 6 | 10 | 18

FIRE SAFETY CERTIFICATE

Certified that the Evergreen Public School, C-32, Acharya Niketan, Mayur Vihar, Phase-1, Delhi-91, owned/occupied by Evergreen Public School, comprised of ground plus two upper floors was issued Fire Safety Certificate vide letter no. F.6/DFS/MS/School/2015/NDZ/1032 dt-18/06/15. The school building was re-inspected by the officer concerned of this department on 10/09/18 in the presence of Smt. Anita Sharma (Principal) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular no.262-362 Dated 17.01.2005 issued by the Director of Education and found that the building is fit for occupancy class B "Educational Building" with effect from for a period of three years, subject to conditions printed overleaf.

Issued on 16 10 18 at New Delhi by

9 | 次, (Vipin Kental) Chief Fire Officer Delhi Fire Service

To,

The Principal, Evergreen Public School, C-32, Acharya Niketan, Mayur Vihar, Phase-1, Delhi-91.

Copy to:-

 The Director of Education, EDMC, Udyog Sadan, Plot No. 419, FIE, Patpargani Industrial Area, Delhi-92.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

ADO LM

1. Name & address of the building: Evergreen Public School, C-32, Acharya Niketan, Mayur

Vihar, Phase-1, Delhi-91.

2. Building is comprised of

: G+2 upper floor

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous NOC létter: F.6/DFS/MS/School/2015/NDZ/1032 dt-18/06/15

6. Fire Safety direction letter No : Circular No.262-362 Dated 17.01.2005

7. Date of Inspection

: 10/09/18

8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of Officer

from the building side

: Smt. Anita Sharma (Principal)

10. Year of Construction

:2000

11. Applicant's letter No

: EPS/MV/9-29/2018/1922 dated 10/08/18

| V | Minimum Standards on fire prevention and | Old Circular | Provided at | Remarks | | | |
|----|--|--------------|--------------|---------|--|--|--|
| | fire safety U/R33 | Requirement | Site | | | | |
| - | Access to building | | | 8.45 | | | |
| | Road width | 06 M | 10 M | MR | | | |
| - | Gate width | N/A | N/A | N/A | | | |
| | Width of internal road | N/A | N/A | N/A | | | |
| | Number, Width, Type and Arrangement of Exits | | | | | | |
| | a. Number of Staircases | | OO Noo | MR | | | |
| | Upper Floor | 01 No | 02 Nos. | N/A | | | |
| | Basement | N/A | N/A | 19/7 | | | |
| | B. Width of Staircases | | 4 5 0 4 40 M | MR | | | |
| | Upper Floor | 1.5 M | 1.5 & 1.10 M | N/A | | | |
| | Basement | N/A | N/A | | | | |
| | c. Protection of exits | N/A | N/A | N/A | | | |
| | Fire check door | N/A | N/A | N/A | | | |
| | Pressurization | N/A | N/A | N/A | | | |
| | e. No. of continuous staircases to | 1 no. | 1 No | MR | | | |
| | terrace • | 1.5 M | 1.8 M | MR | | | |
| | g. Width of Corridor | 1.0 M | 1.0 M | MR | | | |
| 3 | h. Door Size Compartmentation. | | | | | | |
|) | Fire check door | N/A | N/A | N/A | | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | | |
| | - to all all all all all all all all all al | N/A | N/A | N/A | | | |
| | 100 | N/A | N/A | N/A | | | |
| | The second secon | N/A | N/A | N/A | | | |
| A | • File Dailipers Creaks Management System | | | | | | |
| 4 | Basement | N/A | N/A | N/A | | | |
| | Upper floor | N/A | N/A | N/A | | | |
| 5. | Fire Extinguishers | | | | | | |
| J, | Total numbers | 06 Nos. | 06 Nos. | MR | | | |
| | Types | ABC & Co2 | | | | | |
| | IS marking | ISI marked | ISI marke | d MR | | | |

MB

| 6 . | First-aid-Hose Reels. | | | | | |
|-----------------------------------|---|--|------------|-----|--|--|
| | Total numbers of each floor | 1 no. | 1 no. | MR | | |
| | Length of hose reel hose | 30 M | 30 M | MR | | |
| | Nozzle diameter | 5 mm | 5 mm | MR | | |
| 7 | Automatic fire detection and alarming system. | | | | | |
| | Type of detectors | N/A | N/A | N/A | | |
| | Location of main panel | N/A | N/A | N/A | | |
| | Location of repeater panel | N/A | N/A | N/A | | |
| | Alternate source of power | N/A | . N/A | N/A | | |
| | Hooter's location | N/A | N/A | N/A | | |
| 8 | MOEFA | N/A | N/A | N/A | | |
| 9 | Public address System. | N/A | N/A | N/A | | |
| 10 | Automatic Sprinkler System. | N/A | N/A | N/A | | |
| | Basement | N/A | N/A | N/A | | |
| | upper floor | N/A | N/A | N/A | | |
| 9 | sprinkler above false ceiling | N/A | | N/A | | |
| 11 | Internal Hydrants | å = ================================== | 8 | | | |
| | size of riser/down-comer | N/A | N/A | N/A | | |
| | Number of hydrants per floor | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | N/A | | |
| 12 | Yard Hydrants. | <u> </u> | P | | | |
| | Total number of hydrants | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | N/A | | |
| 13 | Pumping Arrangements. | | | | | |
| | Ground Level | N/A | N/A | N/A | | |
| | Discharge of main Pump | N/A | N/A | N/A | | |
| | Head of Main Pump | N/A | N/A | N/A | | |
| | Number of main pumps | N/A | · N/A | N/A | | |
| | Jockey pump out put | N/A | N/A | N/A | | |
| | Jockey pump head | N/A | N/A | N/A | | |
| | Standby pump out put | N/A | N/A | N/A | | |
| | Standby pump Head | N/A | N/A | N/A | | |
| | Auto Starting /Manual | N/A | , N/A | N/A | | |
| Mind Carl Charles And Annie Annie | stopping | | | * | | |
| - | Pump House Access | N/A | N/A | N/A | | |
| | Terrace Level | Required | Provided | MR | | |
| | Discharge of pump | 225 LPM | 225 LPM | MR | | |
| | Head of the Pump | 40 M | 40 M | MR | | |
| | Power supply | Required | Provided | MR | | |
| 4.4 | Auto Starting of pump | Required | Provided | MR | | |
| 14 | Captive Water Storage for Fire Fighting. | N/A | N/A | N/A | | |
| | Underground tank capacity | N/A | N/A | N/A | | |
| | Draw-off connection | N/A | . N/A | N/A | | |
| | ➢ Fire service inlet | N/A | N/A | N/A | | |
| | Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | 2500 Ltrs. | 2500 Ltrs. | MR | | |

| 15 | Exit Signage. | Required | Provided | MR |
|----|--|----------|----------|-----|
| 16 | Provision of Lifts. | | | |
| | Pressurization of Lift Shaft | N/A | N/A | N/A |
| - | Pressurization of Lift lobby | N/A | N/A | N/A |
| | Communication in lift car | N/A | N/A | N/A |
| | Firemen's grounding switch | N/A | N/A | N/A |
| 17 | Lift Signage | N/A | N/A | N/A |
| 18 | Standby power supply | N/A | N/A | N/A |
| | Refuge Area | N/A | N/A | N/A |
| | Total area | N/A | N/A | N/A |
| 19 | Location | N/A | N/A | N/A |
| | Fire Control Room | N/A | N/A | N/A |
| | Detector system panel | N/A | N/A | N/A |
| | Flow switch panel | N/A | N/A | N/A |
| | PA system panel | N/A | N/A | N/A |
| | Battery backup | N/A | N/A | N/A |
| 20 | Building Floor Plans | N/A | N/A | N/A |
| | Special Fire Protection systems for protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety Measures as required under the rules. The Fire Safety certificate issued vide letter no. F.6/DFS/MS/School/2015/NDZ/1032 dt-18/06/15 renewal under the circular no.262-362 dated 17.01.2005 is recommended.

Signature of the Inspecting Officer

Name:- R.K.Yadav Designation:- ADO(LN)

vor Drurol Mon

AQ,

m-scell

F7101.

Su, Ff heller co

put cep for

sign pl.

8/10/2018

CFO(ND2)

miscell We