GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/BNQT./2018/SZ/ 2460

Dated: 25/10/18

FIRE SAFETY CERTIFICATE

Certified that the **M/s Silver Grand Banquet**, S-26 (Part), Second Floor, Ivory Tower, Old Ajanta Cinema Complex, Ajay Enclave, Subhash Nagar, New Delhi, comprised of lower basement, upper basement, ground floor plus four upper floors, but Banquet hall is running at second floor only, was issued FSC by this department vide letter no. F6/DFS/MS/2013/SZ/625 dated 26.07.2013 in the name & style of M/s Green Lounge West Banquets (a unit of Neeti Nagpal Estates Pvt. Ltd.) now owned/occupied by M/s Silver Grand Banquet was re-inspected by the officers concerned of this department on 20.09.2018 in the presence of Sh. Yaddu Mohan Mittal (MD) and found that M/s Silver Grand Banquet have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (**Second floor Only**) is fit for occupancy class Group-D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 25 11012018 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. The Manager,
M/s Silver Grand Banquet, S-26 (Part), Second Floor, Ivory Tower, Old Ajanta
Cinema Complex, Ajay Enclave, Subhash Nagar, New Delhi

2. The Dy. Health Officer, S.D.M.C, Public Health Department, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-110027 Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of lower basement, upper basement, Ground floor plus four upper floors but banquet hall is running at second floor only. INSPECTION REPORT Name & address of the building: M/s Silver Grand Banquet, S-26 (Part), Second Floor, Ivory Tower, Old Ajanta Cinema Complex, Ajay Enclave, Subhash Ngr, ND 2. Type of Occupancy Group D (Assembly Building) 3. Type of Case Renewal 4. Details of Previous NOC F6/DFS/MS/2013/SZ/625 dated 26.07.2013 5. Fire Safety directives letter No. F6/MS/DFS/BP/2004/1973 dated 31.08.2004 6. Date of inspection 20.09.2018 7. Name of Inspecting Officers D.O. M.K. Chattopadhyay & A.D.O. Sandeep Duggal Name and designation of officers From the building side Sh. Yaddu Mohan Mittal (MD) Year of Construction 2010-2011 10. Applicant's letter No. : Nil dated 24.08.2018 S. Minimum Standards on fire prevention and fire Requirement as Provided at Remarks No. safety U/R 33 per FSC dt. site MR/NMR 26.07.2013 1. Access to building Road width 09 mtrs Provided MR Gate width 06 mtrs Provided MR Width of internal road N/A N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 05 no.'s Provided MR Basements 03 no.'s & 01 ramp 03 no.'s & 02 ramps MR b. Width of staircases 200 & 150 cms 200, 150, 150, 150 MR Upper Floor &150 cms Basements 150 cms 200, 150 & 150 cms MR & 02 ramps c. Protection of exits Fire check door Required Provided MR Pressurization Required Provided MR d. No. of continuous staircases to Required Provided MR terrace Width of Corridor 150 cms 205 cms MR 200/150/100 cms 200, 150, 160 & MR Door Size 140 cms 3. Compartmentation Fire check door Required Provided MR Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System Basements Required Provided MR Upper floors Required Provided MR 5. Fire Extinguishers Total numbers 14 No.'s Provided MR ABC/CO₂ Types Provided MR ISI marked IS marking Provided MR 6. First-Aid Hose Reels Total numbers on ground floor Two Provided MR

	Type of detectors	Smoke	Provided	MR		
*	 Location of Main Panel 	Required	G Floor	MR		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	Required	Provided	MR		
	Hooters' Location	Required	Nr. Main gate	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	Basement	Required	Provided	MR		
	Ground Floor	Required	Provided	MR		
4.4	Sprinkler above false ceiling	Required	Provided	MR		
11.	Internal Hydrants					
	Size of riser/down-comer	150 mm	Provided	MR		
	Number of hydrants	Two	Provided	MR		
	Hose Box	Two	Provided	MR		
12.	Yard Hydrants			,		
	Total number of hydrants	09 no.'s	Provided	MR		
v	Hose Box	09 no.'s	Provided	MR		
13.	Pumping Arrangements		(Common with w	hole premises)		
	Ground Level					
	Discharge of main Pump	2850 LPM	Provided	MR		
	Head of Main pump	60 m	Provided	MR		
9	Number of main pumps	Two	Provided	MR		
	Jockey Pump out put	450 LPM	Provided	MR		
	Jockey pump head	60 m	Provided	MR		
	* ***	2850 LPM				
	Standby Pump out put		Provided	MR		
	Standby Pump Head	60 m	Provided	MR		
	Auto Starting/Manual Stopping	Required	Provided	MR		
	Pump House Access	Required	Provided	MR		
	Terrace level					
	Discharge of pump	450 LPM	Provided	MR		
	> Head of the pump	30 mtrs	Provided	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
	·		4.5			
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	2,00000 ltrs	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	Fire service inlet	•				
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
15.	Evit Signage	20000 ltrs	Provided	MR		
16.	Exit Signage. Provision of Lifts.	Required	Provided	MR		
10.				<i>y</i>		
	Pressurization of Lift Shaft Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of Lift lobbyCommunication In lift Car	Required	Provided	MR		
	Communication In lift CarFireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
	Zin Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.					
	Total AreaLocation	N/A	N/A	N/A		
		N/A	IV th floor	N/A		

19.	Fire Control Room						
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup 	Required	Provided	MR			
		N/A	N/A	N/A			
		Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
		Required	Provided	MR			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection and the shortcomings communicated by this department vide letter no. F.6/DFS/MS/BNQT/2018/SZ/2137 dated 18.05.2018 has been complied.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. <u>F6/DFS/MS/2013/SZ/625</u> dated <u>26.07.2013</u>, renewal/grant under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Note: Earlier FSC was issued in the name and style M/s Green Lounge West Banquets (a unit of Neeti Nagpal Estates Pvt. Ltd.). Mini Theatre cum Commercial Complex building in which aforementioned banquet hall is situated has already been issued FSC by this department vide Letter No. F6/DFS/MS/SZ/2018/1770 dated 30.07.2018.

Signature of Inspecting Officer Name: - D.O. M.K. Chattopadhyay Designation: - Divisional Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

10/10/800 10/10/2018 10/10/2018 Dy. C.F.O.(South Zone)

296/1/20

The old Alanta Cinema Corafole & renewal is due. The FSC of same needs to be renewed before is successful. The FSC of samples souls.

The old Alanta Cinema Corafole & same needs to be renewed by same is a successful to be renewed by being net sail.

Mescell

4/x

DCASZ

8/10/18

Xan D