## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2018/ 236 9

Dated: 18/(0/(8

## FIRE SAFETY CERTIFICATE

Hospital, Gurdwara Road, Karol Bagh, New Delhi- 110005 comprised of basement, stilt, ground plus three upper floors, using basement as (storage/hall), stilt (parking & reception), ground floor (05 guest rooms), first floor (05 guest rooms), second floor (05 guest rooms) & third floor (05 guest rooms) owned/occupied by M/s Scope Promoters Pvt. Ltd was inspected by the officer concerned of this department on 15/10/2018 in presence of Sh. Kamlesh Parekh, Director (M/s Scope Promoters Pvt. Ltd) of the guest house and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house-lodging & boarding) total 20 guest rooms with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 18 10 118 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

## Copy to:-

- 1. The Director, Hotel Swati Deluxe, 17A/34, WEA, Opp. Jessa Ram Hospital, Gurudwara Road, Karol Bagh, New Delhi- 110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1<sup>st</sup> floor, New Delhi.

## Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

1. Name & address of the building: M/s. Hotel Swati Deluxe (ANX-2), 17A/34, WEA, Opp. Jessa Ram Hospital, Gurudwara Road, Karol Bagh, New Delhi- 05

2. Type of Occupancy : Lodging House

3. Type of Case : New Case4. Details of previous NOC : N/A

5. Fire Safety directives letter No : Nil

6. Date of inspection : 15.10.2018

7. Name of the Inspecting Officers : M.K. Chattopadhyay, DO(South West)

8. Name and designation of officers

from the building side : Sh. Kamlesh Parekh, Director

9. Year of Construction : 2009

10. Applicant's letter No. : No 1092-95/Addl .C.P./Lic.(H) dated New Delhi 06.09.2018

The said guest house is comprised of basement, stilt, ground plus three upper floors.

S. No.	prev	Iinimum Standards on fire ention and fire safety U/R 33	Arrangements as per NBC-2005 / BBL- 1983	Provided at site	Remarks MR/NMR			
1	Access	s to building						
	•	Road width	06 mts	Provided	MR			
	•	Gate width	4.5 mts	Directly accessible	MR			
	•	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits							
	1	ber of staircases	_	_				
	•	Upper Floors	01	01	MR			
	•	Basements	01	01	MR			
	b. Wid	th of staircases	-	-	-			
	•	Upper Floors	1.25 mts	1.40 mts	MR			
	•	Basements	1.25 mts	1.40 mts	MR			
	c. Prote	ction of exits	-	-				
	•	Fire check door	Required in basement floor	Provided	MR			
		Pressurization	N/A	N/A	N/A			
		f continuous staircases to terrace	01	01	MR			
		h of Corridor	1.25 mts	Provided	MR			
	h. Door	Size	1.25 mt.	Provided	MR			
	Compa	rtmentation.			2_			
	•	Fire check door	Required in basement floor	Provided	MR			
	•	Sealing of electrical shafts	Required	Provided	MR			
		Fire Rating of shaft door	N/A	N/A	N/A			
		Water Curtain	N/A	N/A	N/A			
	• ]	ire Dampers	N/A	N/A	N/A			
	Smoke	Management System.						
		Basements	30 a/c per hour	Provided	MR			
	• 1	Upper floors	12 a/c per hour	N/A	N/A			
	TO: 10			- 1/2 4	14//1			

	Total numbers	20	Provided	M	
	• Types	CO <sub>2</sub> , ABC, WCO			
	IS marking	ISI marked		MR	
6	First-Aid Hose Reels.		Trovided	MR	
	Total numbers on each floor	01	Provided	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming	system.		IVIIC	
	Type of detectors	N/A	N/A	N/A	
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A		
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	Required	Provided		
9	Public Address System.	N/A	N/A	MR N/A	
10	Automatic Sprinkler System.		11/21	IVA	
	Basement	Required	Provided	MR	
	Upper Floor	N/A	Provided	TVIIC	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants	Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A		
	Hose Box	N/A	N/A	N/A N/A	
12	Yard Hydrants.			IN/A	
12	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A	
•	Hose Box	N/A	N/A		
13	Pumping Arrangements.		11//1	N/A	
	• Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	• Terrace level			IN/A	
	Discharge of pump	900 LPM	provided	MR	
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>	30 mts	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	

1		Onderground tank capacity	IN/A	N/A	N/A			
1	~	Draw-off connection	N/A	N/A	N/A			
	>	Fire service inlet	N/A	N/A	N/A			
	>	Access to tank	N/A	N/A	N/A			
	•	Overhead Tank capacity	15,000 lts	Provided	MR			
15	Exit S	ignage.	Required	Provided	MR			
16	Provision of Lifts.							
	•	Pressurization of Lift Shaft	N/A	N/A	N/A			
	•	Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	Required	Provided	MR			
	•	Fireman's Grounding Switch	Required	Provided	MR			
	•	Lift Signage	Required	Provided	MR			
17	Standl	y power supply	Required	Provided	MR			
18	Refug	Refuge Area.						
	>	Total Area	N/A	N/A	N/A			
	>	Location	N/A	N/A	N/A			
19		Fire Control Room						
RE S	RL.	Detector System Panel	N/A	N/A	N/A			
:40	Free	Flow Switch Panel	N/A	N/A	N/A			
17-3	- 16	PA System Panel	N/A	N/A	N/A			
tery No	101	Battery backup	Required	Provided	MR			
er Fire	•	Building Floor Plans	N/A	N/A	N/A			
20	Special Protect	Fire Protection Systems for ion of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules-2010.

DFA is put up for approval & signature please.

15 10 20 8 DCFO (SZ)

M.K. CHATTOPADHYAY Div. Officer (South West)

133/cfos2

16/10

Soisy

m.stell

FT 10)-