GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2018/SZ/ 2 3 3 7

Dated: 1.6.1.1.0.1 8

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Daryaganj (A Unit of Matchless Restaurant Pvt. Ltd) located at Shop No–R1, Lower Ground Floor, Worldmark-I, Aerocity, New Delhi-110037, comprised of three tiers basement, mezzanine, ground + 06 upper floors. The restaurant running at Lower GF of the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 01/10/2018 in the presence of Mr. Tanush Bhalla (Director) and that the premises is fit for occupancy class 'Assembly' Group–D (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 1668 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. Director, M/s Daryaganj (U/o Matchless Restaurant Pvt. Ltd), Shop No.-R1, Lower GF, Worldmark-I, Aerocity, New Delhi-110037
- 2. Dy. Health Officer, South MCD, Public Health Department, Najafgarh Zone, Dhansa Stand, Najafgarh, New Delhi-110043

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

		N REPORT	L(II/o Matchless Restau	rant Pvt.		
1	Name & Address of the Building	M/s DARYAGANJ (U/o Matchless Restaurant Pvt.				
		Ltd), Shop No-R1, LGF, Worldmark-I, Aerocity,				
		New Delhi-110037 (66 Seats) Assembly 'Group-D' (Restaurant)				
2	Type of Occupancy	03 Basements, Mezzanine, Ground + 06 floors.				
3	Building comprised of					
4	Type of Case	New F.6/DFS/MS/Mixed/SZ/2018/338 dated 28/02/2018 (Bldg)				
5	Details of Previous NOC	F.6/DFS/MS/BP/2017/Hotel/368 dated 23/02/2017 (Bldg)				
6	Fire Safety Directives Letter No					
7	Date of Inspection	01-10-2018 Mehmood, ADO (SJ)				
8	Name of the Inspecting Officers	Mr. Tanush Bhalla (Director)				
9	Name & Designation of Officers	IVII. Tallusii Bhana (Dheetoi)				
1.0	from the building side	2014				
10	Year of construction	Outdoor diary No. 13350 dated 18-09-2018				
11	Applicant letter No.	UBBL/NBC-2016 Provided at Site Rema				
S. No.	Minimum standards on Fire Prevention	Requirements	1 Toylaca at Site	MR/NMR		
-	and Fire Safety U/R 33	Provided & Maintained by Bldg Mgmt.				
1.	Access to Building.	Restt located	As above	MR		
	Road width	within	As above	N/A		
	Gate width	Worldmark-I	As above	N/A		
	Width of internal road		715 400 10			
2.	Number, width, type & arrangement of exits a Number of Staircase Provided & Maintained by Bldg Mgmt.					
	a. Number of Staircase	N/A	As above	N/A		
	Upper floors		As above	MR		
	Basement floor	02 Nos				
	b. Width of Staircase		d & Maintained by Bldg	N/A		
	 Upper floors 	N/A	As above			
	Basement floor	2m /1.35m	1.6m each + 7.5m ramp	MR		
	c. Protection of exits	Provided & Maintained by Bldg Mgmt.				
	Fire check door	Required	As above	MR		
	Pressurization	Required	As above	MR		
		Required	As above	MR		
	***************************************	N/A	N/A	N/A		
	e. Width of corridor f. Door size	2m/1.35m	2m & 1.35m	MR		
3.	Compartmentation.	Provided & Maintained by Bldg Mgmt.				
3.	Fire check door.	Required	As above	MR		
	C 1 C 1 L 1 1 - 0 -	Required	As above	MR		
		Required	As above	MR		
	Fire rating of shaft door.Water curtain	Required	As above	MR		
	• Fire dampers.	N/A	As above	N/A		
4.	Smoke Management system.	Provide	ed & Maintained by Bldg	Mgmt.		
4.	Basement / Restt. Area	Required	Smoke venting provided			
		N/A	As above	N/A		
	Upper floors.	11/71	110 000 10			
5.	Fire Extinguishers.	0631	Duaridad	MR		
	Total numbers	06 Nos	Provided 04 / 02	MR		
	• Types	ABC / CO2		MR		
	ISI Marking	ISI marked	Provided			
<u>,</u> 6.	First Aid Hose Reels.		ed & Maintained by Bld	MR MR		
	 Total numbers on each floor. 	One	As above			
	 Length of hose-reel hose. 	30m	As above	MR		
1		5mm	As above	MR		

M/s Daryaganj (U/o Matchless Restt Pvt. Ltd), Shop No-R1, LGF, Worldmark-I, Aerocity, New Delhi

7.	Automatic fire detection & alarming system.	Provided	& Maintained by Bldg M	Igmt.
	Type of detectors	Required	Smoke & Heat	MR
	 Location of Main Panel 	Required	Mezzanine floor	MR
19	 Location of Repeater Panel 	Required	FCR at GF	MR
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	All area	MR
8.	MOEFA	Required	As above	MR
9.	Public Address System	N/A	As above	N/A
10.	Automatic Sprinkler System	Provided	& Maintained by Bldg N	Agmt.
10.	Basement / Restt. Area	Required	As above	MR
	• Upper floors	N/A	As above 🧪 📑	N/A
	Sprinkler above false ceiling	N/A	As above	N/A
11	Internal Hydrants.	Provided	& Maintained by Bldg	Mgmt.
11.	C' CD' /D	N/A	As above	N/A
		N/A	As above	N/A
	Number of Hydrant per floor	N/A	As above	N/A
10	Hose box.		I & Maintained by Bldg	
12.	Yard Hydrants.	N/A	As above	N/A
	Total number of hydrants.	N/A	As above	N/A
	Hose box.			
13.	Pumping arrangements.	Pumping arrangements are common for the complex Provided & Maintained by Bldg Mgmt.		
	Ground Level		2280 LPM	N/A
	Discharge of main pump.	N/A	105m	N/A
	Head of main pump.	N/A	Two	N/A
	Number of main pumps.	N/A	2 x 180 LPM	N/A
	Jockey Pump output.	N/A	105m	N/A
	Jockey Pump head.	N/A	2280 LPM	N/A
	Standby Pump output.	N/A		N/A
	Standby Pump head.	N/A	105m	N/A
	> Auto Starting / Manual Stopping.	N/A	Provided	N/A N/A
	Pump House Access	N/A	Provided	
	Terrace Level		d & Maintained by Bldg	
	Discharge of pump.	450 LPM	900 LPM	MR
	Head of pump.	40 mtr	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Bldg Mgmt.		
	 Underground tank capacity. 	N/A	1,50,000 Ltr	N/A
	Draw-off connection.	N/A	Provided	N/A
	Fire Service Inlet.	N/A	Provided	N/A
	Access to tank.	N/A	Provided	N/A
	 Overhead tank capacity. 	10,000 Ltr	20,000 Ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		ed & Maintained by Bld	
	 Pressurization of lift shaft. 	N/A	As above	N/A
	 Pressurization of lift lobby. 	N/A	As above	N/A
	 Communication in lift car. 	N/A	As above	N/A
	• Fireman's switch.	N/A	As above	N/A
	• Lift signage.	N/A	As above	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area	Provided & Maintained by Bldg Mgmt.		
100	Total area	N/A	550 m ²	N/A
	• Location	N/A	6 th floor	N/A
į.	28 1 6 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- ACTION CO.	Worldmark-I, Aerocity.	37 410 410-4

M/s Daryaganj (U/o Matchless Restt Pvt. Ltd), Shop No-R1, LGF, Worldmark-I, Aerocity, New Delhi

19.	Fire Control Room.	Provided	Provided & Maintained by Bldg Mgmt.		
	Detector System Panel.	N/A	As above	N/A	
	• Flow Switch Panel.	N/A	As above	N/A	
	• PA system Panel.	N/A	As above	N/A	
	Battery backup	N/A	As above	N/A	
	Building floor plan	N/A	As above	N/A	
20.	Special Fire Protection System for the	N/A	As above	N/A	
	Protection of special Risk, if any:				

The Fire protection systems provided in the premises/building were test checked at random and found functional at the time of inspection. Keeping in view of substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: Mehmood

Design: ADO (SJ)

M/s Daryaganj (U/o Matchless Restt Pvt. Ltd), Shop No-R1, LGF, Worldmark-I, Aerocity, New Delhi

DO (8D)

Kindly apsise brow the sequirement of staiscase is M12 in point No. 2.4 if is the premise is covered under hule 27.

STO Sir The quidlines issued By our dept vide

6.61 AFE IMET BR12017 12 Alots 1368 Off 21.217

6.61 AFE IMET BR12017 12 Alots 1319 from Composite

is mp. in but, No-2 to for 141.9 from Composite

is mp. in for according 94 porson from Control

lasel 1.5 mgm for according 12 from Control

in the late 27 Subscitted

20 CEMAIS

15/10/18 Am (45

dy cocon

117/c/o 52

xam

M c co 1/1

FTD,