

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110 001

No. F.6/DFS/MS/Industrial/SZ/2018/ 23/9

Dated: 12/10/18

FIRE SAFETY CERTIFICATE

Certified that **M/s Fashion Trendz**, situated at S-40, Okhla Industrial Area, Phase-II, New Delhi-110020, comprised of Basement, Ground & Three Upper Floors has already been issued FSC by this department vide letter No. F6/DFS/MS/2014/SZ/365 dated 31/03/2014. The building was re-inspected by the officer concerned of this department on 09/10/2018 in the presence of Sh. Ravi Chaudhary & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is deemed fit for occupancy **Group G "Industrial"** with effect 12/10/2018 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on 12/10/18...at New Delhi by.


(Vipin Kental)
Chief Fire Officer
Ph:-011-23412235


Copy to:-

1. Shri Sachbir Singh, M/s Fashion Trendz, situated at S-40, Okhla Industrial Area, Phase-II, New Delhi-110020
2. The Executive Engineer (Bldg.), SDMC, Jal Vihar, Lajpat Nagar, New Delhi-110024

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry."

INSPECTION REPORT

1. Name & address of the building : M/s Fashion Trendz, S-40, Okhla Industrial Area, Phase-II, New Delhi-110020
2. Type of Occupancy : Industrial "Group-G"
3. Type of Case : Renewal [Basement, Ground & 3 Upper Floors]
4. Details of Previous NOC : F6/DFS/MS/2014/SZ/365 dated 31/03/2014 [For Basement & Ground Floor Only]
5. Fire Safety directives letter No : F6/DFS/MS/BP/2013/2400 dated 10/10/2013
6. Date of inspection : 09/10/2018
7. Name of Inspecting Officer : A. K. Malik
8. Name and designation of officer from the building side : Mr. Ravi Chaudhary
9. Year of Construction : 1992
10. Applicant's letter No. : outdoor diary no. _____ dated 19/02/2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	9m NA NA	Provided Abut on Road NA	MR NA NA
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	Two Two	Two Two	MR MR
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.2m 1.2m	Provided Provided	MR MR
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required NA	Provided NA	MR NA
	d. No. of continuous staircases to terrace	One	Two	MR
	e. Width of Corridor	NA	NA	NA
	f. Door Size	NA	1m (final exit)	NA
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required NA NA NA NA	Provided NA NA NA NA	MR NA NA NA NA
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 ACPH 12 ACPH	Exhaust Fan Exhaust Fan	MR MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	30 No's ABC/W.CO ₂ / CO ₂ ISI marked	30 No's 10/10/10 Nos Yes	MR MR MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	01 Nos 30m 5mm	Provided 30m 5mm	MR MR MR
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location 	Smoke & Heat Ground Floor NA Required Required	Provided Provided NA Provided	MR MR NA MR

	<ul style="list-style-type: none"> Basement Upper Floors Sprinkler above false ceiling 	Required	Provided	MR
		Required	Provided	MR
		NA	NA	NA
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	100mm	Provided	MR
		01 No	Provided	MR
		01 No	Provided	MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	Required	2 Nos	MR
		Required	Provided	MR
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual Stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	2280 LPM	Provided	MR
		60m	Provided	MR
		One	Provided	MR
		180 LPM	Provided	MR
		60m	Provided	MR
		2280LPM	Electric Provided	MR
		60m	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		NA	2280 & 450 LPM	NA
		NA	40m	NA
		NA	Provided	NA
		NA	Provided	NA
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> Underground tank capacity <ul style="list-style-type: none"> Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	75,000 Lts	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		20,000 Lts	Provided	MR
		Required	Provided	MR
15.	Exit Signage.			
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> Total Area Location 	NA	NA	NA
		NA	NA	NA
19.	Fire Control Room			
	<ul style="list-style-type: none"> Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

N/17

M/s Fashion Trendz, S-40, Okhla Industrial Area, Phase-II, New Delhi-110020

vide letter no. F6/DFS/MS/Ind./SZ/2018/1377 dated 05/10/16 except at sr. no. 2 found complied, however this is shown as MR in point no.13 of the inspection note on parity with J P Ghosh (MCIE) as mentioned by applicant (C/75) that separate DG set is provided for the stand by electric driven pump.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended under Rule 37(2) to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA of Form "H" is put up for approval under Rule 37(3).

Anilash
10/10/18
Signature of Inspecting Officer
Name: A. K. Malik
Designation: Divisional Officer

DY. CFO(SZ)

Kapoor
11/10

CFO SZ

m.scell

FTA

12/10



99/ds2
12/10

Site F.P. is put up for his place.

CFO(SZ)

Anilash
12/10/18
DSO

m.scell *12/10*