GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/EH/2018/SZ/ 2307

Dated: 12/10/18

FIRE SAFETY CERTIFICATE

Certified that the M/s KFC Restaurant (A unit of sapphire foods), Shop No.-8 to 11, Plot No.-19, Satyam Complex, District Centre, Janakpuri, New Delhi-110058, is running at ground floor of the Satyam Cineplex complex building, was issued FSC by this department vide letter no. F6/DFS/MS/EH/2014/SZ/1085 dated 28.08.2014 owned/occupied by M/s KFC Restaurant (A unit of sapphire foods) was re-inspected by the officers concerned of this department on 20.9.2018 in the presence of Sh. Vinod Kumar (RGM) and found that Management of M/s KFC Restaurant (A unit of sapphire foods) have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground Floor Only) is fit for occupancy class Group-D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

1. The Manager,
M/s KFC Restaurant (A unit of sapphire foods), Shop No.-8 to 11, Plot No.-19, Satyam Complex, District Centre, Janakpuri, New Delhi-110058

2. The Dy. Health Officer, S.D.M.C, Public Health Department, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-110027 Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

ADOTEP

TA EL	INSPECTION	REPORT	1				
	1. Name & address of the building: M/s KFC Re	estaurant (A unit of					
		Satyam Complex, Dis Assembly Building)	strict Centre, Janakp	ouri, New Delhi-58			
	2. Type of Occupancy : Group D (A) 3. Type of Case : Renewal	Assembly building)					
		S/EH/2014/SZ/1085	dated 28.08.2014				
	5. Fire Safety directives letter No : N/A	5/21/2011/52/1000					
	6. Date of inspection : 20.9.2018						
		Chattopadhyay & A	A.D.O. Sandeep D	uggal			
	8. Name and designation of officers						
	From the building side : Sh. Vinod Kumar (RGM)						
	9. Year of Construction : 2010	NT!!					
S.	10. Applicant's letter No. : Nil dated : Minimum Standards on fire prevention and fire	Requirement as	Provided at	Remarks			
No.	safety U/R 33	per FSC dt. 28.08.2014	site	MR/NMR			
1.	Access to building			e			
	Road width	09 mtrs	12 mtrs	MR			
	Road width Gate width	4.5 mtrs	Directly accessible	MR			
	Gate width Width of internal road	06 mtrs	from internal road	MR			
	widin of internal load		Provided				
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	N/A	N/A	(restaurant at GF			
	Basements			only)			
		N/A	N/A	N/A			
	b. Width of staircases		8				
	• Upper Floor	N/A	N/A	(restaurant at GF			
	Basements			only)			
	c. Protection of exits • Fire check door	N/A	N/A	N/A			
			. 4				
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	terrace		* ne p				
	e. Width of Corridor	N/A	One	N/A			
		N/A	Opening in	N/A			
	f. Door Size	IN/A	hall	IN/A			
		02 mtrs	200 & 105 cms	MR			
3.	Compartmentation	OZ IIIIIS	200 00 100 01115	(restaurant at GF			
J.	Compartmentation			only)			
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	• Fire Rating of shaft door	8 8					
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System (Restaurant at GF only						
	Basements	N/A	N/A	N/A			
	Dasoniono	- 22.5		-			
	Upper floors	Required	Provided	MR			
5.	Fire Extinguishers	9					
	Total numbers	04 No.'s	Provided	MR			
	• Types	ABC/CO ₂	Provided	MR			
	IS marking	ISI marked	ISI marked	MR			
6.	First-Aid Hose Reels	101 mantou					
				aurant at GF only)			
	Total numbers on ground floor	One	Provided	MR			
	 Length of hose reel hose 	30 mtrs	Provided	MR			
			D 11 1	MD			

7.	Automatic fire detection and alarming system					
	Type of detectors	Smoke & Heat	Provided	MR		
	 Location of Main Panel 	Required	G Floor	MR		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	Required	Provided	MR		
	 Hooters' Location 	Required	At exit	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Sprinkler System	IV/A		rant at GF only)		
	Basement	N/A	N/A	N/A		
	Ground Floor	Required	Provided	MR		
	Sprinkler above false ceiling	N/A	N/A			
11.	• Sprinkler above false ceiling N/A N/A N/A Internal Hydrants (Restaurant at GF only)					
	Size of riser/down-comer	100 mm	Provided	MR		
	r .	01 No.	Provided	MR		
	Transcor of my drames	01 No.	Provided			
	Hose Box	OT INO.	Provided	MR		
12.	Yard Hydrants					
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements	(1)	Common with a	atyam Complex)		
	Ground Level		Common with S	atyani Complex)		
	Discharge of main Pump	2280 LPM	Provided	MR		
	Head of Main pump	60 mtrs	Provided	MR		
	Number of main pumps	One	Provided	MR		
	Jockey Pump out put	1. TACAMPTOTO				
	Jockey pump head	220 LPM	Provided	MR		
	Standby Pump out put	60 mtrs	Provided	MR		
		2280 LPM	Provided	MR		
	Standby Pump Head	60 mtrs	Provided	MR		
	Auto Starting/Manual Stopping	Required	Provided	MR		
		N/A	N/A	N/A		
	> Pump House Access	11/11	IVA	11///		
	• Terrace level	27/4				
	Discharge of pump	N/A	N/A	N/A		
	> Head of the pump	N/A	N/A	N/A		
	> Power Supply	N/A	N/A	N/A		
	➤ Auto Starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	Required	90,000 ltrs	MR, being old case		
	> Draw-off connection	Required	Provided	MR		
	Fire service inlet					
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
			45000 ltrs	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.			rant at GF only)		
	Pressurization of Lift Shaft Pressurization of Lift Lift	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	• Communication In lift Car	Required	Provided	MR		
	• Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.	1				
	> Total Area	N/A	N/A	N/A		

	Fire Control Room	N/A	N/A	N/A
	Detector System Panel	N/A	N/A	N/A
 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 		N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
			N/A	N/A
20.	Special Fire Protection System for Protection of	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection and the shortcoming communicated by this department vide letter no. F.6/DFS/MS/EH/2017/SZ/2284 dated 04.09.2017 has been complied.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued F6/DFS/MS/EH/2014/SZ/1085 dated 28.08.2014, renewal/grant under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer Name: - M.K. Chattopadhyay

Designation:- Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

1085/200/20 1110118

special Risks, if any:

Dy. C.F.O.(South Zone)

miscell 4/x

F.T. letter is put up for signature please

OFO (SE) M. SCELL WY