

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No.F.6/DFS/MS/EH/2018/SZ/ 2151

Dated: 05/10/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Red Chilli (a unit of Red Chilli F & B Services), R-1, S-1, S-2, Westend Convention Point, Plot No. -15-16, District Centre, Janakpuri, New Delhi-110058, comprised of basement, ground plus three upper floors but restaurant is running at ground floor, was issued FSC by this department vide letter no. F.6/DFS/MS/EH/2013/712 dated 14.08.13 in the name & style of M/s Pind Balluchi-Grills & Platters (a unit of IKO Hospitality Pvt. Ltd.) now owned/occupied by M/s Red Chilli (a unit of Red Chilli F & B Services) was re-inspected by the officers concerned of this department on 27.09.2018 in the presence of Sh. Sanchit Sethi (Owner) and found that M/s Red Chilli (a unit of Red Chilli F & B Services) have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (**Ground floor Only**) is fit for occupancy class Group-D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....05/10/18..... at New Delhi.

VK 5/10.
(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

1. The Owner,
M/s Red Chilli (a unit of Red Chilli F & B Services), R-1, S-1, S-2, Westend Convention Point, Plot No. -15-16, District Centre, Janakpuri, New Delhi-110058
2. The Dy. Health Officer,
S.D.M.C, Public Health Department, West Zone,
Vishal Enclave, Rajouri Garden, New Delhi-110027
(D-1305/HD/WZ dated 23.05.2018)

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ado Jkr/nn

INSPECTION REPORT

1. Name & address of the building: M/s Red Chilli (a unit of Red Chilli F & B Services), R-1, S-1, S-2, Westend Convention Point, Plot No. -15-16, District Centre, Janakpuri, New Delhi-110058
2. Type of Occupancy : Group D (Assembly Building)
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/EH/2013/712 dated 14.08.13
5. Fire Safety directives letter No : N/A
6. Date of inspection : 27.09.2018
7. Name of Inspecting Officers : D.O M.K. Chattopadhyay & A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Sanchit Sethi (Owner)
9. Year of Construction : 2007
10. Applicant's letter No. : Nil dated 14.09.2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible (09 mtrs) 4.5 mtrs N/A	Provided Directly accessible from road N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits	(restaurant is running at GF)		
	a. Number of staircases			
	• Upper Floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper Floor	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	02 mtrs & 01 mtrs	200 & 182 cms	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System	(restaurant is running at GF)		
	• Basements	N/A	N/A	N/A
	• Upper floors	Required	Natural Ventilation	MR
5.	Fire Extinguishers			
	• Total numbers	06 No.'s	Provided	MR
	• Types	ABC/ CO ₂	Provided	MR
	• IS marking	ISI marked	ISI marked	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose reel hose	30 mtrs	Provided	MR
	• Nozzle diameter	5 mm	Provided	MR

7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement Ground Floor Sprinkler above false ceiling 	N/A	N/A	N/A
		N/A	Provided	N/A
		N/A	N/A	N/A
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants Hose Box 	100 mm	Provided	MR
		01 No.	Provided	MR
		01 No.	Provided	MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A	N/A	N/A
		N/A	N/A	N/A
13.	Pumping Arrangements	(common with S.K. Westend Convention Centre)		
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual Stopping 	2280 LPM	Provided	MR
		60 mtrs	Provided	MR
		One	Provided	MR
		180 LPM	Provided	MR
		60 mtrs	Provided	MR
		2280 LPM	Provided	MR
		60 mtrs	Provided	MR
		Required	Provided	MR
	<ul style="list-style-type: none"> Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A	N/A	N/A
		900 LPM	Provided	MR
		40 mtrs	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
14.	Captive Water Storage for fire fighting	(common with S.K. Westend Convention Centre)		
	<ul style="list-style-type: none"> Underground tank capacity <ul style="list-style-type: none"> Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	50,000 ltrs	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		15000 ltrs	25000 ltrs provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	(No Lift)		
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> Total Area Location 	N/A	N/A	N/A
		N/A	N/A	N/A

N/17

19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection and the shortcomings communicated by this department vide letter no. F.6/DFS/MS/EH/2018/SZ/3771 dated 06.09.2018 has been complied. ✓

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/712 dated 14.08.13, renewal/grant under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Note:- Earlier FSC was issued in the name & style M/s Pind Balluchi-Grills & Platters (a unit of IKO Hospitality Pvt. Ltd.) vide letter no. F.6/DFS/MS/EH/2013/712 dated 14.08.13. M/s S.K. Westend Convention Centre building in which aforementioned restaurant is situated has already been issued FSC by this department vide Letter No. F6/DFS/MS/2018/SZ/1981 dated 29.08.2018.

[Handwritten Signature]
11/10/18

Signature of Inspecting Officer
Name:- M.K. Chattopadhyay
Designation:- Divisional Officer

[Handwritten Signature]
28/9/18

Signature of Inspecting Officer
Name:- Sandeep Duggal
Designation:- Asstt. Divisional Officer

1122/DOSK
11/10/18

Dy. C.F.O. (South Zone)

[Handwritten Signature]

77/CF32
4/10/18

[Handwritten Signature]
1/10



CFo Sph MSCU

FT 10.

[Handwritten Signature]
4/10

F.T. letter is put up for signature pl.