GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School(2018/M02/2226

Dated: 3 /1 0/18

FIRE SAFETY CERTIFICATE

Certified that the EDMC Primary School running at ground floor only building comprised of ground plus one upper floor at Mayur Vihar, Ph-II, Pocket-F, Delhi, owned/occupied by EDMC Primary School was issued FSC vide letter No. F.6/DFS/MS/School/2014/NDZ/1483 Dated-28/11/14 (for ground floor only). The school building was inspected by the officer concerned of this department on 13/09/18 in the presence of Smt. Sunita Ghai (Principal) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular F16/Estate/CC/FireSafety/2011/3298 to 3398 dated 01/03/11 issued by Director of Education and the school building is fit for occupancy class "B" 'Educational Building' with effect from 3.1.0.1.8.... for a period of three years, subject to conditions, printed overleaf.

(Vipin Kental) Chief Fire Officer

To.

The Principal, EDMC Primary School, Mayur Vihar, Ph-II, Pocket-F, Delhi.

Copy to:-

 The Director of Education, EDMC, Udyog Sadan, Plot No. 419, FIE, Patparganj Industrial Area, Delhi-92.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form `J` [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

Defo NO2

9

1. Name & address of the building: EDMC Primary School, Mayur Vihar, Ph-II, Pocket-F,

Delhi.

2. Building is comprised of : G+1 floor school running at ground floor only

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous FSC : F.6/DFS/MS/School/2014/NDZ/1483 Dated-28/11/14

6. Fire Safety Circular No. : F.16/Estate/CC/FS/2011/3298 to 3398dt 01.03.2011

7. Date of Inspection : 15/09/18

8. Name of the Inspecting officers: ADO R.K.Yadav

9. Name and designation of

Officer from the building side : Smt. Sunita Ghai (Principal)

10. Year of Construction : 2002

11. Applicant's letter No : Dated 31/08/18

NO	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remarks			
1	Access to building						
	Road width	06 m	18 m	MR			
	Gate width	4.5 m	4.5 m	MR			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases			1.4.			
	Upper Floor	1no.	1 no.	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases						
	Upper Floor	1.5 m/N'	1.6 m	MR			
	 Basement 	N/A W	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases to	01 No.	01 No.	MR			
	terrace e. Width of Corridor	1.5 M	1.5 M	MR			
	f. Door Size	1.0 M	1.0 M	MR			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	 Water curtain 	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
5	Fire Extinguishers						
	Total numbers	4 Nos.	4 Nos.	MR			
	Types	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			

6	First-aid-Hose Reels. Total numbers of each floor	N/A	N/A	N/A				
	Length of hose reel hose Nozzle diameter	N/A	N/A	N/A				
		N/A	N/A	N/A				
7	Automotic fire detection and plarming eye							
	Automatic fire detection and alarming system.							
	 Type of detectors 	N/A	N/A	N/A				
	 Location of main panel 	N/A	N/A	N/A				
	 Location of repeater panel 	N/A	N/A	N/A				
	 Alternate source of power 	N/A	N/A	N/A				
	Hooter's location	N/A	N/A	N/A				
3	MOEFA	N/A	N/A	N/A				
3	Public address System.	N/A	N/A	N/A				
0	Automatic Sprinkler System.	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	upper floor	N/A	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A				
1	Internal Hydrants	N/A	N/A	N/A				
1	size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per floor	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
12	Yard Hydrants.	N/A	N/A	N/A				
1 Lan	Total number of hydrants	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
13	Pumping Arrangements.	N/A	N/A	N/A				
10	Ground Level	N/A	N/A	N/A				
	Discharge of main Pump .	N/A	N/A	N/A				
	Head of Main Pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	> Jockey pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A	N/A				
	> Standby pump Head	N/A	N/A	N/A				
	Auto Starting /Manual	N/A	N/A	N/A				
	stopping							
	Pump House Access	N/A	N/A	N/A				
	Terrace Level	N/A	N/A	N/A				
	Discharge of pump	N/A	N/A	N/A				
	> Head of the Pump	N/A	N/A	N/A				
	Power supply	N/A	N/A	N/A				
	> Auto Starting of pump	N/A	N/A	N/A				
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A				
	Underground tank capacity	N/A	N/A	N/A				
	> Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	N/A	N/A	N/A				
-	Access to tank	N/A	N/A	N/A				
	Overhead Tank capacity	N/A	N/A	N/A				
15	Exit Signage.	N/A	N/A	N/A				

16	Provision of Lifts.	N/A	N/A	N/A
FILE	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	 Firemen's grounding switch 	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	 Detector system panel 	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F.6/DFS/MS/School/2014/NDZ/1483 Dated-28/11/14 renew under the circular no. F.16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01.03.11 is recommended.

Signature of the InspectingOffice

Name:-R.K.Yadav Designation:-ADO (LN)

CF.P. MSEU FTM.
1019.
Sun FT heller as put up for signahme
Rocks

COUNTY MICCOLL W