## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Business/SZ/2018/ 2474

Dated: 2/11/18

## FIRE SAFETY CERTIFICATE

Certified that the Office Block (Tower-4), Kidwai Nagar(East) for GPRA, New Delhi-110023 comprises of three tier Basement, Ground & Four Upper Floors was inspected by the officer concerned of this department on 27/10/2018 in the presence of Sh. Mahaveer (Project Manager) and found that the said office block building (excluding basements) have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-B (Business)" with effect from -2/11-1----2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to:-

1. The Executive Engineer, (Bldg.), NDMC, Palika Kendra, New Delhi-110002.

2. Sh. N J Kaul, GM (Engg.), Project office- Redevelopment of Kidwai Nagar (East), Aurobindo Marg, Near Gate No.2 of INA Metro Station, Kidwai Nagar (East), New Delhi-110023

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form** 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry."
- 7. Basements underneath of Office Block-4 shall not be occupied or used till the receipt of its clearance/FSC from DFS as undertook by NBCC vide its letter no. NBCC/EKN-Office Block-4/GM-II/DFS/2018/1048 dated 24/08/2018.
- 8. NBCC shall ensure that internal layout/fire prevention & fire safety measures as and when carried out by the tenants/occupiers are in conformity with provision of UBBL/NBC as undertook by it vide letter no. NBCC/EKN-Office Block-4/GM-II/DFS/2018/1048 dated 24/08/2018 and plans of the same shall be submitted to this department on compliance for record.

## INSPECTION REPORT

1. Name& address of the building: Office Block (Tower-4), Kidwai Nagar(East) for GPRA, New Delhi

: Class-E "Business" 2. Type of Occupancy

: New [Office Block (Tower-4): 3 tier Basement\*, G. Floor+4Upper floors] 3. Type of Case

4. Details of Previous NOC : NA

5. Fire Safety directives letter No : F6/DFS/MS/BP/2013/196 dated 16/07/2013

: 27/10/2018 6. Date of inspection : A. K. Malik 7. Name of Inspecting Officer

8. Name and designation of officers

: Mr. Mahaveer (Project Manager) From the building side

9. Year of Construction : 2018

: Outdoor diary no. 15028 dated 16/10/2018 & dated 25/10/2018 10. Applicant's letter No.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
•	Access to building	All trans-					
	Road width	12m	12m	MR			
	Gate width	NA	NA	NA			
	Width of internal road	6m (Two side)	Provided	MR			
	Number, Width, Type & Arrangement						
	a. Number of staircases			****			
	Upper Floors	3 Nos	Provided	MR			
	Basements	NA*	NA	NA			
	b. Width of staircases	79		2			
		1.5m	2.3m, 1.5m & 1.5m	MR			
	Upper Floor	NA*	NA	NA			
	Basements						
	c. Protection of exits	Required	Provided	MR			
		Required	Natural Ventilation	MR			
	• Fire check door	2 Nos	Provided	MR			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	1 m	Provided (final exit)	MR			
	e. Width of Corridor f. Door Size	1111	, , , , , , , , , , , , , , , , , , , ,				
	1. Door Size						
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR			
		Required	Provided	MR			
	Fire Rating of shaft door	NA*	NA	NA			
	Water Curtain	Required	Provided	MR			
4	• Fire Dampers			1			
4.	Smoke Management System	NA*	NA	NA			
Commence Children Annahum Sometime (Annah	Basements			MR			
	Upper floors	12 a/c per hou		IVIK			
	Ventilation#						
5.	Fire Extinguishers	2021	Duranidad	MR			
	<ul> <li>Total numbers</li> </ul>	30 No's	Provided	MR			
	• Types	ABC/ W. CO <sub>2</sub> /C					
	IS marking	ISI	Yes	MR			
6.	First-Aid Hose Reels		D 11 1	MAD			
	Total numbers on each floor	Three	Provided	MR			
	Length of hose reel hose	30m	Provided	MR			
	Nozzle diameter	5mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	Type of detectors	Smoke & He		MR			
	Location of Main Panel	Ground Floo		MR			
	<ul> <li>Location of Repeater Panel</li> </ul>	-NA-	-NA-	-NA-			

	Alternate source of power	Required	Provided	Mix		
	Hooters' Location	All Area	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	Basement	NA*	NA	NA		
	<ul> <li>Ground &amp; Upper Floors</li> </ul>	Required	Provided	MR		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	NA#	NA	NA		
11.	Internal Hydrants	111211	1111	1111		
	Size of riser/down-comer	100mm	Provided	MR		
	Number of hydrants per floor	03Nos	Provided	MR		
	Hose Box	03Nos	Provided	MR		
12.	Yard Hydrants	05.105				
	Total number of hydrants	06 Nos	Provided	MR		
	Hose Box	06 Nos	Provided	MR		
13.	Pumping Arrangements	001103	Trovided	la a a a a a a a a a a a a a a a a a a		
	Ground Level [Common Pump Room at B-2 level]					
	Discharge of main Pump	2850LPM	2850LPM	MR		
	Head of Main pump	85m & 40m(WC)	Provided	MR		
	Number of main pumps	3Nos (one is for WC)	Provided	MR		
	> Jockey Pump out put.	2 of 280 LPM	Provided	MR		
	> Jockey pump head	85m	Provided Provided			
	<ul><li>Standby Pump out put</li></ul>	6 97	175	MR		
	Standby Pump Head	2850LPM	Provided	MR		
	> Auto Starting/Manual Stopping	85m	Provided	MR		
	<ul><li>Pump House Access</li></ul>	Required	Provided	MR		
	Tamp House Hooess	Required	Provided	MR		
	Terrace level					
	Discharge of pump	NA	NA :	NA		
	Head of the pump	NA	NA	NA		
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	NA	NA :	NA		
14.		NA	NA	NA		
14.	Captive Water Storage					
	• I Indonesia d touls	2 00 000 T	D 111	N.CD		
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	2,00,000 Lts	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
		Required	Provided	MR		
15	Overhead Tank capacity  Evit Singularity	20,000 Lts.	Provided	MR		
15.	Exit Signage	Required Provided# MR				
16.	Provision of Lifts					
	Pressurization of Lift labla.  Prossurization of Lift labla.	Required	Provided	MR		
	<ul><li>Pressurization of Lift lobby</li><li>Communication In lift Car</li></ul>	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	<ul> <li>Lift Signage</li> </ul>	Required	Provided	MR		
4=		Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area	,	4	,		
	Total Area	NA	NA	NA		
10	> Location	NA	NA	NA		
19.	Fire Control Room		-Entrance Lobby]			
	MOEFA System Panel	Required	Provided	MR		
	• Flow Switch Panel	Required	Provided	MR		
	PA System Panel	Required	Provided	MR		
	Battery backup     Puilding Floor Plans	Required	Provided	MR		
	Building Floor Plans	Required	Provided	MR		

Office Block (Tower-4), Kidwai Nagar (East) for GPRA, New Delhi

20 Special Fire Protection System for NA\* NA NA Protection of special Risks, if any:

## Note:-

- 1. The requirement of basement is not generated in the inspection note and are shown with\*, since applicant i.e. NBCC vide its letter no. NBCC/EKN-Office Block-4/GM-II/DFS/2018/1048 dated 24/08/2018 (C/15) undertook that Basements underneath of Office Block-4 shall not be occupied or used till the receipt of its clearance/FSC from
- 2. The compartmentation/segregation of basements with ground and upper floors found complied as undertook by NBCC at point no.2 of the letter mentioned above.
- 3. The smoke management system, sprinklers/detectors below false ceiling and other fire prevention & fire safety measures shall be executed by the tenants/occupiers as per NBC as undertook at point no. 3 of above letter and same are marked with # in the inspection
- 4. The request made by NBCC vide letter no. NBCC/EKN-Office Block-4/GM-I/DFS/2018/1404 dated 25/10/2018 (C/22) may be accepted by the competent authority as the existing exits meet the requirement as per NBC.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended under Rule 35(3) of the Delhi Fire Service Rules 2010 to grant Fire Safety Certificate under rule 35.

Accordingly form "H" in shape of DFA is put up for approval under Rule 35(4).

Signature of Inspecting Officer

Name: A. K. Malik Designation: Divisional Officer

Chig St Miscell PIBI's We 37/x
Shy Filis pulsep for be please.

006300