GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/BQNT/2018/SZ/ 2462

Dated: 01 11 18

FIRE SAFETY CERTIFICATE

Certified that the M/s Panchshila Rendezvous Banquet Hall (A Unit of Royal Eastern Hospitality Pvt. Ltd) at T-540/3, Corner Market, Maharishi Dayanand Marg, Malviya Nagar, New Delhi-110017, comprised of ground floor plus one temporary pucca construction at 1st floor was issued FSC by this department vide letter No. F6/DFS/MS/2016/SZ/175 dated 27/01/2016. The premise was re-inspected by officer concerned of this department on 18/10/2018 in the presence of Mr. Thomas (Maintenance In-charge) and found that building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-D Assembly" (Banquet Hall) with effect from of 1/11/2018 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on billing at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 911-23412225

Copy to:

1. Sh. Vyoum Ghai, M/s Panchshila Rendezvous Banquet Hall (A Unit of Royal Eastern Hospitality Pvt. Ltd) at T-540/3, Corner Market, Maharishi Dayanand Marg, Malviya Nagar, New Delhi-110017

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of DFS Rules, 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	INSPECTIO	ON REPORT			
1 N	ame & Address of the Building	M/s Panchshila	Rendezvous at T-540/2,	Corner Mkt,	
		Maharishi Dayanand Marg, Malviya Nagar, ND-17			
		(A Unit of Royal Eastern Hospitality Pvt. Ltd)			
2 T	ype of Occupancy	Assembly Building (Banquet Hall)			
3 B	uilding Comprised of	G+1 (Temporary Pucca construction and open terrace			
	ype of Case	Renewal	25		
	etails of Previous NOC	F6/DFS/MS/201	6/SZ/175 Dated 27-01-2	2016	
6 Fi	ire Safety Directives Letter No	Nil			
	eate of Inspection	18-10-2018		19	
	ame of the Inspecting Officers	Mehmood, ADO (SJ)			
9 N	fame & Designation of Officers	Mr. Thomas (Maintenance In-charge)			
	om the building side				
	ear of construction	2008			
	pplicant letter No.		o. 12945 dated 10-09-20		
S. No. M	Iinimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks	
	nd Fire Safety U/R 33	Requirement		MR/NMR	
1 A	ccess to Building.				
	 Road width 	9 mtr	18 mtr	MR	
	Gate width	5 mtr	5 mtr	MR	
	Width of internal road	-NA-	-NA-	-NA-	
2 N	lumber, width, type & arrangement of e			300 3000-301	
a		AILS.			
	> Upper floors.	02 Nos	Provided	MR	
	Basement floor.	-NA-	-NA-	-NA-	
1.		-11/7-	-11/1-	-1421	
b	> Upper floors	1.25m / 1m	1.25m & 1m	MR	
			-NA-	-NA-	
		-NA-	-NA-	-INA-	
c		214)) I A	NI A	
	Fire check door	-NA-	-NA-	-NA-	
	Pressurization	-NA-	-NA-	-NA-	
ď		Required	02 Nos	MR	
e) Width of corridor	-NA-	-NA-	-NA-	
f) Door size	-NA-	-NA-	-NA-	
3 C	Compartmentation.			1	
	 Fire check door. 	-NA-	-NA-	-NA-	
	 Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
	 Fire rating of shaft door. 	-NA-	-NA-	-NA-	
	 Water curtain 	-NA-	-NA-	-NA-	
	 Fire dampers. 	-NA-	-NA-	-NA-	
4 S	Smoke Management system.				
	 Basement 	30 ACPH	-NA-	-NA-	
	 Upper floors. 	12 ACPH	-NA-	-NA-	
5 F	Fire Extinguishers.				
	Total numbers	Required	20 Nos	MR	
	• Types	CO2/ABC	ABC, CO2 & W.CO2	MR	
	ISI Marking	ISI marked	Provided	MR	
6 F	First Aid Hose Reels.				
	Total numbers on each floor.	02 Nos	GF-02, FF-01	MR	
	 Length of hose-reel hose. 	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
	anchshila Rendezvous T_540/2 Corner M				

M/s Panchshila Rendezvous, T-540/2, Corner Mkt, Maharishi Dayanand Marg, Malviya Nagar, ND

7	Automatic fire detection & alarming system.			
	Type of detectors	-NA-	-NA-	-NA-
	 Location of Main Panel 	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8	MOEFA	Required	Provided	
9	Public Address System	-NA-	-NA-	MR
10	Automatic Sprinkler System	-11/1	-INA-	-NA-
	Basement	-NA-	-NA-	-NA-
	 Upper floors 	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	
11	Internal Hydrants.	-1471-	-INA-	-NA-
	Size of Riser/Down-comer	100 mm	Provided	MD
	Number of Hydrant per floor	02 Nos	Provided	MR
	Hose box.	02 Nos		MR
12	Yard Hydrants.	02 INOS	Provided	MR
	Total number of hydrants.	-NA-	-NA-	NT A
	Hose box.			-NA-
3		-NA-	-NA-	-NA-
	Pumping arrangements.			
	Ground Ecver			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump bead.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Terrace Level		6	5 a
	Discharge of pump.	900 LPM	900 LPM	MR
	Head of pump.	40m	40m	MR
	> Power supply.	Required	Provided	MR
4	Auto starting of pump.	Required	Provided	MR
4	Captive water storage for fire fighting.			
	Underground tank capacity.	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.Access to tank.	Required	Provided	MR
		-NA-	-NA-	-NA-
5	Overhead tank capacity. Exit Signs and tank capacity.	5,000 Ltr	Provided	MR
<u>5</u>	Exit Signage. Provision of Lifts.	Required	Provided	MR
0				
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	• Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
7	• Lift signage.	-NA-	-NA-	-NA-
7	Standby Power Supply	Required	Provided	MR
8	Refuge Area	•		
	Total area	-NA-	-NA-	-NA-
1	 Location 			

M/s Panchshila Rendezvous, T-540/2, Corner Mkt, Maharishi Dayanand Marg, Malviya Nagar, ND

19	Fire Control Room.		1	
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.Battery backup.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/2016/SZ/175 dated 27/01/2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Panchshila Rendezvous, T-540/2, Corner Mkt, Maharishi Dayanand Marg, Malviya Nagar, ND

DO (SD)

PANDON

29 (2000)

Ly cap (52)

Land

28/10

G0 874 V

m.scell

1-7 MI,

159 Go | 52 RO 10 18/1/11

J. R. J. Lethic

for my

Jan &

3 NIII

CPV (\$23)

miscell W