GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2018/SZ/ 249 6

Dated: 8-11-1-1-9

FIRE SAFETY CERTIFICATE

Certified that M/s Bamyan the Boutique Guest House located at 6–A, Ring Road, Lajpat Nagar-IV, New Delhi-110024, comprised of Basement (Storage only), Ground floor (Rec., dining hall & 03 guest rooms), 1st Floor (06 guest rooms), 2nd Floor (06 guest rooms) and 3rd Floor (06 guest rooms) was issued FSC by this department vide letter No. F6/DFS/MS/GH/2015/SZ/1933 dated 28/10/2015. The premise was re-inspected by officer concerned of this department on 11/10/2018 in the presence of Sh. Bhupinder Singh Sethi (Prop.) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "Residential, Group-A" (Lodging & Rooming House) as above with effect from Solved and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 8 11 8 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph: 011-23412225

Copy to: -

- 1. Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049
- 2. M/s Bamyan the Boutique Hotel at 6-A, Ring Road, Lajpat Nagar-IV, New Delhi-110024

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	INSPECTIO			300	
1	Name & Address of the Building	M/s Bamyan The Boutique Hotel at 6–A, Ring Road, Lajpat Nagar-IV, New Delhi-110024			
2	Type of Occupancy	Group-A (Lodging or Rooming House)			
3	Type of Occupancy	Basement, Ground + 03 upper floors.			
	Building Comprised of	Renewal			
5	Type of Case Details of Previous NOC	F.6/DFS/MS/GH/2015/SZ/1933 dated 28-10-2015			
6	Fire Safety Directives Letter No				
7	Date of Inspection	Nil 11-10-2018			
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)			
9	Name & Designation of Officers	Mr. Bhupender Singh Sethi (Prop.)			
9	from the building side	Wir. Bittperider Singh Setti (110p.)			
10	Year of construction	2004 Basement (storage), Gd. floor (Rec., Dining Hall + 03 guest room), 1 st floor to 3 rd floor (0 guest rooms each) Total-19 Guest Rooms			
11	Applicant letter No.	Outdoor diary No. 13845 dated 26-09-2018			
S. No.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks	
	and Fire Safety U/R 33	requirements		MR/NMR	
1	Access to Building.				
	Road width	09 mtr	Provided	MR	
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.		A		
	a) Number of Staircase				
	Upper floors.	01 No	Provided	MR	
	➤ Basement floor.	02 Nos	Provided	MR	
	b) Width of Staircase				
	> Upper floors	1.25 mtr	1.30m	MR	
	Basement floor	1.25 mtr	1.30m & 1.15m	MR	
		1.25 IIII	1.5011 & 1.15111	IVIIC	
	c) Protection of exits	NT A	-NA-	-NA-	
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization		Provided	MR	
	d) No. of continuous staircase to terrace	One	-NA-	-NA-	
	e) Width of corridor	-NA-	1.05m (final exit)	MR	
	f) Door size	1m	1.03III (IIIIai exit)	IVIIX	
3	Compartmentation.	-NA-	-NA-	-NA-	
	• Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts. Fire patients of the first are a first and the first are a first and the first are a first are a first and the first are a first are a first are a first and the first are a f	-NA-	-NA-	-NA-	
	• Fire rating of shaft door.			-NA-	
		_N A	_N A _	-14/7	
	Water curtain	-NA-	-NA-	1	
	Water curtainFire dampers.	-NA-	-NA-	-NA-	
4	 Water curtain Fire dampers. Smoke Management system.	-NA-	-NA-	-NA-	
4	 Water curtain Fire dampers. Smoke Management system. Basement 	-NA- 30 ACPH	-NA- Exhaust fan provided	-NA-	
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors 	-NA-	-NA-	-NA-	
4 5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. 	-NA- 30 ACPH 12 ACPH	-NA- Exhaust fan provided Natural Ventilation	MR MR	
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors 	-NA- 30 ACPH 12 ACPH Required	-NA- Exhaust fan provided Natural Ventilation 12 Nos	MR MR MR	
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. 	-NA- 30 ACPH 12 ACPH Required ABC / CO2	-NA- Exhaust fan provided Natural Ventilation 12 Nos CO2 & ABC	MR MR MR MR	
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	-NA- 30 ACPH 12 ACPH Required	-NA- Exhaust fan provided Natural Ventilation 12 Nos	MR MR MR	
	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types 	-NA- 30 ACPH 12 ACPH Required ABC / CO2	-NA- Exhaust fan provided Natural Ventilation 12 Nos CO2 & ABC Provided	MR MR MR MR MR	
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	-NA- 30 ACPH 12 ACPH Required ABC / CO2	-NA- Exhaust fan provided Natural Ventilation 12 Nos CO2 & ABC	MR MR MR MR	
5	 Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. 	-NA- 30 ACPH 12 ACPH Required ABC / CO2 ISI marked	-NA- Exhaust fan provided Natural Ventilation 12 Nos CO2 & ABC Provided	MR MR MR MR MR	

M/s Bamyan the Boutique Hotel at 6-A, Ring Road, Lajpat Nagar-IV, New Delhi-110024

7 A	utomatic fire detection & alarming system.			100
7 21	Type of detectors	Required	Smoke type	MR
	Location of Main Panel	Required	Ground floor	MR
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	Required	Battery backup	MR
	Hooter's location	Required	Stairs	MR
8. N	MOEFA	Required	Provided	MR
	Public Address System	Required	Provided	MR
	Automatic Sprinkler System			
10.	Basement	Required	Provided	MR
	Upper floors	-NA-	Provided	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11 T	nternal Hydrants.			
11. I	a: cp: /p	-NA-	100 mm	-NA-
	27 1 CII 1 4 floor	-NA-	01	-NA-
	xx 1	-NA-	01	-NA-
10 3		2.12		
12. Y	Yard Hydrants. Total number of hydrants.	-NA-	-NA-	-NA-
5	•	-NA-	-NA-	-NA-
10	Hose box.	11/1		
13. I	Pumping arrangements.			
_	Ground Level	-NA-	-NA-	-NA-
	Discharge of main pump.	-NA-	-NA-	-NA-
	> Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.Jockey Pump head.	-NA-	-NA-	-NA-
Els.	Jockey Pump head.Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump bead.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
_	*	-INA-	1411	
	• Terrace Level	900 LPM	450 LPM (02 Nos)	MR
	Discharge of pump.Head of pump.	40m	Provided	MR
		Required	Provided	MR
	Power supply.Auto starting of pump.	Required	Provided	MR
		Required	1101101	
14.	Captive water storage for fire fighting.	-NA-	25,000 Ltr	-NA-
	 Underground tank capacity. Draw-off connection. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		10,000 Lts	10,000 Lts	MR
1-	Overhead tank capacity. Fig. 4. Signature	Required	Provided	MR
15.	Exit Signage.	Required	1 220000	
16.	• Pressurization of lift shaft.	-NA-	-NA-	-NA
		-NA-	-NA-	-NA-
	Pressurization of lift lobby. Communication in lift con.	Required	Provided	MR
	Communication in lift car. The second of the second	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17.	Standby Power Supply	Required	TTOVICCU	14114
18.	Refuge Area	NT A	-NA-	-NA
	Total area	-NA-		-NA
	 Location 	-NA-	-NA-	-INA

M/s Bamyan the Boutique Hotel at 6-A, Ring Road, Lajpat Nagar-IV, New Delhi-110024

19.	Fire Control Room.			-
	Detector system panel.	-NA-	-NA-	-NA-
	• Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/GH/2015/SZ/1933 dated 28-10-2015, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Bamyan the Boutique Hotel at 6-A, Ring Road, Lajpat Nagar-IV, New Delhi-110024