## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Business/SZ/2018/ 2557

Dated: 2 6/11/18

## FIRE SAFETY CERTIFICATE

Certified that the Basement under Office Blocks (1, 2, 3 & 4) for GPRA, New Delhi-110023 comprises of Three tiers i.e. Basement-1, Basement-2 & Basement-3 was inspected by the officer concerned of this department on 15/11/2018 in the presence of Sh. Mahaveer (Project Manager) and found that the said Basement have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-E [Business (car parking) incidental occupancy of towers]" with effect from 26 ft 2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

010 ±

Copy to:-

1. The Executive Engineer, (Bldg.), NDMC, Palika Kendra, New Delhi-110002:

2. Sh. A K Sharma, GM (Engg.), Project office- Redevelopment of Kidwai Nagar (East), Aurobindo Marg, Near INA Metro Station, Kidwai Nagar (East), New Delhi-110023

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration **every year** in **Form** '**K**' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form** 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT 1. Name& address of the building: Basement (1,2 & 3) under Office Blocks (1, 2, 3 & 4), Kidwai Nagar : Class-E "Business [(car parking) incidental occupancy of towers)]" (East) for GPRA, New Delhi Type of Occupancy : New [3 tier Basement] 3. Type of Case : NA 4. Details of Previous NOC 5. Fire Safety directives letter No : F6/DFS/MS/BP/2013/01 dated 02/01/2014 : 15/11/2018 6. Date of inspection 7. Name of Inspecting Officer : A. K. Malik 8. Name and designation of officers : Mr. Mahaveer (Project Manager) From the building side : 2018 9. Year of Construction : Outdoor diary no. 15844 dated 30/10/2018 Remarks 10. Applicant's letter No. Provided at site BBL/NBC Minimum Standards on fire prevention and MR/NMR S. No. Requirement fire safety U/R 33 MR Access to building 12m 1. 12m NA NA Road width NA MR Provided Gate width 6m (Three side) Width of internal road Number, Width, Type & Arrangement 2. a. Number of staircases NA NA NA Upper Floors B3 to B2: 12 Nos MR Provided B2 to B1: 12 Nos Basements B1 to GF:14 Nos NA b. Width of staircases NA NA Upper Floor B3 to B2: 1.51m, 2.4m, 1.5m, 1.5m, 1.5m, 2.4m, 1.5m, 1.5m, 2.39m, 1.51m, 1.5m & 2.4m B2 to B1: 1.51m, 2.4m, 1.5m, 1.5m, 1.5m, 2.4m, 1.5m, MR 1.5m, 2.39m, 1.51m, 1.5m 1.5m & 2.4m Basements B1 to GF: 1.51m, 2.4m, 1.5m, 1.5m, 1.5m, 2.4m, 1.5m, 1.5m, 2.39m, 1.51m, 1.5m, 2.4m, 1.5m & 1.98m MR c. Protection of exits Provided Required MR Fire check door Provided Required Pressurization NA NA d. No. of continuous staircases to terrace NA NA NA NA e. Width of Corridor MR Provided 1m f. Door Size Compartmentation MR Provided 3. Required Fire check door MR Provided Required Sealing of electrical shafts MR Provided Required Fire Rating of shaft door MR Provided Required Water Curtain NA NA NA Fire Dampers Smoke Management System MR Provided 4. 30 ACPH NA Basements NA NA Upper floors

	Fire Ext	tinguishers			MD	
		Total numbers	Required	80 Nos	MR	
		Гуреѕ	ABC/ W. CO <sub>2</sub> /CO <sub>2</sub>	30/30/20	MR	
		IS marking	Required	Provided	MR	
ó.		d Hose Reels	12 Nos	Provided	MR	
-		Total numbers on each floor	12 Nos	Provided	MR	
		Length of hose reel hose	30m	Provided	MR	
		Nozzle diameter	5mm	Provided	IVIIX	
		atic fire detection and alarming system	Smoke & Heat	Provided	MR	
		Type of detectors	Ground Floor	Provided	MR	
		Location of Main Panel	NA NA	NA	NA	
		Location of Repeater Panel Alternate source of power	Required	Provided	MR	
	•	Hooters' Location	All Area	Provided	MR	
		Hooters Location		Provided	MR	
3.	MOEF	A	Required		MR	
).	Public	Address System	Required	Provided	IVIK	
0.		atic Sprinkler System		Provided	MR	
-	•	Basement	Required	Provided	MR	
	•	Ground & Upper Floors	Required		NA	
	•	Sprinkler above false ceiling	NA	NA	INF	
11.	Intern	al Hydrants	100	Provided	MR	
	•	Size of riser/down-comer	100mm	Provided	MR	
	•	Number of hydrants per floor	12Nos		MR	
	•	Hose Box	12Nos	Provided	IVIIX	
12.	Yard	Hydrants	06.21	Provided	MR	
	•	Total number of hydrants	06 Nos	Provided	MR	
	•	Hose Box	06 Nos	Provided	IVIIX	
13.	Pumping Arrangements  [Common Pump Room at B-2 level]					
		Ground Level	2850LPM	2850LPM	MR	
	16	Discharge of main Pump		Provided	MR	
		<ul><li>Head of Main pump</li></ul>	85m & 40m(WC)	Provided	MR	
		Number of main pumps	3Nos (one is for WC)	Provided	MR	
		> Jockey Pump out put	2 of 280 LPM	Provided	MR	
		Jockey pump head	85m .	Provided	MR	
		> Standby Pump out put	2850LPM	Provided	MR	
		> Standby Pump Head	85m		MR	
		Auto Starting/Manual Stopping	Required	Provided	MR	
		> Pump House Access	Required	Provided	IVIIC	
	•	Terrace level		NT A	NA	
		Discharge of pump	NA	NA NA	NA NA	
		> Head of the pump	NA	NA NA	NA	
		> Power Supply	NA NA	NA	NA	
4.4	Auto Starting of pump  Captive Water Storage		(Common with other Bolls.)			
14.	Сар	uve water Storage	(camman	44.7		
		• Underground tank capacity	2,00,000 Lts	Provided	MR	
		> Draw-off connection	Required	Provided	MR	
		Fire service inlet	Required	Provided	MR	
		Access to tank	Required	Provided	MR	
		Overhead Tank capacity	20,000 Lts.	Provided	MR	
1.5			Required	Provided	MR	
15.	Provision of Lifts					
10.	FIO	Pressurization of Lift Shaft	Required	Provided	MR	
		<ul> <li>Pressurization of Lift lobby</li> </ul>	Required	Provided	MR	
		• Communication In lift Car	Required	Provided	MR	
		Eiropan's Grounding Switch	Paguired	Provided	MR	

Basement (1,2 & 3) under Office Blocks (1, 2, 3 & 4), Kidwai Nagar (East) for GPRA, New Delhi

	Lift Signage	Required	Provided	Brak			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area						
	> Total Area	NA	NA	NA			
	Location	NA	NA	NA			
19.	Fire Control Room						
	<ul><li>MOEFA System Panel</li><li>Flow Switch Panel</li></ul>	Required	Provided	MR			
		Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	<ul><li>Battery backup</li><li>Building Floor Plans</li></ul>	Required	Provided	MR			
		Required	Provided	MR			
20.	Special Fire Protection System for Protection of special Risks, if any of Residential Blocks (No. 10, 11 & 12):	Required	Inert Gas Flooding system provided in HT & LT panels				

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly form "H" in shape of DFA under Rule 35(4) is put up for approval.

Signature of Inspecting Officer

Name: A. K. Malik Designation: Divisional Officer

Dy. CFO (SZ)

Choksy

m-scell

FID.

Will PI

Fir f. T. is Joulup for St. plean,

ANG CROISE

Do (SD)

Miscell Gely



26/11