GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Residential/SZ/2018/ 2554

Dated: 26/11/18

FIRE SAFETY CERTIFICATE

Certified that the **Residential Block No. 22-Type III Quarters** situated at Kidwai Nagar (East) for GPRA, New Delhi-110023, comprises of two tier Basement, Ground & Twelve Upper Floors was inspected by the officer concerned of this department on 15/11/2018 in the presence of Sh. Mahaveer (Project Manager) and found that the said residential building blocks (**excluding basements**) have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-A (Residential)" with effect from -2-(-)+-)--2018 for a period of five years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on......at New Delhi by.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to:-

1. The Executive Engineer, (Bldg.), NDMC, Palika Kendra, New Delhi-110002.

2. Sh. A K Sharma, GM (Engg.), Project office- Redevelopment of Kidwai Nagar (East), Aurobindo Marg, Near INA Metro Station, Kidwai Nagar (East), New Delhi-110023

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 7. Basements underneath of these Residential Blocks shall not be occupied or used till the receipt of its clearance/FSC from DFS as undertook by NBCC vide its letter no. NBCC/EKN-Type V/CGM/DFS/2018/1405 dated 25/10/2018.

Type III Quarters at Klawai Nagar (East), New Delhi INSPECTION REPORT 1. Name& address of the building: Residential Block No. 22-Type III Quarters at Kidwai Nagar (East), New Delhi 2. Type of Occupancy Class-A "Residential" 3. Type of Case Block 22: 2 tier Basement, G. Floor + 12Upper floors New 4. Details of Previous NOC : NA 5. Fire Safety directives letter No : F6/DFS/MS/BP/2013/01 dated 02/01/2014 6. Date of inspection : 15/11/2018 7. Name of Inspecting Officer : A. K. Malik 8. Name and designation of officers From the building side : Mr. Mahaveer (Project Manager) 9. Year of Construction : 2018 10. Applicant's letter No. : Outdoor diary dated 09/11/2018 Minimum Standards on fire prevention and BBL/NBC Provided at site Remarks fire safety U/R 33 Requirement MR/NMR 1. Access to building Road width 12m 12m MR Gate width -NA--NA--NA-Width of internal road 6m (Two side) Provided MR 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 2 Nos Provided MR Basements -NA-* -NA--NAb. Width of staircases Upper Floor 1.35m# 1.44m & 1.45m MR Basements -NA-* -NA--NAc. Protection of exits Fire check door Required Provided MR Pressurization Required Natural Ventilation MR d. No. of continuous staircases to terrace 2 Nos Provided MR Width of Corridor -NA--NA--NAf. Door Size 1m Provided (final exit). MR 3. Compartmentation Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door Required Provided MR Water Curtain -NA--NA-Fire Dampers -NA--NA--NA--NA-4. Smoke Management System Basements -NA-* -NA--NA- Upper floors 12 a/c per hour Natural Ventilation MR 5. Fire Extinguishers Total numbers 30 No's 30 No's MR Types ABC/ W. CO₂/CO₂ 15/15/-- No's MR IS marking ISI Yes MR 6. First-Aid Hose Reels Total numbers on each floor One Provided MR Length of hose reel hose 30m Provided MR Nozzle diameter 5mm Provided MR 7. Automatic fire detection and alarming system Type of detectors -NA--NA--NA-Location of Main Panel -NA--NA-Location of Repeater Panel -NA--NA--NA-Alternate source of power -NA--NA-Hooters' Location -NA--NA--NA--NA--NA-MOFFA

9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		*	
	Basement	-NA-*	-NA-	-NA-
	Ground Floor	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11.	Internal Hydrants			
5	Size of riser/down-comer	100mm	Provided	MR
	 Number of hydrants per floor 	. 01Nos	Provided	MR
9	Hose Box	01Nos	Provided	MR
12.	Yard Hydrants			Y
	Total number of hydrants	01 Nos	Provided	MR
	Hose Box	01 Nos	Provided	MR
13.	Pumping Arrangement		1	
	Ground Level [Common Pump Room at B-2 level]			
		Hydrant &	Hydrant &	MR
	Discharge of main Pump	Sprinkler (H&S): 2850LPM (each) Water Curtain (WC): 2 of 2280 LPM	Sprinkler (H&S): 2850LPM (each) Water Curtain (WC): 2 of 2850 LPM	
	Head of Main pump	(H&S):90m(each) (WC): 45m (each)	Provided	MR
	Number of main pumpsJockey Pump out put	4Nos	Provided	MR
	Jockey Pump out putJockey pump head	2 of 280 LPM	2 of 450 LPM	MR
	Standby Pump out put	(H&S):90m&60m	Provided	MR
	Standby Pump Head	2850LPM	Provided	MR
	Auto Starting/Manual Stopping	90m	Provided	MR
	Pump House Access	Required	Provided	MR
	T diffp House Heeess	Required	Provided	MR
	Terrace level			
	Discharge of pump	-NA-	-NA-	-NA-
	Head of the pump	-NA-	-NA- ';	-NA-
42	Power Supply	-NA-	-NA-	-NA-
	Auto Starting of pump	-NA-	-NA-	-NA-
14.	Captive Water Storage for firefighting			
	 Underground tank capacity 	2,00,000 Lts	Provided	MR
	> Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	10,000 Lts.	Provided	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	Required	Natural Ventilation	MR
	 Communication In lift Car 	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.				
	> Total Area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19.	Fire Control Room		1	
	MOEFA System Panel	Required	Provided	MR
	Flow Switch Panel	-NA-	-NA-	-NA-
	PA System Panel	Required	Provided	MR
	Battery backup	Required	Provided	MR

Residential Block No. 22-Type III Quarters at Kidwai Nagar (East), New Delhi **Building Floor Plans** Required Provided Special Fire Protection System for -NA-* -NA-Protection of special Risks, if any of

Residential Blocks (No. 1 & 23): Note:-

20.

- 1. The requirement of basement is not generated in the inspection note and is shown with*, applicant i.e. **NBCC** vide its letter no. NBCC/EKN-Type II&III/GM/DFS/2018/1403 dated 25/10/2018 (C/50) undertook that Basements underneath shall not be occupied or used till the receipt of its clearance/FSC from DFS.
- 2. The basement-3 beneath the Block-22 is not constructed and only 12 upper floors are constructed by NBCC against the approved 3 tier basement & 14 upper floors as submitted by NBCC vide letter no. NBCC/EKN-Type-III/GM/DFS/2018/741 dated 12/06/2018 (C/36). This is not affecting the fire prevention & fire safety measures of the building/premise. Thus the same may be accepted by competent authority.
- 3. The compartmentation/segregation of basements with ground and upper floors found complied as undertook by NBCC at point no.2 of the letter mentioned above.

4. #The staircase width of 1.35m already approved on Type-II file N/11&12, in conformity with Clause 7.11.1(a) of UBBL-2016.

The Shortcomings observed during the last inspection of 31/10/2018 (N/7) found complied. The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35(3) of the Delhi Fire Service Rules

Accordingly form "H" in shape of DFA is put up for approval under rule 35(4)

Signature of Inspecting Officer Name: A. K. Malik

MR

-NA-

Designation: Divisional Officer

o. St. M. scell FTA M. 27/8/.
Gr. F. T. is Jandup for Sis. please

m.scell