GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

No.F.6/DFS/MS/School/2018/SZ/

2539

Dated:

19/11/18

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C. Pratibha Vidyalaya**, Site-IV, Vikas Puri, New Delhi-110018 comprised of ground floor plus two upper floors, owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2015/SZ/764 dated 14.05.15. The School building was re-inspected by the officer concerned of this department on 23.10.2018 in the presence of Sh. Kartar Singh (Attendant) and found that S.D.M.C. Pratibha Vidyalaya have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on /9///// at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal,
 S.D.M.C. Pratibha Vidyalaya,
 Site-IV, Vikas Puri, New Delhi-110018
- 2. Director of Education, S.D.M.C, Civic Centre, Minto Road, New Delhi-110001

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT S.D.M.C. Pratibha Vidyalaya, Site-IV, Vikas Puri, New Delhi-110018 1. Name & address of the building: Type of Occupancy Educational Renewal 3. Type of Case F.6/DFS/MS/School/2015/SZ/764 dated 14.05.15 4. Details of Previous NOC N/A 5. Fire Safety directives letter No 23.10.2018 6. Date of inspection A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers Sh. Kartar Singh (Attendant) From the building side 9. Year of Construction 2013 Email letter dated 22.09.2018 10. Applicant's letter No. Remarks Provided at Requirements Minimum Standards on fire prevention and S. No. MR/NMR as per FSC dt. site fire safety U/R 33 14.05.15 1. Access to building M/R Provided 06 mtrs. Road width Directly accessible M/R 4.5 mtrs. Gate width from road N/A N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases M/R 03 No.'s Upper Floors 02 No.'s N/A Basements N/A N/A b. Width of staircases M/R 152, 175 & 122 150 cms Upper Floor cms Basements N/A N/A N/A c. Protection of exits N/A Fire check door N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to M/R One Required terrace M/R 181 cms 150 cms. Width of Corridor 117 cms M/R 100 cms Class Room Door Size (double door) Compartmentation 3. N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural ventilation M/R Required Upper floors provided Fire Extinguishers 5. MR Provided 07 no's Total numbers ABC/CO₂ type MR Provided Types MR Provided IS marking ISI marked First-Aid Hose Reels 6. MR Provided One Total numbers on each floor MR Provided 30 mtrs Length of hose reel hose Provided MR 5 mm Nozzle diameter

7.	Automatic fire detection and alarming system			
7	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	 Basement 	N/A	N/A	N/A
	 Ground Floor 	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			And the second s
9	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	100 000000 200		
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	11/12		
	Ground Level Discharge of main Rump	DI/A	N/A	N/A
	Discharge of main PumpHead of Main pump	N/A		
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	11/11	1772	
	Terrace level	450 LPM	Provided	MR
	Discharge of pump		Provided	MR
	Head of the pump	40 mtrs Required	Provided	MR
	Power SupplyAuto Starting of pump	Required	Provided	MR
	Auto Starting of pump	Required	Trovided	1411
14.	Captive Water Storage for fire fighting			The second secon
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	Provided	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10000 ltrs	Provided	MR
15	Evit Signaga	Required	Provided	MR
15.	Exit Signage.	Required	Tiovided	4744
16.	Provision of Lifts.		No Li	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
1/.	Standby power suppry	1 1/2 1		
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
l	> Location			1 X 1 1 1 6 2 1 1

10/8

19.	Fire Control Room					
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2015/SZ/764_dated_14.05.15_renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

1135 DOCSW)
30/12018

Divisional Officer (South West)

20/× (18

SHOP FINE CREEK

Go G

May 7

miscell FTM.

F. T. lefter to put up for signature of

M. SOU W