GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2018/ 26/2

Dated: 1.1.2.1.18

FIRE SAFETY CERTIFICATE

Issued on 4/11/18 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. M/s Monkey Bar restaurant, Plot No-11, Local Shopping Center, Pocket C- 6 & 7, Vasant Kunj, New Delhi-110070
- 2. DHO (SZ), South MCD, Health Department, Aurobindo Marg, Green Park, New Delhi-70.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

			ON REPORT			
1	Nar	ne & Address of the Building		located at Plot No-11, Lo		
			Shopping Center, Pocket C-6 & 7, Vasant Kunj, New Delhi-70			
2	Typ	be of Occupancy	Assembly Buildin	ng, "Group-D" Restaurar	nt	
3	Building Comprised of		Basements, Ground + Two upper floor. (Restaurant			
			running at ground, first and second floor)			
4		be of Case	Renewal			
5		ails of Previous NOC	F6/DFS/MS/EH/2013/316 dated 18-01-2013			
6		e Safety Directives Letter No	F6/MS/DFS/BP/2003/2347 dated 01-10-2003			
7		te of Inspection	14-11-2018			
8		me of the Inspecting Officers	Mehmood, ADO (SJ)			
9		me & Designation of Officers	Mr. Azim			
1.0		m the building side	2005			
10		ar of construction		a 15707 detect 20 10 20	1 Ω	
11		plicant letter No. nimum standards on Fire Prevention	Outdoor Diary No. 15797 dated 29.10.2018 Old NOC Provided at Site Remarks			
S. No.			requirements	Flovided at Site	MR/NMI	
1		d Fire Safety U/R 33	requirements		THEOTHER	
1	AC	cess to Building. Road width	9 mtr	Provided	MR	
		Gate width	-NA-	-NA-	-NA-	
		Width of internal road	-NA-	-NA-	-NA-	
2	N	mber, width, type & arrangement of ex		141		
4		Number of Staircase	AICS.			
	a)	> Upper floors.	2 Nos	2 Nos	MR	
		Basement floor.	2 Nos	2 Nos	MR	
		THE CONTRACTOR OF THE PROPERTY	2 1105	2 1403	IVIIC	
	b)	Width of Staircase	1.5m	1.5m & 60 cm	MR	
		> Upper floors				
		> Basement floor	1.5m	1.25m & 1m	MR	
	c)	Protection of exits		D 11.1) (D	
		Fire check door	Required	Provided	MR	
		Pressurization	-NA-	-NA-	-NA-	
	d)	No. of continuous staircase to terrace	-NA-	-NA-	-NA-	
	e)	Width of corridor	-NA-	-NA-	-NA-	
	f)	Door size	2m	Provided	MR	
3	Co	mpartmentation.		n z _a e		
		 Fire check door. 	Required	Provided	MR	
		 Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
		• Fire rating of shaft door.	-NA-	-NA-	-NA-	
		Water curtain	-NA-	-NA-	-NA-	
		Fire dampers.	-NA-	-NA-	-NA-	
4.	Sn	noke Management system.		T 1 . C . '1 1	MD	
		Basement	30 ACPH	Exhaust fan provided	MR	
		Upper floors	12 ACPH	Exhaust fan provided	MR	
5.	Fi	re Extinguishers.				
		Total numbers	10 Nos	Provided	MR	
		• Types	ABC,	Provided	MR	
	14	ISI Marking	Co2,Foam	Provided	IVIK	
		- 101 Islanding	ISI marked	Provided	MR	
6.	IIT:	rst Aid Hose Reels.				
0.	1.1	Total numbers on each floor.	01	Provided	MR	
			30 mtr	Provided	MR	
		• Length of hose-reel hose.		Provided	MR	
		Nozzle Diameter	5 mm	Provided		

M/S Monkey Bar located at Plot No-11, Local Shopping Center, Pocket C-6 & 7, Vasant Kunj, New Delhi

7	Automatic fire detection & alarming system.		-	
,	Type of detectors	Smoke	Provided	MR
	Location of Main Panel	Ground Floor	Provided	MR
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	Every Floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	required	110/100	
_	Basement	Required	Provided	MR
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.	1111	- 11.1	
11.	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12.	Yard Hydrants.	One	TTOVIGEG	14117
14.	• Total number of hydrants.	Required	Provided	MR
		Required	Provided	MR
12		Required	riovided	NIV
13.	Pumping arrangements.	0		
	• Ground Level	2050 / D) /	D) (D
	Discharge of main pump.	2850 LPM	Provided	MR
	> Head of main pump.	60m	Provided	MR
	Number of main pumps.Jockey Pump output.	01	Provided	MR
	Jockey Pump output.Jockey Pump head.	180 LPM	Provided	MR
	Standby Pump output.	60m	Provided	MR
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	Required	Provided	MR
d	•	Required	Provided	MR
	Terrace Level	D.T.A.	DIA .	NIA
	Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	Power supply.Auto starting of pump.	-NA-	-NA-	-NA-
1.4		-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.	1 00 000 14	Duavidad	MR
	Underground tank capacity.	1,00,000 Ltr	Provided Provided	MR
	Draw-off connection.Fire Service Inlet.	Required	Provided	MR
	Fire Service Inlet.Access to tank.	Required	Provided	MR
		Required -NA-	-NA-	-NA-
15.	Overhead tank capacity. Exit Signage.	-NA- Required	Provided	MR
	Exit Signage. Provision of Lifts.	Required	Tiovided	IVIIX
16.		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car. Figure 2.2 a writch	-NA-	-NA-	-NA-
	• Fireman's switch.			
4.00	• Lift signage.	-NA-	-NA-	-NA-
17.	Standby Power Supply	Required	Provided	MR
18.	Refuge Area	374	NTA	TA T A
	Total area	-NA-	-NA-	-NA-
	 Location 	-NA-	-NA-	-NA-

M/s Monkey Bar located at Plot No-11, Local Shopping Center, Pocket C-6 & 7, Vasant Kunj, New Delhi

19.	Fire Control Room.		Λ	
	Detector system panel.	-NA-	-NA-	-NA-
	• Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the	-NA-	-NA-	-NA-
	Protection of special Risk, if any.			

The fire protection system provided in the building/ premises were tested, checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/316 dated 18/01/2013, renewal under rule 35 of the Delhi Fire Service Rules 2010, is recommended.

Accordingly DFA is put up for approval and signature please.

X

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Monkey Bar located at Plot No-11, Local Shopping Center, Pocket C-6 & 7, Vasant Kunj, New Delhi

DO (SB) (16/11/18)

Rycho (52)

SINE SEPLICA

12 Pho15 212

18/4

form miscell

4 22/X1.

+ F.t. Lahri but up d

(601821)

miscell 49/1