GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ 17

Dated: 4/12/18

FIRE SAFETY CERTIFICATE

Certified that the **SDMC Primary School,** Uttam Nagar New No.-I/II, K-Block, Santosh Park, Uttam Nagar, New Delhi-110059, comprised of ground floor plus two upper floors, having total 28 rooms (including Class rooms, Science Lab, Computer Lab, Sports rooms, Staff room & Offices etc.) owned/occupied by SDMC was inspected by the officer concerned of this department on 16.11.2018 in the presence of Sh. Rakesh Kumar (JE Elect.) and found that SDMC Primary School have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal,
 SDMC Primary School,
 Uttam Nagar New No.-I/II, K-Block,
 Santosh Park, Uttam Nagar, New Delhi-110059.
- Director of Education,
 S.D.M.C, Civic Centre,
 Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Ground plus two upper floors **INSPECTION REPORT** 1. Name & address of the building: SDMC Primary School, Uttam Nagar New No.-I/II, K-Block, Santosh Park, Uttam Nagar, New Delhi-110059. 2. Type of Occupancy Educational 3. Type of Case New 4. Details of Previous NOC : N/A 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection : 16.11.2018 7. Name of Inspecting Officer : A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side : Sh. Rakesh Kumar (JE Elect.) 9. Year of Construction : Before 2009 Applicant's letter No. : 514/Z.E.E2018-2019 dated 09.10.2018 S. No. Minimum Standards on fire prevention and NBC/BBL/ Dir. Of Provided at Remarks Edu. Circular dt. fire safety U/R 33 site MR/NMR 01.03.2011 Requirement 1. Access to building Accessible 06 mtrs Road width 06 mtrs M/R 4.5 mtrs Gate width Directly accessible MR from road N/A Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 No 02 No's M/R Basements N/A N/A N/A Width of staircases Upper Floor 150 cms or less upto 118 cms & 116 **Basements** M/R 75 cms & 75 cms cms c. Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A N/A N/A N/A No. of continuous staircases to terrace N/A N/A N/A Width of Corridor e. 150 cms 240 cms M/R Class Room Door Size 100 cms 130 & 100 cms M/R 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A Basements Required Natural Upper floors M/R ventilation 5. Fire Extinguishers Total numbers 06 no.'s Provided M/R Types ABC/CO₂ type Provided M/R IS marking ISI marked Provided M/R First-Aid Hose Reels 6. Total numbers on each floor 01 no. per floor Provided M/R 30 M Length of hose reel hose Provided M/R 5 mm Nozzle diameter Provided M/R

7.	Automatic fire detection and alarming system	n		
	 Type of detectors 	N/A	N/A	N/A
	 Location of Main Panel 	N/A		N/A
	 Location of Repeater Panel 			
	 Alternate source of power 	0.868		N/A
	 Hooters' Location 	N/A		N/A
8.	MOEFA	NI/A		N/A
		IN/A	N/A N/A N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
4.4	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	 Size of riser/down-comer 	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			- 1/4
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A		N/A
13.	Pumping Arrangements			- 1/1.4
	Ground Level	~		
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump			N/A
	Number of main pumps			-
	Jockey Pump out put			N/A
	Jockey pump headStandby Pump out put	-		N/A
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	Surreng Wanda Stopping	N/A	N/A	N/A
		San Anna San	1 6	N/A
	Pump House Access			N/A N/A
	Terrace level	- //	INIX	14/71
	Discharge of pump	450 I DN4	Descrit 1) In
	➤ Head of the pump			MR
	Power Supply			MR
	Auto Starting of pump			MR
		Kequired	Provided	MR
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	NI/A	77/4	. 37/4
	Order ground tank capacityDraw-off connection	700 740 KW.200		N/A
	Fire service inlet	The second secon		N/A
	Access to tank		N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		10,000 ltrs	Provided	MR
				MR
5.	Exit Signage.			and the second s
6.	Provision of Lifts.			No Lift
· ·	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 			N/A
	 Communication In lift Car 	N/A	N/A N/A	N/A N/A
	 Fireman's Grounding Switch 			
	• Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
7.	Standby power supply	N/A	N/A	N/A
8.	Refuge Area.			
.				
	Total AreaLocation	N/A	N/A	N/A
	2000001	N/A	N/A	N/A

X

Fire Control Room				
Detector System Panel	N/A	N/A	N/A	
 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A	
	N/A	N/A	N/A	
	N/A	N/A	N/A	
	N/A	N/A	N/A	
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A	
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection N/A N/A N/A	● Detector System Panel N/A N/A ● Flow Switch Panel N/A N/A ● PA System Panel N/A N/A ● Battery backup N/A N/A ● Building Floor Plans N/A N/A Special Fire Protection System for Protection N/A N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/2011/School/3569 dated 16.12.2011 has been complied.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

22/11/18

191/20/3W DCFO (522) on (eave 21/11/18
21/11/18
21/11/19
21/11/12
M·SCELL FT/M.

F.T. letter is pul 14 for signature blease.

cho (sy) Miscell Wyliz