## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2018/SZ/

2666

Dated: .../0/19/18

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s KAMPAI (A Unit of Tasteshop Pvt. Ltd) situated at G-02, Ground Floor, Worldmark-I, Asset-11, Aerocity, New Delhi-110037, comprised of three tiers basement, mezzanine, ground plus 06 upper floors. The restaurant running at ground floor of the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 30/11/2018 in the presence of Mr. Sandeep Chhikara (Gen. Manager) and that the premises is fit for occupancy class 'Assembly' Group-D (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/12/18 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

## Copy to: -

- 1. Director, M/s KAMPAI (A Unit of Tasteshop Pvt. Ltd) situated at G-02, Ground Floor, Worldmark-I, Asset-11, Aerocity, New Delhi-110037,
- 2. Dy. Health Officer, South M.C.D., Public Health Department, Najafgarh Zone, Dhansa Stand, Najafgarh, New Delhi-110043

## **Conditions for the validity of Fire Safety Certificate: -**

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

	INSPECTIO	N REPORT		1		
1	Name & Address of the Building	M/s KAMPAI (A Unit of Tasteshop Pvt. Ltd) at G-02,				
1	1,000	Ground Floor, Worldmark-1, Asset-11, Aerocity, IGI				
		Airport, New Delhi-110037 (90 Covers)				
2	Type of Occupancy	Assembly 'Group-D' (Restaurant at Ground Floor)				
3	Building comprised of	03 Basements, Me	03 Basements, Mezzanine, Ground + 06 floors.			
4	Type of Case	New				
5	Details of Previous NOC	F.6/DFS/MS/Mixed/SZ/2018/338 dated 28/02/2018 (Bldg)				
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2017/Hotel/368 dated 21/02/2017 (Bldg)				
7	Date of Inspection	30-11-2018				
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)				
9	Name & Designation of Officers	Mr. Sandeep Chhi	kara (Gen. Manager)			
	from the building side	-				
10	Year of construction	2014				
11	Applicant letter No.	Nil Dated 26-11-2	Nil Dated 26-11-2018			
S. No.	Minimum standards on Fire Prevention	UBBL/NBC-2016 Provided at Site Remark				
	and Fire Safety U/R 33	Requirements		MR/NMR		
1	Access to Building.		& Maintained by Bldg N			
	Road width	Restt located	As above	MR		
	Gate width	within	As above	N/A		
	Width of internal road	Worldmark-I	As above	N/A		
2	Number, width, type & arrangement of exits					
	a. Number of Staircase	Provided & Maintained by Bldg Mgmt.				
	Upper floors	-NA-	As above	-NA-		
	Basement floor	-NA-	As above	-NA-		
	b. Width of Staircase	Provided	& Maintained by Bldg I	Mgmt.		
	Upper floors	N/A	As above	-NA-		
		N/A	As above	-NA-		
	Basement floor			100 340000		
	c. Protection of exits	Provided & Maintained by Bldg Mgmt.  -NA-  As above -NA-				
	Fire check door	-NA-	As above			
	<ul> <li>Pressurization</li> </ul>	-NA-	As above	-NA-		
	d. No. of continuous staircase to terrace	Required	As above	MR		
	e. Width of corridor	-NA-	-NA-	-NA-		
	f. Door size	2m / 1.35m	2m, 1.40m & 1.06m	MR		
3	Compartmentation.	Provided & Maintained by Bldg Mgmt.				
	Fire check door.	Required	As above	MR		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	As above	MR		
	<ul> <li>Fire rating of shaft door.</li> </ul>	Required	As above	MR		
	Water curtain	Required	As above	MR		
	<ul> <li>Fire dampers.</li> </ul>	-NA-	As above	-NA-		
4	Smoke Management system.	Provided & Maintained by Bldg Mgmt.				
	Basement	-NA-	As above	-NA-		
	Upper floors / Restt.	Required	Smoke venting provided	d MR		
5	Fire Extinguishers.	1	J 1			
	Total numbers	06 Nos	Provided	MR		
	• Types	ABC / CO2	ABC type	MR		
	ISI Marking	ISI marked	Provided	MR		
6	First Aid Hose Reels.	Provided & Maintained by Bldg Mgmt.				
		One	As above	MR		
	Total numbers on each floor.	30m	As above As above	MR		
		411m	AC SHOVE	I IVIR		
	<ul><li>Length of hose-reel hose.</li><li>Nozzle Diameter</li></ul>	5mm	As above	MR		

M/s KAMPAI at G-02, GF, World Mark-1, Asset-11, Aerocity, IGI Airport, New Delhi

7	Automatic fire detection & alarming system.	Provided	& Maintained by Bldg	Mgmt.	
21	Type of detectors	-NA-	Smoke & Heat	-NA-	
	Location of Main Panel	-NA-	Mezzanine floor	-NA-	
	Location of Repeater Panel	-NA-	FCR at GF	-NA-	
	Alternate source of power	-NA-	Provided	-NA-	
	Hooter's location	-NA-	All area	-NA-	
8	MOEFA	Required	Provided	MR	
9	Public Address System	-NA-	As above	-NA-	
10	Automatic Sprinkler System	Provided & Maintained by Bldg Mgmt.			
10	Basement	-NA-	As above	-NA-	
	Upper floors / Restt Area	-NA-	As above	-NA-	
	Sprinkler above false ceiling	-NA-	As above	-NA-	
11	Internal Hydrants.	and the second s	d & Maintained by Bldg	Mgmt.	
11	Size of Riser/Down-comer	-NA-	As above	-NA-	
	Number of Hydrant per floor	-NA-	As above	-NA-	
	Hose box.	-NA-	As above	-NA-	
12	Yard Hydrants.		d & Maintained by Bldg	Mgmt.	
14	Total number of hydrants.	-NA-	As above	-NA-	
	<ul><li>Hose box.</li></ul>	-NA-	As above	-NA-	
13	Pumping arrangements.		ngements are common fo	r the comple	
13	Ground Level	Provided & Maintained by Bldg Mgmt.			
		-NA-	2280 LPM	-NA-	
	Discharge of main pump.	-NA-	105m	-NA-	
	> Head of main pump.	-NA-	Two	-NA-	
	<ul><li>Number of main pumps.</li><li>Jockey Pump output.</li></ul>	-NA-	2 x 180 LPM	-NA-	
	<ul><li>Jockey Pump badpat.</li><li>Jockey Pump head.</li></ul>	-NA-	105m	-NA-	
	<ul><li>Standby Pump output.</li></ul>	-NA-	2280 LPM	-NA-	
	<ul><li>Standby Pump head.</li></ul>	-NA-	105m	-NA-	
	<ul><li>Auto Starting / Manual Stopping.</li></ul>	-NA-	Provided	-NA-	
	<ul><li>Pump House Access</li></ul>	-NA-	Provided	-NA-	
	Terrace Level		ed & Maintained by Bldg	1	
	> Discharge of pump.	450 LPM	900 LPM	MR	
	<ul><li>Head of pump.</li></ul>	40 mtr	Provided	MR	
	Power supply.	Required	Provided	MR	
	Auto starting of pump.	Required	Provided	MR	
14	Captive water storage for Fire Fighting.	A	ed & Maintained by Bldg	Mgmt.	
	Underground tank capacity.	-NA-	1,50,000 Ltr	-NA-	
	> Draw-off connection.	-NA-	Provided	-NA-	
.6	Fire Service Inlet.	-NA-	Provided	-NA-	
	Access to tank.	-NA-	Provided	-NA-	
	Overhead tank capacity.	10,000 Ltr	20,000 Ltr	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.	Provided & Maintained by Bldg Mgmt.		g Mgmt.	
	Pressurization of lift shaft.	-NA-	As above	-NA-	
	Pressurization of lift lobby.	-NA-	As above	-NA-	
	Communication in lift car.	-NA-	As above	-NA-	
	• Fireman's switch.	-NA-	As above	-NA-	
	• Lift signage.	-NA-	As above	-NA-	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area		ed & Maintained by Bld		
	Total area	-NA-	550 m <sup>2</sup>	-NA-	
	• Location	-NA-	6 <sup>th</sup> floor	-NA-	
	Location	-INA-	0 11001	-INA-	

M/s KAMPAI at G-02, GF, World Mark-1, Asset-11, Aerocity, IGI Airport, New Delhi

1	True Control I Drawn	Provided	& Maintained by Bldg	g Mgmt.	
19	<ul> <li>Fire Control Room.</li> <li>Detector System Panel.</li> <li>Flow Switch Panel.</li> <li>PA system Panel.</li> <li>Battery backup</li> <li>Building floor plan</li> </ul>	-NA-	As above	-NA-	
		-NA-	As above	-NA-	
		-NA-	As above	-NA-	
		-NA-	As above	-NA-	
		-NA-	As above	-NA-	
		Protection of special Risk, if any:		N/A	
20	Special Fire Protection System for the Protection of special Risk, if any:  N/A				

Total Covered Area- 213.36m<sup>2</sup> ÷ 1.5= 142.24 Person

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection. The shortcoming communicated by this department vide even letter dated 04/12/2018 (C-8) found complied.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s KAMPAI at G-02, GF, World Mark-1, Asset-11, Aerocity, IGI Airport, New Delhi

A G.T. Letter Som up for Signature Dease

M.5 Cell 10/12