## FORM 'H': FORM FOR ISSUING FIRE SAFETY C'ERTIFICATE [See sub-rule (1) of rule 35]

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. DFS/MS/Banquets/2018/WZ/ 2643

Dated: 67/ /2/2018

## FIRE SAFETY CERTIFICATE

Certified that the The Grace Banquet (A Unit of Malhotra Realtech Pvt. Ltd.) located at B-10, G.T. Karnal Road, (Opp. Gujrawala Town) New Delhi-110033 running at Ground Floor & 1st Floor only in a building comprising Ground, Mezz. & 1st Floor only owned/ occupied by the Grace Banquet (A Unit of Malhotra Realtech Pvt. Ltd.), have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service rules 2010 and verified by the officers concerned of Fire Service on 27.11.2018 in presence of Sh. Pawan Malhotra and that the building / premises is fit for occupantly class Assembly (Group — D) / Banquets (For Ground Floor & 1st Floor only) with effect from 67 / 12 /2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on 67/2/18 at New Delhi.

(ATÚL GARG) CHIEF FIRE OFFICER.

Copy to :-

- 1. Sh. Pawan Malhotra, The Grace Banquet (A Unit of Malhotra Realtech Pvt. Ltd.) located at B-10, G.T. Karnal Road, (Opp. Gujrawala Town) New Delhi-110033.
- 2. Deputy Health Officer, North Delhi Municipal Corporation, Keshav Puram Zone, Keshav Puram, Delhi.

**Conditions for the validity of Fire Safety Certificate:** 

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be ver fied by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in
- 7. Mezz. Floor should remain seal and not used for any purpose.

416

## **INSPECTION REPORT**

1. Name & address of the building: The Grace Banquet (A Unit of Malhotra Realtech Pvt. Ltd.), G.F. & 1st F., B-10, G.T. Karnal Road, Industrial Area, (Opp. Gujrawala Town) New Delhi-110033.

: Assembly (Banquet Hall at Ground Floor & 1st 2. Type of Occupancy Floor only in a building comprising Ground, Mezz. & 1st Floor)

3. Type of Case : New

Plot Area :- 123.977 m<sup>2</sup> Details of previous NOC : Nil

5. Fire Safety directives Letter No.: F6/DFS/MS/2018/4325 dated 12/10/18

6. Date of inspection : 27/11/2018

7. Name of the Inspecting Officer: Dy. C.F.O (West) & A.D.O. (JWP)

: - Nil

8. Name and designation of Officer

from the building side : Sh. Pawan Malhotra

9. Year of Construction : 2016-17 **10.** Applicant's letter No.

S No	Minimum standards on fire prevention and fire safety	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR		
_	U/R 33					
1.	Access of building					
	<ul> <li>Road width</li> </ul>	18 mtr.	On main road	MR		
	<ul> <li>Gate width</li> </ul>	4.5 mtr.	On main road	MR		
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A		
2.	Number, width, Type & Arran	gements of exits				
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	2	2	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	b. Width of staircases		2 E 2			
	<ul> <li>Upper floors</li> </ul>	2.00 mtr x 2	2.00 mtr x 2	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	d. No of continuous	1	1	MR		
	staircase to terrace	*				
	e. Width Of Corridor	N/A	N/A	N/A		
	f. Door Size	2.00 mtr.	2.00 mtr x 1	MR		
			1.00 mtr x 1			
3.	Compartmentation					
	<ul> <li>Fire check door</li> </ul>	Required	Provided	MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke managements System					
	Basements	N/A	N/A	N/A		
	Upper floors	Required	Provided	MR		
5.	Fire Extinguishers					
	Total numbers	5	8	M/R		
	• Types	ISI marked ABC/CO <sub>2</sub>	Provided	M/R		
	IS marking	Required	Provided	M/R		

6.	First – Aid Hose Reels				Spirit Street
	Total numbers on	2	2	MR	-
	each floor		/ <u> </u>	1.65	-
	<ul> <li>Length of hose reel</li> </ul>	30 mtr.	30 mtr.	MR	
	hose		5	MR	-
	Nozzle diameter	5 mm	5 mm	IVIIC	_
7.	Automatic fire detection and a		NI/A	N/A	-
	Type of detector	N/A	N/A N/A	N/A	-
	<ul> <li>Location of Main</li> </ul>	N/A	N/A	IN/A	
	Panel	N/A	N/A	N/A	1
	<ul> <li>Location of Repeater</li> <li>Panel</li> </ul>	N/A	1377		
	Alternate source of	N/A	N/A	N/A	
	power				-
	Hooters' Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	. Provided	MR	
10.	Automatic Sprinkler System				
	Basements	N/A	N/A	N/A	
	Upper Floor	N/A	Provided	N/A	_
	Sprinkler above false	N/A	N/A	N/A	
	ceiling		9		
11.	Internal Hydrants				
	Size of riser/down-	150 mm •	150 mm	MR	
	comer			MR	_
	• Number of hydrants	Two	Two	IVIK	
	per floor			MR	
	Hose Box	Two	Two	IVIN	_
12.			D1/0	N/A	-
	• Total number of	N/A	N/A	IN/A	
	hydrants	N/A	N/A	N/A	-
12	Hose Box  Downing Agreements	IV/A	IN/ A	1.47.	
13.	G 1 Y 1	N/A			
	<ul><li> Ground Level</li><li> Discharge of main pump</li></ul>	2280LPM	2280LPM	MR	
	Head of main pump	70MH	70MH	MR	
	> Number of main pumps	1	1	MR	
	> Jockey pump out put	180LPM	180LPM	MR	
	Jockey pump head	40MH	40MH	MR	
	> Standby Pump out put	N/A	N/A	N/A	_
	Standby Pump Head	N/A	N/A	N/A	_
	Auto Staring/Manual	Required	Provided	MR	
	stopping	N/A	N/A	N/A	
	> Pump House Access	N/A	IN/ A	14/74	7
	Terrace level     Disclarace of nump	900 LPM	900 LPM	MR	
	Discharge of pump	40 MH	40 MH	MR	
	<ul><li>Head of the pump</li><li>Power supply</li></ul>	Required	Provided	MR	
	> Auto starting of pump	Required	Provided	MR	
		•			
14	1		50.00011	N1/A	
	<ul> <li>Underground tank</li> </ul>	N/A	50,000 Ltr	N/A	
	capacity	N/A	N/A	N/A	
<ul><li>Draw of connection</li><li>Fire service inlet</li></ul>		N/A N/A	Provided	N/A	
	> Access to tank	N/A	N/A	N/A	
			10 000 Ltr connecte	d MR	

	***	H	100			
15	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts					
10.	> Pressurization of Lift	N/A	N/A	N/A		
	Shaft		1-	21/0		
	> Pressurization of lift	N/A	N/A	N/A		
	lobby	1		N1/A		
	Communication in lift	N/A	N/A	N/A		
	Car		21/2	N/A		
	Fireman's Grounding	N/A	N/A	N/A		
	Switch		D1/A	N/A		
	Lift Signage	N/A	N/A	IN/A		
17.	Standby power supply	Required	Provided	MR		
	Refuge Area	N/A	N/A	N/A		
18.	> Total area	N/A	N/A	N/A		
		N/A	N/A	N/A		
> Location 17/A						
19.	Fire control room	N/A	N/A	N/A		
	Detector system panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	> PA System Panel	N/A	N/A	N/A		
	Battery backup		N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.	Special Fire Protection	N/A	14/7	1.7.		
	Systems for Protection of					
	special Risks, if any;					

Note:- 1) MCB / ELCB and metal conduit wiring (Concealed wiring), earth leakage circuit breaker have been Provided.

2) An UGWS Tank of 50,000 ltr capacity having connected to riser & Pumps of 2280 LPM and 180 LPM and an Over Head Tank of 10,000 ltrs capacity connected to terrace pump of 900 LPM and down comer have been provided which meets the requirement.

3) Applicant has given undertaking that he will not use Mezz. Floor for any Banquet activities. Only Ground Floor & 1<sup>st</sup> Floor will be used for the Banquet Hall activities for which Fire Safety Certificate is recommended.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate for Ground Floor & 1<sup>st</sup> Floor under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

J 29/11/18

Signature of the Inspecting Officer Name : Ashok Kumar Jaiswal

Designation: A.D.O. (Jwala Puri)

Signature of the Inspecting Officer
Name : Dharampal Bhardwai

Designation: Dy.C.F.O. (West)

fo west of MIR

F.T. is fout up for signature pl.